

Springdale Water Utilities

Springdale, Arkansas


System Overflow Report for October 2013

This report submitted to Arkansas Department of Environmental Quality in compliance with Permit Number AR0022063 AFIN: 72-00003

Date	Time	Duration	Address	Est. Vol.	Cause of overflow	Remedial Action	Environmental Impact	Discharge Location
10/05/2013- 10/07/2013	9:39 pm – 9:39 am	36 hrs.	3107 Great House Springs Rd. Johnson, AR	2000 gal	I & I-Rainfall/Equipment Failure	Damaged pump(s) to be repaired	None	Overflow from one manhole pooled and appears to have soaked into ground with no discernible migration of run off detected.

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that all qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Signature



Date

11-14-13

Springdale Water Utilities
P.O. Box 769
Springdale, AR 72765-0769

IF THE RETURN ADDRESS, FOLD AT DOTTED LINE


CERTIFIED MAIL™



7012 3050 0000 5906 6644



UNITED STATES
POSTAL SERVICE



1000


72118

U.S. POSTAGE
PAID
SPRINGDALE, AR
72764
NOV 15, '13
AMOUNT

\$6.31

USA
FIRST-CLASS
PER

00044614-03



ADEQ
NPDES Enforcement Section
5301 Northshore Drive
North Little Rock, AR 72118



**RETURN RECEIPT
REQUESTED**

7211835328 R015

