

Springdale Water Utilities

Springdale, Arkansas


System Overflow Report for October 2014

This report submitted to Arkansas Department of Environmental Quality in compliance with Permit Number AR0022063 AFIN: 72-00003

Date	Time	Duration	Address	Est. Vol.	Cause of overflow	Remedial Action	Environmental Impact	Discharge Location
10/10/2014	9:30 am- 11:30 am	2 hrs.	Pleasant St & Rebecca St. Springdale, AR		I & I Rainfall -- SSO due to flash flooding		None	Into street during storm event.
10/19/2014	2:00 pm- 3:00 pm	1 hr.	Intersection of Backus Ave & N West End St. Springdale, AR	15 gal	Grease	Jet-Vac	None	Two clean outs- into ditch.

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that all qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Signature



Date

11-14-14

CERTIFIED MAIL™

Springdale Water Utilities
P. O. Box 769
Springdale, AR 72765-0769




7013 0600 0001 6399 9194



UNITED STATES
POSTAL SERVICE

1000




72118

U.S. POSTAGE
PAID
SPRINGDALE, AR
72764
NOV 17, '14
AMOUNT

\$6.21

00018142-06



NOV 17 2014

USPS

RETURN REQUEST
REQUESTED

Arkansas Dept. of Environmental Quality
NPDES Enforcement Section
5301 Northshore Drive
North Little Rock, AR 72118-5317

721185317 2014

