

Springdale Water Utilities


Springdale, Arkansas

System Overflow Report for October 2015

This report submitted to Arkansas Department of Environmental Quality in compliance with Permit Number AR0022063 AFIN: 72-00003

Date	Time	Duration	Address	Est. Vol.	Cause of overflow	Remedial Action	Environmental Impact	Discharge Location
10/24/2015	2:30 pm-3:50	1 hr. 20 min	4205 Brant Drive Springdale, AR 72762	50 gal	Roots	Jet-Vac, Disinfected & Deodorized	None	Contained in building. A restoration company was sent to property to dewater and sanitize.

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that all qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Signature  Date 11-19-15

CERTIFIED MAIL™

Springdale Water Utilities
P. O. Box 769
Springdale, AR 72765-0769



7013 0600 0001 6399 9347

NORTHWEST AR P&DF



UNITED STATES
POSTAL SERVICE®

1000



72118

U.S. POSTAGE
PAID
SPRINGDALE, AR
72764
NOV 19, 15
AMOUNT

\$6.47

R2305E125778-03

FOREVER
USA

**Arkansas Dept. of Environmental Quality
NPDES Enforcement Section
5301 Northshore Drive
North Little Rock, AR 72118-5317**

**RETURN RECEIPT
REQUESTED**

72118+5317

