

Springdale Water Utilities

Springdale, Arkansas

System Overflow Report for September 2014

This report submitted to Arkansas Department of Environmental Quality in compliance with Permit Number AR0022063 AFIN: 72-00003

Date	Time	Duration	Address	Est. Vol.	Cause of overflow	Remedial Action	Environmental Impact	Discharge Location
09/01/2014	4:00 pm-5:00 pm	1 hr.	206 E Maple Ave Springdale, AR 72764	75 gal	Grease	Jet-Vac	None	Overflow went into storm drain.
09/05/2014	3:50 pm-4:20 pm	½ hr.	1300 A Q Cir Springdale, AR 72764	50 gal	Grease	Jet-Vac	None	Overflow soaked into ground.

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that all qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Signature Keith A. Wood Date 10-9-2014

CERTIFIED MAIL™

Springdale Water Utilities
P. O. Box 769
Springdale, AR 72765-0769



7012 3050 0000 5906 6798




1000

72118

ADEQ
NPDES Enforcement Section
5301 Northshore Drive
Little Rock, AR 72118

U.S. POSTAGE
PAID
GREENLAND, AR
72737
OCT 17, 14
AMOUNT

\$6.21
00091160 73



7211845317 R015

