

# Springdale Water Utilities

Springdale, Arkansas


## System Overflow Report for February 2015

This report submitted to Arkansas Department of Environmental Quality in compliance with Permit Number AR0022063 AFIN: 72-00003

Date	Time	Duration	Address	Est. Vol.	Cause of overflow	Remedial Action	Environmental Impact	Discharge Location
02/03/2015	10:41 pm- 11:20 pm	39 min.	1509 Letha Dr. Springdale, AR 72762	305 gal	Grease	Jet-Vac, Disinfected and Deodorized	None	Clean out into yard-soaked into ground (300 gal). Minor backup in building bathroom (5 gal).
02/17/2015	11:00 am- 11:20 am	20 min.	1644 Cartwright Cir. Springdale, AR 72762	30 gal	Grease	Jet-Vac	None	Manhole into storm drain.
02/21/2015	2:50 pm- 4:00 pm	1 hr. 10 min.	1652 Wensworth Ave. Springdale, AR 72762	100 gal	Roots	Jet-Vac	None	Manhole into yard - soaked into ground.
02/27/2015	8:15 am- 8:45	30 min.	2202 Magnolia Dr. Springdale, AR 72762	500 gal	Debris, Vandalism	Jet-Vac	None	Manhole into storm drain.

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that all qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Signature



Date

3-12-15

# Springdale Water Utilities

Springdale, Arkansas


## System Overflow Report for February 2015

This report submitted to Arkansas Department of Environmental Quality in compliance with Permit Number AR0022063 AFIN: 72-00003

Date	Time	Duration	Address	Est. Vol.	Cause of overflow	Remedial Action	Environmental Impact	Discharge Location
02/28/2015	6:25 pm- 8:25 pm	2 hrs.	1206 Christian Ave. Springdale, AR 72764	100 gal	Grease, Debris	Jet-Vac	None	Manhole into yard, soaked into ground.

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that all qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Signature



Date

3-12-15

Springdale Water Utilities  
P. O. Box 769  
Springdale, AR 72765-0769

**CERTIFIED MAIL**



7012 3050 0000 5906 6828

NORTHWEST AR P&DE



UNITED STATES  
POSTAL SERVICE




1000

72118

U.S. POSTAGE  
PAID  
SPRINGDALE, AR  
72769  
MAR 13, 15  
AMOUNT

**\$6.21**  
00062537-06



**RETURN RECEIPT  
REQUESTED**

ADEQ  
NPDES Enforcement Section  
5301 Northshore Drive  
North Little Rock, AR 72118

721185317

