Phone: 479.752.3912



October 21, 2014

Michelle Bolenbaugh Enforcement Analyst ADEQ 5301 Northshore Drive North Little Rock, AR 72118

RE: Decatur Permit Violations Permit Number AR0022292, AFIN 04-00052

Dear Ms. Bolenbaugh,

The Decatur WWTP had permit limit problems concerning the 7 day average portion of our permit for phosphorus and TSS. This problem occurred on the last week of the month of September.

The wastewater plant has been for a lack of a better word, "burping" a small amount of solids or mixed liquor from the SBR treatment trains into the post equalization tank before it goes to the disk filter, from time to time. Phosphorus is tied up in the solids so when the solids concentration came up the phosphorus did to. Our disk filter catches most of the solids but what it has not caused our violations.

We have turned over to engineering some solutions to this problem for the long term; and they are reviewing them. It looks like this problem could continue sporadically so a permanent solution is in order. In the mean time we will continue to do our best to control the solids issues with what we have in place.

If you have any questions or concerns please give me a call at 479-752-3912

Sincerely,

James Boston

Public Works Manager

City of Decatur

## Sanitary Sewer Overflow Monthly Report

	•	• ,	1
Facility Name DECATID City of	Downski Namekow 22202	_Reporting Period(Month/Year): 🕰	12014
Facility Name: DECATUR, City of	Permit Number: 22292	_Reporting Period(Ivionth/Year): Car	1,701
	$(I_{+},I)(X_{-})$		<del></del>

No Sanitary Sewer Overflows This Monitoring Period


Summary Report Code Descriptions							
Cause(s) of SSO		SSO Impact	Action(s) Taken	Ultimate Discharge Location			
CO-Construction	. D-Debris	NEAH-No Evidence of Adverse Health or Environmental	WO-Work Order	CR-Creek/Stream/River (please specify)			
E-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup	DI-Ditch			
HC-Hydro Clean	LF-Line Failure/Break	EFK-Evidence of Fish Kill	HC-Hydro Cleaned	DR-Drop Inlet			
R-Rainfall	RG-Roots & Grease		HR-Hand Rodded	GR-Ground Surface			
RO-Roots	V-Vandalism		EN-Referred to Engineering	PA-Paved Area			
			PN-Public Notification	CB-Contained in Building			

Location	Manhole#	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action (s) Taken to Address SSO	Ultimate Discharge Location
						\$\frac{1}{2}\tag{1}		
· · · · · · · · · · · · · · · · · · ·								
				.,	····	- 2		
<u> </u>			3					
<u> </u>								
								,
		·						
						:		
							·	·
						<u> </u>		
	1.							
1								
(ban A	Bt Du	hlic Wor	Vs Mai	naals	. Liste W. Ann	10	121/2014	

Signature of Cognizant or Ranking Official

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

P.O. Box 247 • 310 Maple Ave. Decatur, Arkansas 72722



գրոլիովթենիկը/||վլիկիկիկիկիկիկիկիկիկի

Arkansas Dept. of Environmental Quality Water Division-Enforcement Branch 5301 Northshore Drive North Little Rock, AR 72118-5317