

Environmental Services Company, Inc.

Corporate Office
 13715 West Markham
 Little Rock, AR 72211
 Tel. (501)221-2565 Fax (501)221-1341

Northwest Arkansas Branch
 1107 Century Avenue
 Springdale, AR 72762
 Tel. (479)750-1170 Fax (479)750-1172

Control Number: 1607010309	Composite Date: 07/19/16 - 07/19/16	Collected By: ANNETTE STRICKL
Customer Name : CAMDEN WATER & WASTEWATER UTILTY	Sample Time : 1000-1500	Delivery By : TMO
Customer Number : 1550	Sample Type : COMPOSITE WWATER	Work Order :
Report Date : 07/26/16	Sample From : EFFLUENT	Purchase Order :

Laboratory Analysis

Analysis				Laboratory Analysis				Quality Assurance	
Date	Time	By	Parameter	Result	Notes	Quantity	Method	Precision % RPD	Accuracy % Recovery
07/21	0640	NTR	Phosphorous, Total (as P)	0.26 mg/L			EPA 365.3	0.00	97.8
07/21	0700	NTR	Nitrate + Nitrite	3.32 mg/L			SM 2000 4500-NO3 E	2.67	99.5 *

* QA data shown is from a different sample or standard on the same date.

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.

Signature _____


 Environmental Services Co., Inc.

Sanitary Sewer Overflow Monthly Report

Facility Name: WINNEN WATER UTILITIES Permit Number: AR0022365 Reporting Period (Month/Year): 07/2016

No Sanitary Sewer Overflows This Monitoring Period


Cause(s) of SSO		Summary Report Code Descriptions		
		SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO-Construction	D-Debris	NEAH-No Evidence of Adverse Health or Environmental Impact	WO-Work Order	CR-Creek/Stream/River (please specify)
E-Equipment Failure	G-Grease			
HC-Hydro Clean	LF-Line Failure/Break	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup	DI-Ditch
R-Rainfall	RG-Roots & Grease	BFK-Evidence of Fish Kill	HC-Hydro Cleaned	DR-Drop Inlet
RO-Roots	V-Vandalism		HR-Hand Rodded	GR-Ground Surface
			EN-Referred to Engineering	PA-Paved Area
			PN-Public Notification	CB-Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action (s) Taken to Address SSO	Ultimate Discharge Location

Thomas K. Ballard
Signature of Cognizant or Ranking Official

08/17/2016
Date

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."



Camden
Water
Utilities

P.O. BOX J
CAMDEN, AR 71711

LITTLE ROCK AR 722

19 AUG 2016 PM 4 L



ADEQ

Water Division-Enforcement Branch
5301 Northshore Drive
North Little Rock, AR 72118-5317

72118-531799

