

Sanitary Sewer Overflow Monthly Report

Facility Name: INDEN WATER UTILITIES Permit Number: AR0022365 Reporting Period(Month/Year): 03/2016

No Sanitary Sewer Overflows This Monitoring Period

Cause(s) of SSO		Summary Report Code Descriptions		
		SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO-Construction	D-Debris	NEAH-No Evidence of Adverse Health or Environmental Impact	WO-Work Order	CR-Creek/Stream/River (please specify)
E-Equipment Failure	G-Grease		EC-Environmental Cleanup HC-Hydro Cleaned	DI-Ditch
HC-Hydro Clean	LF-Line Failure/Break	OBHC-Observed or Evidence of Human Contact EFK-Evidence of Fish Kill		DR-Drop Inlet
R-Rainfall	RG-Roots & Grease		HR-Hand Rodded	GR-Ground Surface
RO-Roots	V-Vandalism	EN-Referred to Engineering	PA-Paved Area	
		PN-Public Notification	CB-Contained in Building	

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action (s) Taken to Address SSO	Ultimate Discharge Location
<u>Cash Rd + Mary Street</u>		<u>3/13/2016</u>	<u>03/13/2016</u>	<u>4000 gals</u>	<u>R</u>	<u>NEAH</u>	<u>HC</u>	<u>DI</u>

Thomas K. Ballard
Signature of Cognizant or Ranking Official

03-18-2016
Date

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Environmental Services Company, Inc.

Corporate Office
 13715 West Markham
 Little Rock, AR 72211
 Tel. (501)221-2565 Fax (501)221-1341


Northwest Arkansas Branch
 1107 Century Avenue
 Springdale, AR 72762
 Tel. (479)750-1170 Fax (479)750-1172

Control Number: 1603010319	Composite Date: 03/15/16 - 03/15/16	Collected By: ANNETTE STRICKL
Customer Name : CAMDEN WATER & WASTEWATER UTILTY	Sample Time : 1000-1500	Delivery By : TMO
Customer Number : 1550	Sample Type : COMPOSITE WATER	Work Order :
Report Date : 04/01/16	Sample From : FINAL EFFLUENT	Purchase Order :

<u>Laboratory Analysis</u>							<u>Quality Assurance</u>	
Analysis			Result	Notes	Quantity	Method	Precision	Accuracy
Date	Time	By					Parameter	% RPD
03/17	1530	NTR	Phosphorous, Total (as P)	0.49 mg/L		EPA 365.3	1.08	92.5 *
03/17	1400	NTR	Nitrate + Nitrite	0.28 mg/L		SM 2000 4500-NO3 E	1.94	102.3 *

* QA data shown is from a different sample or standard on the same date.

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter, where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.

Signature 
 Environmental Services Co., Inc.




Camden
Water
Utilities

P.O. BOX J
CAMDEN, AR 71711

LITTLE ROCK AR 722

20 APR 2016 PM 3 L



ADEQ
Water Division-Enforcement Branch
5301 Northshore Drive
North Little Rock, AR 72118-5317

72118531799

