

Sanitary Sewer Overflow (SSO) Monthly Report

Facility Name: CAMDEN WATER UTILITIES NPDES Permit No.: AR0022365 Monitoring Period (Month/Year): 11/2013

No Sanitary Sewer Overflows This Monitoring Period


Summary Report Code Descriptions			
Cause(s) of SSO	SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO-Construction	D-Debris	NEAH-No Evidence Adverse Health/ Environmental Impact	CR-Creek/Stream/River (specify)
E-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup
HC-Hydro Clean	LF-Line Failure	EFK-Evidence of Fish Kill	EC-Hydro Cleaned
R-Rainfall	RG-Roots / Grease		HR-Hand Rodded
RO-Roots	V-Vandalism		EN-Referred to Engineering
			FN-Public Notification
			DI-Ditch
			DR-Drop Inlet
			GR-Ground Surface
			PA-Paved Area
			CB-Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action (s) Taken to Address SSO	Discharge Location
Adams St.		11/14/2013	11/14/2013	500 gallons	RG/D/G	NEAH	EC/HC/HR	CR

Thomas K Bellard
12-10-2013

Signature of Cognizant or Ranking Official
Date

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."




Camden
Water
Utilities

LOCK DRAWER J
CAMDEN, AR 71711

LITTLE ROCK AR 722

10 DEC 2013 PM 4 1



A.D.E.Q.
NPDES ENFORCEMENT DIV.
5301 NORTSHORE DR.
N. LITTLE ROCK, AR
72118-5317

72118531799

