

## Sanitary Sewer Overflow (SSO) Monthly Report

Facility Name: CADDEN WATER UTILITIES NPDES Permit No.: AR0022365 Monitoring Period (Month/Year): 11 / 2014

No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions				
Cause(s) of SSO		SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO-Construction	D-Debris	NEAH-No Evidence Adverse Health/ Environmental Impact		CR-Creek/Stream/River (specify)
E-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup	DI-Ditch
HC-Hydro Clean	LF-Line Failure	EFK-Evidence of Fish Kill	HC-Hydro Cleaned	DR-Drop Inlet
R-Rainfall	RG-Roots / Grease		HR-Hand Rodded	GR-Ground Surface
RO-Roots	V-Vandalism		EN-Referred to Engineering	PA-Paved Area
			FN-Public Notification	CB-Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action (s) Taken to Address SSO	Discharge Location
<i>Smackover Lift Station</i>		<i>11/11/2014</i>	<i>11/11/2014</i>	<i>2000</i>	<i>E</i>	<i>NEAH</i>	<i>replaced pump</i>	<i>GR</i>

*Thomas K Ballard*

*12-10-2014*

Signature of Cognizant or Ranking Official Date

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

# Environmental Services Company, Inc.

Corporate Office  
 13715 West Markham  
 Little Rock, AR 72211  
 Tel. (501)221-2565 Fax (501)221-1341


Northwest Arkansas Branch  
 1107 Century Avenue  
 Springdale, AR 72762  
 Tel. (479)750-1170 Fax (479)750-1172

Control Number: 1411010422	Composite Date: 11/19/14 - 11/19/14	Collected By: ANNETTE STRICKL
Customer Name : CAMDEN WATER & WASTEWATER UTILTY	Sample Time : 1000-1500	Delivery By : TMO
Customer Number : 1550	Sample Type : COMPOSITE WATER	Work Order :
Report Date : 11/24/14	Sample From : FINAL EFFLUENT	Purchase Order :

<u>Laboratory Analysis</u>						<u>Quality Assurance</u>		
<u>Analysis</u>			<u>Result</u>	<u>Notes</u>	<u>Quantity</u>	<u>Method</u>	<u>Precision</u>	<u>Accuracy</u>
<u>Date</u>	<u>Time</u>	<u>By</u>	<u>Parameter</u>				<u>% RPD</u>	<u>% Recovery</u>
11/21	1000	NTR	Phosphorous, Total (as P)	0.26 mg/L		EPA 365.3	0.00	99.9 *
11/20	1200	NTR	Nitrate + Nitrite	3.53 mg/L		SM 2000 4500-NO3 E	1.03	97.7 *

\* QA data shown is from a different sample or standard on the same date.

All equipment used is checked and/or calibrated daily. All NPDES testing is conducted in accordance with 40 CFR Part 136. A minimum of 10% spiked and duplicate samples is run on each parameter where applicable for Quality Assurance purposes. Quality Assurance Plan on file with Arkansas Department of Environmental Quality. Analysis time indicates the time of the start of the analytical batch in which the specific sample was included.

Signature   
 Environmental Services Co., Inc.



Camden  
Water  
Utilities

P.O. BOX J  
CAMDEN, AR 71711

LITTLE ROCK AR 722

10 DEC 2014 PM 1 T



**ADEQ**

Water Division-Enforcement Branch  
5301 Northshore Drive  
North Little Rock, AR 72118-5317

72118\$5317

