

NON-COMPLIANCE REPORT

Arkansas Department of Environmental Quality
NPDES Enforcement Section
5301 Northshore Drive
North Little Rock, AR 72118

RE: NPDES Permit No: AR0022411

Discharge Number: 001-A-Monthly

Facility: Hazen

Address: 1789 Utility Street

City: Hazen

State: AR

Zip: 72064

Contact:

Phone:

Date of Non-Compliance	Parameter Exceeded	Quantity or Loading	Quality or Concentration	Permit Limits
August-23	Fecal		4800MPN/100mL 7D Geo	2000MPN/100mL 7D Geo
August-23	Fecal		2101MPN/100 30D Geo	1000MPN/100 30D Geo

We feel this problem was due to:

V.V. lights are out

We plan on correcting the problem in this manner:

We are in the process of getting new V.V. system

Time estimated that it will take to correct the problem/s:

1 month

Sincerely,



Authorized Signature

9-25-23

Date

NON-COMPLIANCE REPORT

Arkansas Department of Environmental Quality
NPDES Enforcement Section
5301 Northshore Drive
North Little Rock, AR 72118

RE: NPDES Permit No: AR0022411

Discharge Number: 001-A-Monthly

Facility: Hazen

Address: 1789 Utility Street

City: Hazen

State: AR

Zip: 72064

Contact:

Phone:

Date of Non-Compliance	Parameter Exceeded	Quantity or Loading	Quality or Concentration	Permit Limits
August-23	Fecal		4800MPN/100mL 7D Geo	2000MPN/100mL 7D Geo
August-23	Fecal		2101MPN/100 30D Geo	1000MPN/100 30D Geo

We feel this problem was due to:

V.V. lights are out

We plan on correcting the problem in this manner:

We are in the process of getting new V.V. system

Time estimated that it will take to correct the problem/s:

1 month

Sincerely,



Authorized Signature

9-25-23

Date