


# Sanitary Sewer Overflow Monthly Report

Facility Name: Hazen WW Treatment Plant Permit Number: AL6022411 Reporting Period (Month/Year): 7/12

No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions			
Cause(s) of SSO		SSO Impact	Ultimate Discharge Location
CO-Construction	D-Debris	NEAH-No Evidence of Adverse Health or Environmental Impact	WO-Work Order
E-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup
HC-Hydro Clean	LF-Line Failure/Break	EFK-Evidence of Fish Kill	HC-Hydro Cleaned
R-Rainfall	RG-Roots & Grease		HR-Hand Rodded
RO-Roots	V-Vandalism		EN-Referred to Engineering
			PN-Public Notification
			DI-Ditch
			DR-Drop Inlet
			GR-Ground Surface
			PA-Paved Area
			CB-Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action (s) Taken to Address SSO	Ultimate Discharge Location


8-10-12

---

Signature of Cognizant or Ranking Official Date

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

CITY OF HAZEN  
BOX 564  
HAZEN, ARKANSAS  
72064

LITTLE ROCK AR 720

15 AUG 2002 PM 4 1



ENFORCEMENT SECTION  
AR DEPARTMENT OF ENVIRONMENTAL QUAL  
5301 NORTH SHORE DRIVE  
NORTH LITTLE ROCK, AR 72118-5317

72118531799

