

# Springdale Water Utilities

Springdale, Arkansas

## System Overflow Report for November 2021

This report submitted to Arkansas Department of Environmental Quality in compliance with Permit Number AR0022063 AFIN: 72-00003

Date	Time	Duration	Address	Est. Vol.	Cause of overflow	Remedial Action	Environmental Impact	Discharge Location
11/24/2021	8:15 am-9:15 am	1 hr.	100 Michelle St. Springdale, AR 72764	5 gal	Roots/Debris	Jet/Vac. Hydro Cleaned	None	Into storm drain
11/29/2021	4:30 pm-4:50 pm	20 mins.	1306 AQ Circle Springdale, AR 72764	100 gal	Grease	Jet/Vac. Spread Lime on Affected Area	None	Soaked into ground
11/30/2021	4:00 pm-4:15 pm	15 mins.	1907 Stone Street Springdale, AR 72762	50 gal	Grease	Jet/Vac. Hydro Cleaned, Spread Lime on Affected Area	None	Into storm drain

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that all qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Signature Matthew C. Wood Date: 12/10/2021