

# ADEQ

ARKANSAS  
Department of Environmental Quality

August 2, 2011

Larry Waldrop  
El Dorado Water Utilities-South Plant  
325 Quail Crossing  
El Dorado, AR 71730

RE: NPDES Permit Number AR0033723, AFIN 70-00341,  
Deficient Discharge Monitoring Report

Dear Mr. Waldrop:

The Discharge Monitoring Report (DMR) submitted for 6/30/2011 Monitoring Period, Discharge Number TX1Q has been received by the Department. Upon review, I noticed that you failed to sign the DMR.

Submit two legible copies of the corrected DMR with an **original signature and date** by the Cognizant Official. These corrected copies should be received by the Department no later than **August 16, 2011**.

Thank you for your attention to this matter. Please refer to NPDES Permit Number AR0033723 and AFIN 70-00341 in any written correspondence to this Department. Should you have any questions, feel free to contact me at 501-682-0667 or you may e-mail me at carlsonm@adeq.state.ar.us.

Sincerely,



Michelle Carlson  
Enforcement Analyst  
Water Division, Enforcement Branch