

CONFIRMATION NUMBER

EB2EBE5E-FD66-4D27-80FD-65C2A298E225

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: EB2EBE5E-FD66-4D27-80FD-65C2A298E225

Date Sent: 12/9/2014

SSO Bypass Upset

Facility Permit Number: **AR0033880**

Facility name: **Hot Springs Wastewater**

Date Overflow Began: **12/08/2014**

Time: **12:30am**

Date Overflow Ended: **12/08/2014**

Time: **2:30 am**

Location:

Catherine Heights Rd. Manhole #1750 overflowed into Gulpha Creek.

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- <=""> Other Overflow Type:

(Enter overflow type if not listed)

Volume:

2,500

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause: **Old Bar Screen in Wetwell was blocked with debris**

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification
- Raked & Picked Up Debris**

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By Shawn Davis Title Sewer Collection Manager Telephone Number 501-623-6981

Additional

Comments
if Needed:

CONFIRMATION NUMBER

30FEEF08-6ACC-4ABF-BCE0-21E8588A42EE

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 30FEEF08-6ACC-4ABF-BCE0-21E8588A42EE

Date Sent: 12/15/2014

SSO Bypass Upset

Facility Permit Number: **AR0033880**

Date Overflow Began: **12/14/2014**

Date Overflow Ended: **12/14/2014**

Location:

Facility name:

Hot Springs Wastewater

Time:

3:55pm

Time:

7:30pm

111 Jefferson St. Manhole # 2506 overflowed into Storm Inlet that went to Hot Springs creek.

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 3000

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Shawn Davis**

Title **Sewer Collection Manager**

Telephone Number **501-623-6981**

Additional Comments If Needed:

CONFIRMATION NUMBER

C8048F4F-A297-453B-A47E-95D441B7AE9F

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: C8048F4F-A297-453B-A47E-95D441B7AE9F

Date Sent: 12/29/2014

SSO Bypass Upset

Facility Permit Number: **AR0033880**

Date Overflow Began: **12/29/2014**

Date Overflow Ended: **12/29/2014**

Location:

Facility name:

Hot Springs Wastewater

Time:

7:23am

Time:

7:23am

Catherine Heights Rd. Manhole #1750 overflowed into Gulpha Creek. We received notification from your Department 12/29/2014 that an overflow occurred at this location. There was evidence of an overflow, however we do not know when it began or when it ended. we did not witness either occurrence.

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- <=""> Other Overflow Type:

(Enter overflow type if not listed)

Volume:

Undetermined

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Raked & Picked Up Debris

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Shawn Davis** Title **Sewer Collection Manager** Telephone Number **501-623-6981**

Additional Comments if Needed: