

CONFIRMATION NUMBER

BABF989F-4619-4F1B-ACAB-F2B3E7769A35

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

Close this window Print this page

24-Hour Sanitary Sewer Overflow Report

SSO ID#: BABF989F-4619-4F1B-ACAB-F2B3E7769A35

Date Sent: 2/3/2014

SSO Bypass Upset

Facility Permit Number: AR0033880
Date Overflow Began: 02/02/2014
Date Overflow Ended: 02/02/2014
Location: MH# 9250, 100 RIDGE PT, RAN OVER IN LAKE HAMILTON

Facility name:
Time:

HOT SPRINGS WASTEWATER
8:00 pm
10:00 pm

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

3000

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEL - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By CHRIS GORDON

Title MAINTENANCE CONTROLLER

Telephone Number (501) 623-7963

Additional Comments if Needed:

CONFIRMATION NUMBER

BAA7ED09-C4E9-4C00-A9DC-BA7597408C51

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

Close this window Print this page

24-Hour Sanitary Sewer Overflow Report

SSO ID#: BAA7ED09-C4E9-4C00-A9DC-BA7597408C51

Date Sent: 2/3/2014

SSO Bypass Upset

Facility Permit Number: AR0033880
Date Overflow Began: 02/02/2014
Date Overflow Ended: 02/02/2014
Location: MH # 7117, DONNIE CT, RAN OVER IN UNKNOWN STREAM

Facility name:
Time:
Time:

HOT SPRINGS WASTEWATER
8:00 pm
10:00 pm

MH # 7117, DONNIE CT, RAN OVER IN UNKNOWN STREAM
(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 2000

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe RAKED UP

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By CHRIS GORDON

Title MAINTENANCE CONTROLLER

Telephone Number (501) 623-7963

Additional Comments if Needed:

[Empty text box for additional comments]

CONFIRMATION NUMBER

C20A306F-8ABD-4F99-BE60-9973BDE344E6

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: C20A306F-8ABD-4F99-BE60-9973BDE344E6

Date Sent: 2/3/2014

SSO Bypass Upset

Facility Permit Number: **AR0033880**
 Date Overflow Began: **02/02/2014**
 Date Overflow Ended: **02/02/2014**
 Location:

Facility name: **Hot Springs Wastewater**
 Time: **1:00 pm**
 Time: **10:00 pm Forest**

Forestveiw Court Manhole # 12242 overflowed into Hot Springs Creek

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- <=""> Other Overflow Type:

(Enter overflow type if not listed)

Volume: 8,000

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe **Raked & Picked Up Debris**

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Shawn Davis** Title **Sewer Collection Manager** Telephone Number **501-623-6981**

Additional Comments if Needed:

CONFIRMATION NUMBER

9F927F2B-B0DB-4756-B0F3-50C2DD42DE53

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 9F927F2B-B0DB-4756-B0F3-50C2DD42DE53

Date Sent: 2/3/2014

SSO Bypass Upset

Facility Permit Number: **AR0033880**

Facility name:

Hot Springs Wastewater

Date Overflow Began: **02/02/2014**

Time:

1:00 pm

Date Overflow Ended: **02/02/2014**

Time:

8:00PM

Location:

Carpenter Dam Rd. Manhole # 5259 overflowed into unknown creek

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- <=""> Other Overflow Type:

(Enter overflow type if not listed)

Volume: **4500**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Disinfected and Deodorized
- Jet-Vac
- Hydro Cleaned
- Hand rodded
- Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment
- Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Shawn Davis** Title **Sewer Collection Manager** Telephone Number **501-623-6981**

Additional Comments if Needed:

[Empty text box for additional comments]

CONFIRMATION NUMBER

23393215-60A5-46C8-9DB6-A01A68129875

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 23393215-60A5-46C8-9DB6-A01A68129875

Date Sent: 2/3/2014

SSO Bypass Upset

Facility Permit Number: **AR0033880**
 Date Overflow Began: **02/02/2014**
 Date Overflow Ended: **02/02/2014**
 Location:

Facility name: **Hot Springs Wastewater**
 Time: **1:00 pm**
 Time: **8:00PM**

Spring St Manhole # 4118 overflowed into Gulpha Creek

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- <=""> Other Overflow Type:

(Enter overflow type if not listed)

Volume: **4500**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe **Raked & Picked Up Debris**

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Shawn Davis** Title **Sewer Collection Manager** Telephone Number **501-623-6981**

Additional Comments if Needed:

CONFIRMATION NUMBER

1A98D478-2482-48AB-A9FC-85A7AAAF9762

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 1A98D478-2482-48AB-A9FC-85A7AAAF9762

Date Sent: 2/3/2014

SSO Bypass Upset

Facility Permit Number: **AR0033880**

Facility name:

Hot Springs Wastewater

Date Overflow Began: **02/02/2014**

Time:

1:00 pm

Date Overflow Ended:

Time:

Location:

Catherine Heights Rd Manhole # 1750 overflowed into Gulpha Creek (still overflowing at this time.)

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- <=""> Other Overflow Type:

(Enter overflow type if not listed)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Volume:

Still overflowing at still time.

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Shawn Davis** Title **Sewer Collection Manager** Telephone Number **501-623-6981**

Additional Comments if Needed:

CONFIRMATION NUMBER

5837413F-38CE-4B06-BCEE-9C523348AE10

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 5837413F-38CE-4B06-BCEE-9C523348AE10

Date Sent: 2/3/2014

SSO Bypass Upset

Facility Permit Number: **AR0033880**

Facility name:

Hot Springs Wastewater

Date Overflow Began: **02/02/2014**

Time:

1:30pm

Date Overflow Ended: **02/02/2014**

Time:

7:30pm

Location:

Spring St. Manhole # 4117 overflowed into Gulpha Creek

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- <=""> Other Overflow Type:

(Enter overflow type if not listed)

Volume: **4,000**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Raked & Picked Up Debris

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Shawn Davis** Title **Sewer Collection Manager** Telephone Number **501-623-63981**

Additional Comments if Needed:

CONFIRMATION NUMBER

613F726A-6A63-43DD-AC82-A0EDE4B96736

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 613F726A-6A63-43DD-AC82-A0EDE4B96736

Date Sent: 2/3/2014

SSO Bypass Upset

Facility Permit Number: **AR0033880**

Facility name:

Hot Springs Wastewater

Date Overflow Began: **02/02/2014**

Time:

2:00 pm

Date Overflow Ended: **02/02/2014**

Time:

7:30pm

Location:

McLeod St Manhole # 993 overflowed into Stokes Creek

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- <=""> Other Overflow Type:

(Enter overflow type if not listed)

Volume: 5000

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Raked & Picked Up Debris

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Shawn Davis** Title **Sewer Collection Manager** Telephone Number **501-623-6981**

Additional Comments if Needed:

[Empty box for additional comments]

CONFIRMATION NUMBER

8875F45B-F6F4-4116-9A87-B528039EEC3E

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 8875F45B-F6F4-4116-9A87-B528039EEC3E

Date Sent: 2/3/2014

SSO Bypass Upset

Facility Permit Number: **AR0033880**

Facility name:

Hot Springs Wastewater

Date Overflow Began: **02/02/2014**

Time:

1:00 pm

Date Overflow Ended: **02/03/2014**

Time:

1:00 pm

Location:

Catherine Heights Rd. Manhole # 1750 overflowed into Gulpha Creek

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 45000

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe **Raked & Picked Up Debris**

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Shawn Davis** Title **Sewer Collection Manager** Telephone Number **501-623-6981**

Additional Comments if Needed:

CONFIRMATION NUMBER

57480CFF-EA6B-4F30-9E64-84C509F2D313

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 57480CFF-EA6B-4F30-9E64-84C509F2D313

Date Sent: 2/5/2014

SSO Bypass Upset

Facility Permit Number: **AR0033880**

Facility name:

Hot Springs Wastewater

Date Overflow Began: **02/04/2014**

Time:

5:00 pm

Date Overflow Ended: **02/04/2014**

Time:

7:00 pm

Location:

Gorge Rd. Manhole# 3319 overflowed into Gulpha Creek

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **600**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe **Raked & Picked Up Debris**

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Shawn Davis** Title **Sewer Collection Manager** Telephone Number **501-623-6981**

Additional Comments if Needed:

CONFIRMATION NUMBER

797FA601-E106-40A9-B295-78B4078E0474

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 797FA601-E106-40A9-B295-78B4078E0474

Date Sent: 2/5/2014

SSO Bypass Upset

Facility Permit Number: **AR0033880**
Date Overflow Began: **02/04/2014**
Date Overflow Ended: **02/05/2014**
Location:

Facility name: **Hot Springs Wastewater**
Time: **3:00 pm**
Time: **5:00am**

Forestveiw Court Manhole # 12242 overflowed into Hot Springs Creek

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- <=""> Other Overflow Type:

(Enter overflow type if not listed)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Volume: 7500

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe **Raked & Picked Up Debris**

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Shawn Davis** Title **Sewer Collection Manager** Telephone Number **501-623-6981**

Additional Comments if Needed:

Sanitary Sewer Overflow (SSO) Monthly Report

ility Name: Hot Springs Wastewater NPDES Permit No.: AR0033880 Monitoring Period (Month/Year) February / 2014

No Sanitary Sewer Overflows This Monitoring Period


Summary Report Code Descriptions

Cause(s) of SSO	SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO-Construction	D-Debris	NEAH-No Evidence Adverse Health/Environmental Impact	CR-Creek/Stream/River (specify)
E-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	DI-Ditch
HC-Hydro Clean	LF-Line Failure	EFK-Evidence of Fish Kill	DR-Drop Inlet
R-Rainfall	RG-Roots/Grease	HR-Hand Rodded	GR-Ground Surface
RO-Roots	V-Vandalism	EN-Referred to Engineering	PA-Paved Area
		PN-Public Notification	CB-Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Discharge Location
Spring St.	MH# 4118	02/04/2014	02/05/2014	3500	R	NEAH	EC	CR-Gulpha
Catherine Heights Rd.	MH# 1750	02/04/2014	Still overflowing		R	NEAH		CR--Gulpha
Catherine Heights Rd.	MH# 7150 1750 SS	02/04/2014	02/09/2014	Undetermined	R	NEAH	EC	CR-Gulpha

Signature of Cognizant or Ranking Official

Date



3-13-2014

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are

CONFIRMATION NUMBER

D87EE80D-D713-4779-9038-05E41CA1BFED

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: D87EE80D-D713-4779-9038-05E41CA1BFED

Date Sent: 2/5/2014

SSO Bypass Upset

Facility Permit Number: **AR0033880**

Facility name:

Hot Springs Wastewater

Date Overflow Began: **02/04/2014**

Time:

3:00 pm

Date Overflow Ended: **02/05/2014**

Time:

1:00am

Location:

Spring St. Manhole # 4118 overflowed into Gulpha Creek

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 3500

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Raked & Picked Up Debris

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Shawn Davis** Title **Sewer Collection Manager** Telephone Number **501-623-6981**

Additional Comments if Needed:

CONFIRMATION NUMBER

6470B608-706C-4E42-B5BB-B469A82A5A47

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 6470B608-706C-4E42-B5BB-B469A82A5A47
Date Sent: 2/5/2014

SSO Bypass Upset

Facility Permit Number: **AR0033880**
Date Overflow Began: **02/04/2014**
Date Overflow Ended:
Location:

Facility name: **Hot Springs Wastewater**
Time: **3:00 pm**

Catherine Heights Rd. Manhole # 1750 overflowing into Gulpha Creek

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Volume: **Still overflowing at still time.**
(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river,stream)**

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Shawn Davis** Title **Sewer Collection Manager** Telephone Number **501-623-6981**

Additional Comments if Needed:

CONFIRMATION NUMBER

F2A15788-DA81-4181-AFE9-E5A0D8938ACC

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: F2A15788-DA81-4181-AFE9-E5A0D8938ACC

Date Sent: 2/10/2014

SSO Bypass Upset

Facility Permit Number: **AR0033880**

Facility name:

HOT SPRINGS WASTEWATER

Date Overflow Began: **2/4/2014**

Time:

3:00 pm

Date Overflow Ended: **2/9/2014**

Time:

3:00 pm

Location:

MH# 1750, CATHERINE HEIGHTS RD, RAN OVER IN GULPHA CREEK

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume:

UNDETERMINED

(Give an estimate in gallons)

Impact of SSO Event:

SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

RAKED UP

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **CHRIS GORDON**

Title **MAINTENANCE CONTROLLER**

Telephone Number **(501) 623-7963**

Additional Comments if Needed: