## Sanitary Sewer Overflow (SSO) Monthly Report

ility Name:	Hot Springs Wastewater	NPDES Permit No.:	AR0033880	Monitoring Period (Month/Year)	April	/_	2014

## □ No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions								
Cause(s) of SSO		SSO Impact	Action(s) Taken	Ultimate Discharge Location				
<b>CO</b> -Construction	<b>D</b> -Debris	<b>NEAH</b> -No Evidence Adverse Health/Environmental. Impact	·	CR-Creek/Stream/River (specify)				
E-Equipment Failure	<b>G-</b> Grease	<b>OEHC</b> -Observed or Evidence of Human Contact	EC-Environmental Cleanup	<b>DI</b> -Ditch				
<b>HC</b> -Hydro Clean	<b>LF-</b> Line Failure	<b>EFK-</b> Evidence of Fish Kill	<b>HC</b> -Hydro Cleaned	DR-Drop Inlet				
<b>R-</b> Rainfall	RG-Roots/Grease		HR-Hand Rodded	GR-Ground Surface				
RO-Roots	<b>V-</b> Vandalism		EN-Referred to Engineering	PA-Paved Area				
			PN-Public Notification	CB-Contained in Building				

Location	Manhole #	Start Date of	End Date of SSO	Estimated Volume	Cause of	Environmental	Action(s) Taken to	Discharge Location
		SSO		(in gallons)	SSO	Impact	Address SSO	<u>.</u>
Gorge Rd.	MH# 3327	04/13/2014	04/14/2014	20000	R	NEAH	HC & EC	CRGulpha
Gorge Rd.	MH# 3347	04/13/2014	04/14/2014	22000	R	NEAH	HC & EC	CRGulpha
Spring St.	MH# 4117	04/13/2014	04/14/2014	15000	R	NEAH	EC	CRGulpha
Spring St.	MH# 4118	04/13/2014	04/14/2014	20000	R	NEAH	EC	CRGulpha
McLeod St.	MH# 991	04/13/2014	04/14/2014	23000	R	NEAH	EC	CRStokes
McLeod St.	MH# 993	04/13/2014	04/14/2014	27000	R	NEAH	EC	CRStokes
McLeod St.	MH# 998	04/13/2014	04/14/2014	31000	R	NEAH	EC	CRStokes
Forest View Ct.	MH# 12242	04/13/2014	04/14/2014	24000	R	NEAH	EC	CR—Hot Springs
Fontana St.	MH# 1865	04/13/2014	04/14/2014	30000	R	NEAH	EC	CR—Hot Springs
Carpenter Dam Rd.	MH# 5259	04/13/2014	04/14/2014	18000	R	NEAH	нс	CRUnknown
Catherine Heights Rd.	MH# 1750	04/13/2014	04/15/2014	65000	R	NEAH	EC	CRGulpha

Signature of Cognizant or Ranking Official

Date

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment of knowing violations.

## **Sanitary Sewer Overflow (SSO) Monthly Report**

lity Name:	Hot Springs Wastewater	NPDES Permit No.:	AR0033880	Monitoring Period (Month/Year)	April	/ _2014
------------	------------------------	-------------------	-----------	--------------------------------	-------	---------

## ☐ No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions								
Cause(s) of SSO		SSO Impact	Action(s) Taken	Ultimate Discharge Location				
<b>CO</b> -Construction	<b>D</b> -Debris	<b>NEAH-</b> No Evidence Adverse Health/Environmental. Impact		CR-Creek/Stream/River (specify)				
E-Equipment Failure	<b>G</b> -Grease	<b>OEHC</b> -Observed or Evidence of Human Contact	EC-Environmental Cleanup	<b>DI</b> -Ditch				
HC-Hydro Clean	<b>LF-</b> Line Failure	<b>EFK</b> -Evidence of Fish Kill	<b>HC</b> -Hydro Cleaned	DR-Drop Inlet				
<b>R</b> -Rainfall	RG-Roots/Grease		HR-Hand Rodded	<b>GR</b> -Ground Surface				
RO-Roots	<b>V-</b> Vandalism		<b>EN</b> -Referred to Engineering	PA-Paved Area				
			PN-Public Notification	CB-Contained in Building				

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Discharge Location
McLeod St.	MH# 991	04/13/2014		Still overflowing	33U R	NEAH	Address 550	CR-Stokes
		<del></del>			<u> </u>	<del> </del>		
McLeod St.	MH# 993	04/13/2014		Still Overflowing	R	NEAH		CRStokes
McLeod St.	MH# 998	04/13/2014		Still Overflowing	R	NEAH		CRStokes
Catherine Heights Rd.	MH# 1750	04/13/2014		Still Overflowing	R	NEAH		CRGulpha
Spring St.	MH# 4117	04/13/2014		Still Overflowing	R	NEAH		CRGulpha
Spring St.	MH# 4118	04/13/2014		Still Overflowing	Ř	NEAH		CRGulpha
Forestveiw Court	MH# 12242	04/13/2014		Still Overflowing	R	NEAH		CR—Hot Springs
Fontana Rd.	MH# 1865	04/13/2014		Still Overflowing	R	NEAH		CR—Hot Springs
Carpenter Dam Rd.	MH# 5259	04/13/2014		Still Overflowing	R	NEAH		CRUnknown
Gorge Rd.	MH# 3327	04/13/2014		Still Overflowing	R	NEAH		CRGulpha
Gorge Rd.	MH# 3347/	04/13/2014		Still Overflowing	R	NEAH		CRGulpha

Signature of Cognizant or Ranking Official

Date

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment of knowing violations.