

Sanitary Sewer Overflow (SSO) Monthly Report


ility Name: Hot Springs Wastewater NPDES Permit No.: AR0033880 Monitoring Period (Month/Year) August / 2012

No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions

Cause(s) of SSO	SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO -Construction	D -Debris	NEAH -No Evidence Adverse Health/Environmental Impact	CR -Creek/Stream/River (specify)
E -Equipment Failure	G -Grease	OEHC -Observed or Evidence of Human Contact	DI -Ditch
HC -Hydro Clean	LF -Line Failure	EFK -Evidence of Fish Kill	DR -Drop Inlet
R -Rainfall	RG -Roots/Grease		GR -Ground Surface
RO -Roots	V -Vandalism		PA -Paved Area
		EN -Referred to Engineering	CB -Contained in Building
		PN -Public Notification	

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Discharge Location
Fontana Rd.	MH# 1866	08/24/12	08/24/12	10,000	E	NEAH	HC & EC	CR-Hot Springs
201 McMahan Dr.	MH# 2025	08/29/12	08/29/12	500	RG	NEAH	HC	GR



Signature of Cognizant or Ranking Official

9/12/12
Date

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment of knowing violations.

CONFIRMATION NUMBER

06C0CEBF-2579-4663-AD04-7F0586E4FC30

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 06C0CEBF-2579-4663-AD04-7F0586E4FC30
Date Sent: 8/27/2012

SSO Bypass Upset

Facility Permit Number: **AR0033880** Facility name: **Hot Springs Wastewater**
 Date Overflow Began: **08/24/12** Time: **5:00 pm**
 Date Overflow Ended: **08/24/12** Time: **6:00 pm**
 Location:

Fontana Rd. Manhole # 1866 @ Hot Springs Creek Pump Station overflowed into Hot Springs Creek.

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: **10,000**

(Give an estimate in gallons)

Impact of SSO Event: **SSO Reached Receiving Water (river, stream)**

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause: **Tripped Control Breaker**

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe **Raked & Picked Up Debris**

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Shawn Davis** Title **Sewer Collection Manager** Telephone Number **(501) 623-6981**

Additional Comments if Needed:

CONFIRMATION NUMBER

08674502-99FC-4D17-ACBE-1066027681F8

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 08674502-99FC-4D17-ACBE-1066027681F8

Date Sent: 8/29/2012

SSO Bypass Upset

Facility Permit Number: **AR0033880** Facility name: **Hot Springs Wastewater**

Date Overflow Began: **08/29/2012** Time: **11:30 am**

Date Overflow Ended: **08/29/2012** Time: **2:00 pm**

Location: **201 McMahan Dr. Manhole # 2025 overflowed into lower yard.**

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Volume:

500

(Give an estimate in gallons)

Impact of SSO Event:

SSO Affected Private Property (ground)

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded Disinfected and Deodorized
- Jet-Vac Hydro Cleaned
- Hand rodded Spread Lime on Affected Area
- Used Generator To Power Pumps/Equipment Public Notification
- Other: Describe

Environmental Damage

- OEHC - Observed or Evidence of Human Contact NEAH - No Evidence of Adverse Health/Environmental Impact
- OEI - Observed or Evidence of Environmental Impact EFK - Evidence of Fish Kill

Reported By **Shawn Davis**

Title **Sewer Collection Manager**

Telephone Number **(501) 623-6981**

Additional Comments if Needed:



**City of Hot Springs
Utilities Department**

780 Adams
Post Office Box 700
Hot Springs National Park,
Arkansas 71902

CERTIFIED MAIL™



7010 0290 0000 5195 6575



02 1P

\$ 005.95⁰

0003062254

SEP 12 2012

MAILED FROM ZIP CODE 71901

ADEQ
NPDES Enforcement Section
Attn: Mo Shafii
5301 Northshore Dr.
North Little Rock, AR 72118-5317

72118531799

