


Sanitary Sewer Overflow (SSO) Monthly Report

Facility Name: Hot Springs Wastewater NPDES Permit No.: AR0033880 Monitoring Period (Month/Year) August / 2015

No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions				
Cause(s) of SSO	SSO Impact	Action(s) Taken	Ultimate Discharge Location	
CO -Construction	D -Debris	NEAH -No Evidence Adverse Health/Environmental Impact		CR -Creek/Stream/River (specify)
E -Equipment Failure	G -Grease	OEHC -Observed or Evidence of Human Contact	EC -Environmental Cleanup	DI -Ditch
HC -Hydro Clean	LF -Line Failure	EFK -Evidence of Fish Kill	HC -Hydro Cleaned	DR -Drop Inlet
R -Rainfall	RG -Roots/Grease		HR -Hand Rodded	GR -Ground Surface
RO -Roots	V -Vandalism		EN -Referred to Engineering	PA -Paved Area
			PN -Public Notification	CB -Contained in Building


Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Discharge Location
2816 Albert Pike Rd.	20" Pressure Sewer Main	08/20/2015	08/20/2015	Undetermined	LF	NEAH	EC & HC	CR—Lake Hamilton
176 Emerson Pt.	Emerson Pt. Pump Station	08/25/2015	08/25/2015	100	E	NEAH	EC	GR—Ground Surface
Chadwood Dr.	Chadwood Pump Station	08/30/2015	08/30/2015	2500	PF	NEAH	EC	CR--Unknown


 Signature of Cognizant or Ranking Official

9-17-2015
 Date

OF THE RETURN ADDRESS, FOLD AT DOTTED LINE
CERTIFIED MAIL


City of
Treat
320 D
Hot Springs, AR 71901



7015 0640 0000 3285 0553



1000



72118

U.S. POSTAGE
PAID
HOT SPRINGS NATIONAL PARK, A
71913
SEP 18, 15
AMOUNT
\$7.89
R2304H108744-05

**RETURN RECEIPT
REQUESTED**

Arkansas Department of Environmental
Quality
5301 North Shore Drive
North Little Rock, AR 72118-5317