


# Sanitary Sewer Overflow (SSO) Monthly Report

Facility Name: Hot Springs Wastewater NPDES Permit No.: AR0033880 Monitoring Period (Month/Year) December / 2014

**No Sanitary Sewer Overflows This Monitoring Period**

Summary Report Code Descriptions				
Cause(s) of SSO	SSO Impact	Action(s) Taken	Ultimate Discharge Location	
CO-Construction	D-Debris	NEAH-No Evidence Adverse Health/Environmental Impact		CR-Creek/Stream/River (specify)
E-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup	DI-Ditch
HC-Hydro Clean	LF-Line Failure	EFK-Evidence of Fish Kill	HC-Hydro Cleaned	DR-Drop Inlet
R-Rainfall	RG-Roots/Grease		HR-Hand Rodded	GR-Ground Surface
RO-Roots	V-Vandalism		EN-Referred to Engineering	PA-Paved Area
			PN-Public Notification	CB-Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Discharge Location
Catherine Heights Rd.	Manhole # 1750	12/08/2014	12/08/2014	2500	D	NEAH	EC	CR-Gulpha
111 Jefferson St.	Manhole # 2506	12/14/2014	12/14/2014	3000	RO	NEAH	HC	CR--Hot Springs
Catherine Heights Rd.	Manhole # 1750	12/29/2014	12/29/2014	Undetermined	D	NEAH	EC	CR--Gulpha

  
 Signature of Cognizant or Ranking Official

1-1-2015  
 Date