

Sanitary Sewer Overflow (SSO) Monthly Report

Facility Name: Hot Springs Wastewater NPDES Permit No.: AR0033880 Monitoring Period (Month/Year) January / 2016

No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions

Cause(s) of SSO	SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO -Construction	D -Debris	NEAH -No Evidence Adverse Health/Environmental Impact	CR -Creek/Stream/River (specify)
E -Equipment Failure	G -Grease	OEHC -Observed or Evidence of Human Contact	DI -Ditch
HC -Hydro Clean	LF -Line Failure	EFK -Evidence of Fish Kill	DR -Drop Inlet
R -Rainfall	RG -Roots/Grease	HR -Hand Rodded	GR -Ground Surface
RO -Roots	V -Vandalism	EN -Referred to Engineering	PA -Paved Area
		PN -Public Notification	CB -Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Discharge Location
127 Foxwood St.	Hot Springs #4 Pump Station	01/05/2016	01/05/2016	3000	E	NEAH	EC	GR—Ground
615 McLeod St.	MH# 998	01/09/2016		Sill Overflowing	R	NEAH		CR--Stokes
519 McLeod St.	MH# 995	01/09/2016		Still Overflowing	R	NEAH		CR--Stokes
403 McLeod St.	MH# 991	01/09/2016		Still Overflowing	R	NEAH		CR-- Stokes
857 Carpenter Dam Rd.	MH# 5259	01/09/2016		Still Overflowing	R	NEAH		CR--Unknown
816Carpenter Dam Rd.	MH# 5260	01/09/2016		Still Overflowing	R	NEAH		CR--Unknown
3047 Malvern Ave.	MH# 1747	01/09/2016		Still Overflowing	R	NEAH		CR--Gulpha
1539 Spring St.	MH# 4117	01/09/2016		Still Overflowing	R	NEAH		CR--Gulpha
1539 Spring St.	MH# 4118	01/09/2016		Still Overflowing	R	NEAH		CR—Gulpha
362 Fontana Rd.	MH# 1865	01/09/2016		Still Overflowing	R	NEAH		CR—Hot Springs
352 Fontana Rd.	MH# 1866	01/09/2016		Still Overflowing	R	NEAH		CR—Hot Springs

Signature of Cognizant or Ranking Official

Date

2-16-2016

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are

Sanitary Sewer Overflow (SSO) Monthly Report

Facility Name: Hot Springs Wastewater NPDES Permit No.: AR0033880 Monitoring Period (Month/Year) January / 2016

No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions				
Cause(s) of SSO		SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO-Construction	D-Debris	NEAH-No Evidence Adverse Health/Environmental Impact		CR-Creek/Stream/River (specify)
E-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup	DI-Ditch
HC-Hydro Clean	LF-Line Failure	EFK-Evidence of Fish Kill	HC-Hydro Cleaned	DR-Drop Inlet
R-Rainfall	RG-Roots/Grease		HR-Hand Rodded	GR-Ground Surface
RO-Roots	V-Vandalism		EN-Referred to Engineering	PA-Paved Area
			PN-Public Notification	CB-Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Discharge Location
106 Forest View Ct.	MH# 12242	01/09/2016		Still Overflowing	R	NEAH		CR—Hot Springs
104 Forest View Ct.	MH# 1864	01/09/2016		Still Overflowing	R	NEAH		CR—Hot Springs
816 Carpenter Dam Rd.	MH# 5260	01/09/2016	01/09/2016	5000	R	NEAH	EC	CR--Unknown
362 Fontana Rd.	MH# 1865	01/09/2016	01/09/2016	8500	R	NEAH	EC	CR—Hot Springs
104 Forest View Ct.	MH# 1864	01/09/2016	01/09/2016	5000	R	NEAH	EC	CR—Hot Springs
403 McLeod St.	MH# 991	01/09/2016	01/09/2016	7500	R	NEAH	EC	CR--Stokes
857 Carpenter Dam Rd.	MH# 5259	01/09/2016	01/10/2016	10000	R	NEAH	EC	CR--Unknown
352 Fontana Rd.	MH# 1866	01/09/2016	01/10/2016	14000	R	NEAH	EC	CR—Hot Springs
1539 Spring St.	MH# 4117	01/09/2016	01/10/2016	7000	R	NEAH	EC	CR--Gulpha
1539 Spring St.	MH# 4118	01/09/2016	01/10/2016	7000	R	NEAH	EC	CR--Gulpha
519 McLeod St.	MH# 995	01/09/2016	01/10/2016	9000	R	NEAH	EC	CR--Stokes


Signature of Cognizant or Ranking Official

2-16-2016
Date

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment of knowing violations.

Sanitary Sewer Overflow (SSO) Monthly Report

Facility Name: Hot Springs Wastewater NPDES Permit No.: AR0033880 Monitoring Period (Month/Year) January / 2016

No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions

Cause(s) of SSO	SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO -Construction	D -Debris	NEAH -No Evidence Adverse Health/Environmental Impact	CR -Creek/Stream/River (specify)
E -Equipment Failure	G -Grease	OEHC -Observed or Evidence of Human Contact	EC -Environmental Cleanup
DI -Ditch	HC -Hydro Clean	EFK -Evidence of Fish Kill	DI -Ditch
DR -Drop Inlet	LF -Line Failure	HR -Hand Rodded	DR -Drop Inlet
GR -Ground Surface	R -Rainfall	EN -Referred to Engineering	GR -Ground Surface
PA -Paved Area	RG -Roots/Grease	PN -Public Notification	PA -Paved Area
CB -Contained in Building	RO -Roots		CB -Contained in Building
	V -Vandalism		


Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Discharge Location
615 McLeod St.	MH# 998	01/09/2016	01/10/2016	10000	R	NEAH	EC	CR--Stokes
106 Forest View Ct.	MH# 12242	01/09/2016	01/10/2016	15000	R	NEAH	EC	CR--Hot Springs

A-S
2-16-2016

Signature of Cognizant or Ranking Official Date

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment of knowing violations.

City of Hot Springs Wastewater
Treatment Plant
320 Davidson Dr.
Hot Springs, AR 71901



Arkansas Department of Environmental
Quality
5301 North Shore Drive
North Little Rock, AR 72118-5317

