

Sanitary Sewer Overflow (SSO) Monthly Report

OCT 27 2015
RECEIVED


Community Name: Hot Springs Wastewater NPDES Permit No.: AR0033880 Monitoring Period (Month/Year) September / 2015

POST
OCT 22 2015
MARKED

No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions				
Cause(s) of SSO	SSO Impact	Action(s) Taken	Ultimate Discharge Location	
CO-Construction	D-Debris	NEAH-No Evidence Adverse Health/Environmental Impact		CR-Creek/Stream/River (specify)
E-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup	DI-Ditch
HC-Hydro Clean	LF-Line Failure	EFK-Evidence of Fish Kill	HC-Hydro Cleaned	DR-Drop Inlet
R-Rainfall	RG-Roots/Grease		HR-Hand Rodded	GR-Ground Surface
RO-Roots	V-Vandalism		EN-Referred to Engineering	PA-Paved Area
			PN-Public Notification	CB-Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Discharge Location
2816 Albert Pike Rd.	20" Pressure Sewer Main	08/20/2015	08/20/2015	28,845 Revision for last month SSO	LF	NEAH	HC & EC	CR—Lake Hamilton
421 Lakepark Dr.	Carpenter Dam Pump Station	09/21/2015	09/21/2015	300	P	NEAH	EC	GR-Ground
Lakeland Dr. & Lake Hamilton Dr.	Hot Springs #2 Pump Station	09/26/2015	09/26/2015	1000	E	NEAH	EC	CR—Lake Hamilton


Signature of Cognizant or Ranking Official

10-20-2015
Date