

Sanitary Sewer Overflow (SSO) Monthly Report

Facility Name: Hot Springs Wastewater NPDES Permit No.: AR0033880 Monitoring Period (Month/Year) June / 2015

No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions					
Cause(s) of SSO		SSO Impact		Action(s) Taken	Ultimate Discharge Location
CO-Construction	D-Debris	NEAH-No Evidence Adverse Health/Environmental Impact			CR-Creek/Stream/River (specify)
E-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact		EC-Environmental Cleanup	DI-Ditch
HC-Hydro Clean	LF-Line Failure	EFK-Evidence of Fish Kill		HC-Hydro Cleaned	DR-Drop Inlet
R-Rainfall	RG-Roots/Grease			HR-Hand Rodded	GR-Ground Surface
RO-Roots	V-Vandalism			EN-Referred to Engineering	PA-Paved Area
				PN-Public Notification	CB-Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Discharge Location
Foxwood St. & Burchwood Bay Rd.	Hot Springs # 4 Pump Station	06/21/2015	06/21/2015	2000	E	NEAH	EC	GR—Ground Surface

Signature of Cognizant or Ranking Official

Date

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

Close this window Print this page

24-Hour Sanitary Sewer Overflow Report

SSO ID#: B1DDD50D-87E5-44D3-B9C3-297552A22981

Date Sent: 6/21/2015

SSO Bypass Upset

Facility Permit Number: AR0033880

Date Overflow Began: 06/21/2015

Date Overflow Ended: 06/21/2015

Location:

Facility name:

Time:

Time:

Hot Springs Wastewater

11:00 am

11:30 am

Foxwood St. & Burchwood Bay Rd. Hot Springs #4 Pump Station overflowed onto ground

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Volume: 2000

(Give an estimate in gallons)

Impact of SSO Event: SSO Affected Private Property (ground)

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification
- raked and picked up debris

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- OEEI - Observed or Evidence of Environmental Impact
- EFK - Evidence of Fish Kill

Reported By Shawn Davis Title Sewer Collection Manager Telephone Number (501) 623-6981

Additional Comments if Needed:

[Empty box for additional comments]

Email a Copy of This Report to the Email Address: