

Sanitary Sewer Overflow (SSO) Monthly Report


Facility Name: Hot Springs Wastewater NPDES Permit No.: AR0033880 Monitoring Period (Month/Year) March / 2015

No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions					
Cause(s) of SSO		SSO Impact		Action(s) Taken	Ultimate Discharge Location
CO-Construction	D-Debris	NEAH-No Evidence Adverse Health/Environmental Impact			CR-Creek/Stream/River (specify)
E-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact		EC-Environmental Cleanup	DI-Ditch
HC-Hydro Clean	LF-Line Failure	EFK-Evidence of Fish Kill		HC-Hydro Cleaned	DR-Drop Inlet
R-Rainfall	RG-Roots/Grease			HR-Hand Rodded	GR-Ground Surface
RO-Roots	V-Vandalism			EN-Referred to Engineering	PA-Paved Area
				PN-Public Notification	CB-Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Discharge Location
McLeod St.	MH# 998	03/10/2015		Still Overflowing at this time	R	NEAH		CR-Stokes
McLeod St.	MH# 993	03/10/2015		Still Overflowing at this time	R	NEAH		CR-Stokes
Malvern Ave	MH# 1747	03/10/2015		Still Overflowing at this time	R	NEAH		CR-Gulpha
Carpenter Dam Rd.	MH# 5259	03/10/2015		Still Overflowing at this time	R	NEAH		CR--Unknown
Spring St.	MH# 4118	03/10/2015		Still Overflowing at this time.	R	NEAH		CR-Gulpha
Spring St.	MH# 4118	03/10/2015	03/10/2015	5000	R	NEAH	EC	CR-Gulpha
McLeod St.	MH# 993	03/10/2015	03/10/2015	75000	R	NEAH	EC	CR--Stokes
McLeod St.	MH# 998	03/10/2015	03/10/2015	115000	R	NEAH	EC	CR--Stokes
Carpenter Dam Rd.	MH# 5259	03/10/2015	03/10/2015	150000	R	NEAH	EC & HC	CR--Unknown
Malvern Ave.	MH# 1747	03/10/2015			R	NEAH	EC	CR--Gulpha
McLeod St	MH# 998	03/12/2015		Still Overflowing	R	NEAH		CR-Stokes


Signature of Cognizant or Ranking Official

 4-17-2015
Date

Sanitary Sewer Overflow (SSO) Monthly Report

Facility Name: Hot Springs Wastewater NPDES Permit No.: AR0033880 Monitoring Period (Month/Year) March / 2015

No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions				
Cause(s) of SSO		SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO-Construction	D-Debris	NEAH-No Evidence Adverse Health/Environmental Impact		CR-Creek/Stream/River (specify)
E-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup	DI-Ditch
HC-Hydro Clean	LF-Line Failure	EFK-Evidence of Fish Kill	HC-Hydro Cleaned	DR-Drop Inlet
R-Rainfall	RG-Roots/Grease		HR-Hand Rodded	GR-Ground Surface
RO-Roots	V-Vandalism		EN-Referred to Engineering	PA-Paved Area
			PN-Public Notification	CB-Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Discharge Location
128 Shore Acres	MH# 9760	03/13/2015		Still Overflowing	R	NEAH		CR-Lake Hamilton
Hollywood Ave	MH# 138	03/13/2015		Still Overflowing	R	NEAH		DI-Ditch
793 Adams St	MH# 1899	03/13/2015	03/13/2015	2500	R	NEAH	HC	PA
797 Adams St	MH# 4206	03/13/2015		Still Overflowing	R	NEAH		CR-Hot Springs
797 Adams St	MH# 4206	03/13/2015	03/13/2015	3500	R	NEAH	EC	CR-HotSprings
202 Shady Grove Rd.	MH# 166	03/13/2015	03/13/2015	10000	R	NEAH	EC	CR-Hot Springs
Hollywood Ave.	MH# 138	03/13/2015	03/13/2015	4500	R	NEAH	EC	DI
611 E. Grand Ave	MH# 10578	03/13/2015	03/13/2015	4000	R	NEAH	HC	DI
128 Shore Acres	MH# 9760	03/13/2015	03/14/2015	4500	R	NEAH	EC	CR-Lake Hamilton
Forest View Ct.	MH# 12242	03/13/2015	03/14/2015	400000	R	NEAH	EC	CR-Hot Springs
816 Carpenter Dam Rd.	MH# 5260	03/13/2015	03/14/2015	200000	R	NEAH	EC	CR-Unknown

Signature of Cognizant or Ranking Official

Date 4-17-15

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment of knowing violations.

Sanitary Sewer Overflow (SSO) Monthly Report


Facility Name: Hot Springs Wastewater NPDES Permit No.: AR0033880 Monitoring Period (Month/Year) March / 2015

No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions

Cause(s) of SSO	SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO -Construction	D -Debris	NEAH -No Evidence Adverse Health/Environmental Impact	CR -Creek/Stream/River (specify)
E -Equipment Failure	G -Grease	OEHC -Observed or Evidence of Human Contact	DI -Ditch
HC -Hydro Clean	LF -Line Failure	EFK -Evidence of Fish Kill	DR -Drop Inlet
R -Rainfall	RG -Roots/Grease		HR -Hand Rodded
RO -Roots	V -Vandalism		EN -Referred to Engineering
		PN -Public Notification	PA -Paved Area
			CB -Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Discharge Location
Spring St.	MH# 4117	03/13/2015	03/14/2015	45000	R	NEAH	EC	CR--Gulpha
McLeod St.	MH# 991	03/12/2015	03/14/2015	175000	R	NEAH	EC	CR-Stokes
Spring St.	MH# 4118	03/12/2015	03/14/2015	60000	R	NEAH	EC	CR--Gulpha
McLeod St.	MH# 993	03/12/2015	03/15/2015	Undetermined	R	NEAH	EC	CR--Stokes
McLeod St.	MH# 998	03/12/2015	03/15/2015	Undetermined	R	NEAH	EC	CR--Stokes
Carpenter Dam Rd.	MH# 5259	03/12/2015	03/15/2015	Undetermined	R	NEAH	EC	CR-Unknown
Malvern Ave	MH# 1747	03/12/2015	03/15/2015	Undetermined	R	NEAH	EC	CR--Gulpha
Carpenter Dam Rd.	MH# 5259	03/22/2015		Still Overflowing	R	NEAH		CR-Unknown
Carpenter Dam Rd.	MH# 5259	03/22/2015	03/22/2015	450000	R	NEAH	EC	CR-Unknown
314 West St. Louis(VOID)	Service Line	03/27/2015	VOID	VOID	VOID	VOID	VOID	VOID
314 West St. Louis	Service Line	03/26/2015		Still Overflowing	LF	NEAH		DR

Signature of Cognizant or Ranking Official:  Date: 4-17-15

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment of knowing violations.

Sanitary Sewer Overflow (SSO) Monthly Report

Facility Name: Hot Springs Wastewater NPDES Permit No.: AR0033880 Monitoring Period (Month/Year) March / 2015

No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions

Cause(s) of SSO	SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO-Construction	D-Debris	NEAH-No Evidence Adverse Health/Environmental Impact	CR-Creek/Stream/River (specify)
E-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup
HC-Hydro Clean	LF-Line Failure	EFK-Evidence of Fish Kill	DI-Ditch
R-Rainfall	RG-Roots/Grease		DR-Drop Inlet
RO-Roots	V-Vandalism		HR-Hand Rodded
		EN-Referred to Engineering	GR-Ground Surface
		PN-Public Notification	PA-Paved Area
			CB-Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Discharge Location
Forestview Ct.	MH#12242	03/12/2015		Still overflowing	R	NEAH		CR--Hot Springs
McLeod St.	MH# 993	03/12/2015		Still overflowing	R	NEAH		CR--Stookes
Carpenter Dam Rd.	MH# 5259	03/12/2015		Still overflowing	R	NEAH		CR--Unknown
Malvern Ave	MH# 1747	03/12/2015		Still overflowing	R	NEAH		CR--Gulpha
Spring St	MH# 4118	03/12/2015		Still overflowing	R	NEAH		CR--Gulpha
McLeod St.	MH# 991	03/12/2015		Still overflowin	R	NEAH		CR--Stokes
Spring St.	MH# 4117	03/12/2015		Still overflowing	R	NEAH		CR--Gulpha
816 Carpenter Dam Rd.	MH# 5260	03/13/2015		Still overflowing	R	NEAH		CR-Unknown
793 Adams St.	MH# 1899	03/13/2015		Still overflowing	R	NEAH		DI
202 Shady Grove Rd.	MH# 166	03/13/2015		Still overflowing	R	NEAH		CR-Hot Springs
611 E. Grand Ave	MH# 10578	03/13/2015		Still overflowing	R	NEAH		DI

Signature of Cognizant or Ranking Official

Date 4-17-15

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment of knowing violations.

Sanitary Sewer Overflow (SSO) Monthly Report

Facility Name: Hot Springs Wastewater NPDES Permit No.: AR0033880 Monitoring Period (Month/Year) March / 2015

No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions				
Cause(s) of SSO	SSO Impact	Action(s) Taken	Ultimate Discharge Location	
CO -Construction	D -Debris	NEAH -No Evidence Adverse Health/Environmental Impact		CR -Creek/Stream/River (specify)
E -Equipment Failure	G -Grease	OEHC -Observed or Evidence of Human Contact	EC -Environmental Cleanup	DI -Ditch
HC -Hydro Clean	LF -Line Failure	EFK -Evidence of Fish Kill	HC -Hydro Cleaned	DR -Drop Inlet
R -Rainfall	RG -Roots/Grease		HR -Hand Rodded	GR -Ground Surface
RO -Roots	V -Vandalism		EN -Referred to Engineering	PA -Paved Area
			PN -Public Notification	CB -Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Discharge Location
314 West St. Louis	Service Line	03/26/2015	03/27/2015	15000	LF	NEAH	HC & EC	DR

Signature of Cognizant or Ranking Official _____

Date _____

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment of knowing violations.