

# Sanitary Sewer Overflow (SSO) Monthly Report

Facility Name: Hot Springs Wastewater NPDES Permit No.: AR0033880 Monitoring Period (Month/Year) November / 2015

**No Sanitary Sewer Overflows This Monitoring Period**

### Summary Report Code Descriptions

Cause(s) of SSO	SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO-Construction	D-Debris	NEAH-No Evidence Adverse Health/Environmental Impact	CR-Creek/Stream/River (specify)
E-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup
HC-Hydro Clean	LF-Line Failure	EFK-Evidence of Fish Kill	DI-Ditch
R-Rainfall	RG-Roots/Grease		DR-Drop Inlet
RO-Roots	V-Vandalism		GR-Ground Surface
		EN-Referred to Engineering	PA-Paved Area
		PN-Public Notification	CB-Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Discharge Location
415 Essex Park Terrace	Malvern Hwy P.S.	11/28/2015	11/28/2015	1,500	E & R	NEAH	EC	GR -- Ground
244 Scroggins Terrace	Wilson Mill P.S.	11/28/2015	11/28/2015	1,000	R	NEAH	EC	GR--Ground
5506 Central Ave	MH# 10297	11/29/2015	11/30/2015	2,000	R	NEAH	EC	GR--Ground
152 Aberina St.	Hot Springs P.S. #1	11/30/2015	11/30/2015	2,500	R & E	NEAH	EC	GR--Ground

12-14-15

Signature of Cognizant or Ranking Official

Date

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly

## Sanitary Sewer Overflow (SSO) Monthly Report

Facility Name: Hot Springs Wastewater NPDES Permit No.: AR0033880 Monitoring Period (Month/Year) November / 2015

**No Sanitary Sewer Overflows This Monitoring Period**

### Summary Report Code Descriptions

Cause(s) of SSO	SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO-Construction	D-Debris	NEAH-No Evidence Adverse Health/Environmental Impact	CR-Creek/Stream/River (specify)
E-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup
HC-Hydro Clean	LF-Line Failure	EFK-Evidence of Fish Kill	DI-Ditch
R-Rainfall	RG-Roots/Grease	HR-Hand Rodded	DR-Drop Inlet
RO-Roots	V-Vandalism	EN-Referred to Engineering	GR-Ground Surface
		PN-Public Notification	PA-Paved Area
			CB-Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Discharge Location
405 McLeod St.	MH# 991	11/27/2015	11/30/2015	205,000	R	NEAH	EC	CR--Stokes
519 McLeod St	MH# 995	11/27/2015	11/30/2015	255,000	R	NEAH	EC	CR--Stokes
615 McLeod St.	MH# 998	11/27/2015	11/30/2015	255,000	R	NEAH	EC	CR--Stokes
1539 Spring St.	MH# 4117	11/27/2015	11/30/2015	90,000	R	NEAH	EC	CR--Gulpha
106 Forest View Ct.	MH# 12242	11/27/2015	12/01/2015	125,000	R	NEAH	EC	CR--Hot Springs
104 Forest View Ct.	MH# 1864	11/27/2015	12/01/2015	125,000	R	NEAH	EC	CR--Hot Springs
362 Fontana Rd.	MH# 1866	11/27/2015	12/01/2015	245,000	R	NEAH	EC	CR--Hot Springs
857 Carpenter Dam Rd	MH# 5259	11/27/2015	12/01/2015	95,000	R	NEAH	EC	CR--Unknown
816 Carpenter Dam Rd.	MH# 5260	11/27/2015	11/30/2015	95,000	R	NEAH	EC	CR--Unknown
3047 Malvern Ave	MH# 1747	11/27/2015	12/01/2015	255,000	R	NEAH	EC	CR--Gulpha
1539 Spring St.	MH# 4118	11/27/2015	11/30/2015	90,000	R	NEAH	EC	CR--Gulpha

Signature of Cognizant or Ranking Official

Date

*12-18-15*

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment of knowing violations.

# Sanitary Sewer Overflow (SSO) Monthly Report

Facility Name: Hot Springs Wastewater NPDES Permit No.: AR0033880 Monitoring Period (Month/Year) November / 2015

**No Sanitary Sewer Overflows This Monitoring Period**

### Summary Report Code Descriptions

Cause(s) of SSO	SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO-Construction	D-Debris	NEAH-No Evidence Adverse Health/Environmental Impact	CR-Creek/Stream/River (specify)
E-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup
HC-Hydro Clean	LF-Line Failure	EFK-Evidence of Fish Kill	DI-Ditch
R-Rainfall	RG-Roots/Grease		DR-Drop Inlet
RO-Roots	V-Vandalism		HR-Hand Rodded
		EN-Referred to Engineering	GR-Ground Surface
		PN-Public Notification	PA-Paved Area
			CB-Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Discharge Location
352 Fontana Rd.	MH# 1866	11/17/2015	11/18/2015	40000	PF & R	NEAH	EC	CR—Hot Springs
362 Fontana Rd.	MH# 1865	11/17/2015	11/18/2015	40000	PF & R	NEAH	EC	CR—Hot Springs
857 Carpenter Dam Rd.	MH# 5259	11/17/2015	11/18/2015	25000	R	NEAH	EC	CR--Unknown
816 Carpenter Dam Rd.	MH# 5260	11/17/2015	11/18/2015	15000	R	NEAH	EC	CR--Unknown
1539 Spring St.	MH# 4117	11/17/2015	11/18/2015	7000	R	NEAH	EC	CR--Gulpha
1539 Spring St.	MH# 4118	11/17/2015	11/18/2015	7500	R	NEAH	EC	CR—Gulpha
2332 Higdon Ferry Rd.	Hot Springs #3 P.S.	11/17/2015	11/18/2015	40000	PF	NEAH	HC	CR—Lake Hamilton
3047 Malvern Ave	MH# 1747	11/17/2015	11/18/2015	75000	R	NEAH	EC	CR--Gulpha
106 Forestview Ct.	MH# 12242	11/17/2015	11/18/2015	65000	R	NEAH	EC	CR—Hot Springs
116 Long Island Bay	Island #6 P.S	11/17/2015	11/19/2015	2500	PF	NEAH	HC	CR—Lake Hamilton
109 Green Cir	Island #5 P.S	11/17/2015	11/19/2015	2500	PF	NEAH	HC	CR—Lake Hamilton

Signature of Cognizant or Ranking Official

Date 12-14-15

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment of knowing violations.

## Sanitary Sewer Overflow (SSO) Monthly Report

Facility Name: Hot Springs Wastewater NPDES Permit No.: AR0033880 Monitoring Period (Month/Year) November / 2015

**No Sanitary Sewer Overflows This Monitoring Period**

### Summary Report Code Descriptions

Cause(s) of SSO	SSO Impact	Action(s) Taken	Ultimate Discharge Location
<b>CO</b> -Construction	<b>D</b> -Debris	<b>NEAH</b> -No Evidence Adverse Health/Environmental Impact	<b>CR</b> -Creek/Stream/River (specify)
<b>E</b> -Equipment Failure	<b>G</b> -Grease	<b>OEHC</b> -Observed or Evidence of Human Contact	<b>DI</b> -Ditch
<b>HC</b> -Hydro Clean	<b>LF</b> -Line Failure	<b>EFK</b> -Evidence of Fish Kill	<b>DR</b> -Drop Inlet
<b>R</b> -Rainfall	<b>RG</b> -Roots/Grease		<b>HR</b> -Hand Rodded
<b>RO</b> -Roots	<b>V</b> -Vandalism		<b>GR</b> -Ground Surface
		<b>EN</b> -Referred to Engineering	<b>PA</b> -Paved Area
		<b>PN</b> -Public Notification	<b>CB</b> -Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Discharge Location
1539 Spring St.	MH# 4117	11/17/2015		Still Overflowing	R	NEAH		CR--Gulpha
110 Jefferson St.	MH# 2506	11/17/2015		Still Overflowing	R	NEAH		CR--Hot Springs
2330 Lakeshore Dr.	MH# 12440	11/17/2015		Still Overflowing	PF & R	NEAH		CR--Lake Hamilton
2332 Higdon Ferry Rd.	Hot Springs #3 P.S.	11/17/2015		Still Overflowing	PF	NEAH		CR--Lake Hamilton
109 Green Circle	Island #5 P.S.	11/17/2015		Still Overflowing	PF	NEAH		CR--Lake Hamilton
116 Long Island Bay	Island # 6	11/17/2015		Still Overflowing	PF	NEAH		CR--Lake Hamilton
152 Aberina St.	Hot Springs #1 P.S.	11/17/2015	11/17/2015	20000	PF	NEAH	EC	CR--Lake Hamilton
579 Lake Hamilton Dr.	Hot Springs #2 P.S.	11/17/2015	11/17/2015	21000	PF	NEAH	EC	CR--Lake Hamilton
403 McLeod St.	MH# 991	11/17/2015	11/18/2015	10000	R	NEAH	EC	CR--Stokes
519 McLeod St.	MH# 995	11/17/2015	11/18/2015	12000	R	NEAH	EC	CR--Stokes
615 McLeod St.	MH# 998	11/17/2015	11/18/2015	13000	R	NEAH	EC	CR--Stokes

Signature of Cognizant or Ranking Official

Date

## Sanitary Sewer Overflow (SSO) Monthly Report


Facility Name: Hot Springs Wastewater NPDES Permit No.: AR0033880 Monitoring Period (Month/Year) November / 2015

No Sanitary Sewer Overflows This Monitoring Period

### Summary Report Code Descriptions

Cause(s) of SSO		SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO-Construction	D-Debris	NEAH-No Evidence Adverse Health/Environmental Impact		CR-Creek/Stream/River (specify)
E-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup	DI-Ditch
HC-Hydro Clean	LF-Line Failure	EFK-Evidence of Fish Kill	HC-Hydro Cleaned	DR-Drop Inlet
R-Rainfall	RG-Roots/Grease		HR-Hand Rodded	GR-Ground Surface
RO-Roots	V-Vandalism		EN-Referred to Engineering	PA-Paved Area
			PN-Public Notification	CB-Contained in Building


Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Discharge Location
360 Fontana Rd.	MH # 1866	11/06/2015	11/06/2015	2000	R	NEAH	EC	CR—Hot Springs
403 McLeod St.	MH# 991	11/17/2015		Still Overflowing	R	NEAH		CR--Stokes
519 McLeod St.	MH# 995	11/17/2015		Still Overflowing	R	NEAH		CR--Stokes
615 McLeod St.	MH# 998	11/17/2015		Still Overflowing	R	NEAH		CR--Stokes
106 Forestview Ct.	MH# 12242	11/17/2015		Still Overflowing	R	NEAH		CR—Hot Springs
362 Fontana Rd.	MH# 1866	11/17/2015		Still Overflowing	R	NEAH		CR—Hot Springs
352 Fontana Rd.	MH# 1865	11/17/2015		Still Overflowing	R	NEAH		CR—Hot Springs
857 Carpenter Dam Rd.	MH# 5259	11/17/2015		Still overflowing	R	NEAH		CR--Unknown
816 Carpenter Dam Rd.	MH# 5260	11/17/2015		Still Overflowing	R	NEAH		CR--Unknown
3047 Malvern Ave.	MH# 1747	11/17/2015		Still Overflowing	R	NEAH		CR-- Gulpha
1539 Spring St	MH# 4118	11/17/2015		Still Overflowing	R	NEAH		CR--Gulpha

  
Signature of Cognizant or Ranking Official

12-14-2015  
Date

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment of knowing violations.

City of Hot Springs  
Wastewater Treatment Plant  
320 Davidson Drive  
Hot Springs, Ar 71901



**RETURN RECEIPT  
REQUESTED**

**FIRST CLASS**

Ar Department of Environmental  
Quality  
5301 North Shore Drive  
North Little Rock, AR 72118-5317

