

Sanitary Sewer Overflow (SSO) Monthly Report

Facility Name: Hot Springs Wastewater NPDES Permit No.: AR0033880 Monitoring Period (Month/Year) October / 2014

No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions				
Cause(s) of SSO	SSO Impact	Action(s) Taken	Ultimate Discharge Location	
CO -Construction	D -Debris	NEAH -No Evidence Adverse Health/Environmental Impact		CR -Creek/Stream/River (specify)
E -Equipment Failure	G -Grease	OEHC -Observed or Evidence of Human Contact	EC -Environmental Cleanup	DI -Ditch
HC -Hydro Clean	LF -Line Failure	EFK -Evidence of Fish Kill	HC -Hydro Cleaned	DR -Drop Inlet
R -Rainfall	RG -Roots/Grease		HR -Hand Rodded	GR -Ground Surface
RO -Roots	V -Vandalism		EN -Referred to Engineering	PA -Paved Area
			PN -Public Notification	CB -Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Discharge Location
418 Essex Park Ter.	MH# 8574	10/3/2014	10/3/2014	2000	E	NEAH	HC & EC	GR
152 Aberina Dr.	MH# 8172	10/14/2014	10/14/2014	5000	E	NEAH	HC & EC	CR—Lake Hamilton

Signature of Cognizant or Ranking Official

Date 10-17-14

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment of knowing violations.

CONFIRMATION NUMBER

89490969-83D9-4857-BBDF-D74177DA7BBB

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

Close this window Print this page

24-Hour Sanitary Sewer Overflow Report

SSO ID#: 89490969-83D9-4857-BBDF-D74177DA7BBB
Date Sent: 10/3/2014

[x]SSO []Bypass []Upset

Facility Permit Number: AR0033880
Date Overflow Began: 10/3/2014
Date Overflow Ended: 10/3/2014
Location: MH # 8574, 418 ESSEX PARK TER, RAN OVER INTO YARD

Facility name: Hot Springs Wastewater
Time: 6:30 am
Time: 7:30 am

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- [x] Manhole Overflow
[] Lift Station Overflow
[] Main Line Overflow
[] Service Line Overflow
[] Other Overflow Type:

(Enter overflow type if not listed)

Volume: 2000

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Public Land Only (ground)

Cause of Overflow

- [] I & I - Rainfall
[] Roots
[] Grease
[] Debris
[x] Equipment Failure
[] Construction
[] Vandalism
[] Power Failure
[] Line Failure/Break
[] Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- [] Machine rodded [] Disinfected and Deodorized
[] Jet-Vac [x] Hydro Cleaned
[] Hand rodded [x] Spread Lime on Affected Area
[] Used Generator To Power Pumps/Equipment [] Public Notification
[] Other: Describe RAKED UP

Environmental Damage

- [] OEHC - Observed or Evidence of Human Contact [x] NEAH - No Evidence of Adverse Health/Environmental Impact
[] OEEI - Observed or Evidence of Environmental Impact [] EFK - Evidence of Fish Kill

Reported By CHRIS GORDON

Title MAINTENANCE CONTROLLER

Telephone Number (501) 623-7963

Additional Comments if Needed:

CONFIRMATION NUMBER

C28AEC67-9C31-4EE7-84FC-855DEED24E11

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

The following information has been sent.

[Close this window](#) [Print this page](#)

24-Hour Sanitary Sewer Overflow Report

SSO ID#: C28AEC67-9C31-4EE7-84FC-855DEED24E11

Date Sent: 10/15/2014

SSO Bypass Upset

Facility Permit Number: **AR0033880**

Facility name:

Hot Springs Wastewater

Date Overflow Began: **10/14/2014**

Time:

10:00 am

Date Overflow Ended: **10/14/2014**

Time:

11:00 am

Location: **M.H. #8172, 152 Aberina, stream to Lake Hamilton.**

(Give address, manhole number-if numbered. Include where the overflow went-yard, ditch, stream, storm sewer, building, other).

Type of Overflow

- Manhole Overflow
- Lift Station Overflow
- Main Line Overflow
- Service Line Overflow
- Other Overflow Type:

(Enter overflow type if not listed)

Volume: 5000 gallons

(Give an estimate in gallons)

Impact of SSO Event: SSO Reached Receiving Water (river,stream)

Cause of Overflow

- I & I - Rainfall
- Roots
- Grease
- Debris
- Equipment Failure
- Construction
- Vandalism
- Power Failure
- Line Failure/Break
- Other Cause:

Action Taken - Check all that apply

(Short term and long-term action, including clean-up and any plans to remediate I & I).

- Machine rodded
- Jet-Vac
- Hand rodded
- Used Generator To Power Pumps/Equipment
- Other: Describe
- Disinfected and Deodorized
- Hydro Cleaned
- Spread Lime on Affected Area
- Public Notification

Raked up

Environmental Damage

- OEHC - Observed or Evidence of Human Contact
- OEEI - Observed or Evidence of Environmental Impact
- NEAH - No Evidence of Adverse Health/Environmental Impact
- EFK - Evidence of Fish Kill

Reported By **Don Ashley** Title **Maintenance Controller** Telephone Number **(501) 321-6200**

Additional Comments if Needed: