

The following information has been sent.

# CONFIRMATION NUMBER

## e694c1d6-6356-451b-ba78-e6defb6c54be

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

**Date/Time Overflow Range**

\*Date Overflow Began:  
2/3/2023

\*Time:  
10:00 am

Date Overflow Ended:  
2/5/2023

Time:  
08:00 am

**Facility/Permit Information**

\*Facility Name:  
Sheridan Water Works

\*Permit Number:  
AR0034347

**Location Information**

Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, stream, storm sewer, building, or other. Be specific as possible.

Pine Bluff Drive

**Description of Problem (check all items that apply)**

Type of Overflow

Manhole Overflow  Lift Station Overflow  Main Line Overflow  Service Line Overflow  Other:

Cause of Overflow

I & I - Rainfall  Roots  Grease  Debris  Equipment Failure

Construction  Vandalism  Power Failure  Line Failure/Break  Other: ice storm took out powerlines & pulled service off side of pump

Volume of Overflow:  
2000

Impact of SSO Overflow Incident

**Environmental Damage (check all items that apply)**

OEHC - Observed or Evidence of Human Contact  OEEI - Observed or Evidence of Environmental Impact

EFK - Evidence of Fish Kill Manhole  NEAH - No Evidence of Adverse Health/Environmental Impact

Action Taken (check all items that apply)

Short term and long-term action, including clean-up and any plans to remediate I & I.

Machine Rodded  Jet-Vac  Hand Rodded  Used Generator to Power Pumps/Equipment  
 Disinfected and Deodorized  Hydro Cleaned  Spread Lime on Affected Area  Public Notification  Other: Generator to power

Reported By

"I certify" under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Name:  
David Fitzgerald  
Title:  
manager  
Phone:  
8709422722  
Email a Copy of This Report to the Email Address:  
sheridanwater@windstream.net

Additional Comments:

The following information has been sent.

# CONFIRMATION NUMBER

## cc2df154-9a84-48f8-ad80-dfa680185e6e

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

**Date/Time Overflow Range**

\*Date Overflow Began:  
2/3/2023

\*Time:  
10:00 am

Date Overflow Ended:  
2/4/2023

Time:  
09:30 am

**Facility/Permit Information**

\*Facility Name:  
Sheridan Water Works

\*Permit Number:  
AR0034347

**Location Information**

Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, stream, storm sewer, building, or other. Be specific as possible.

Brownwood P.S. South

**Description of Problem (check all items that apply)**

Type of Overflow

Manhole Overflow  Lift Station Overflow  Main Line Overflow  Service Line Overflow  Other:

Cause of Overflow

I & I - Rainfall  Roots  Grease  Debris  Equipment Failure

Construction  Vandalism  Power Failure  Line Failure/Break  Other: ice storm caused trees to break power lines and blocked roads

Volume of Overflow:  
3000

Impact of SSO Overflow Incident

**Environmental Damage (check all items that apply)**

OEHC - Observed or Evidence of Human Contact  OEEI - Observed or Evidence of Environmental Impact

EFK - Evidence of Fish Kill Manhole  NEAH - No Evidence of Adverse Health/Environmental Impact

Action Taken (check all items that apply)

Short term and long-term action, including clean-up and any plans to remediate I & I.

Machine Rodded  Jet-Vac  Hand Rodded  Used Generator to Power Pumps/Equipment  
 Disinfected and Deodorized  Hydro Cleaned  Spread Lime on Affected Area  Public Notification  Other:

Reported By

"I certify" under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Name:

David Fitzgerald

Title:

manager

Phone:

8709422722

Email a Copy of This Report to the Email Address:

sheridanwater@windstream.net

Additional Comments:

The following information has been sent.

## CONFIRMATION NUMBER

**7a9b8be9-37f0-4454-85a0-40925736d62b**

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

### Date/Time Overflow Range

\*Date Overflow Began:

2/3/2023

\*Time:

10:00 am

Date Overflow Ended:

2/4/2023

Time:

09:30 am

### Facility/Permit Information

\*Facility Name:

Sheridan Water Works

\*Permit Number:

AR0034347

### Location Information

Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, stream, storm sewer, building, or other. Be specific as possible.

Brownwood P.S. North

### Description of Problem (check all items that apply)

#### Type of Overflow

Manhole Overflow  Lift Station Overflow  Main Line Overflow  Service Line Overflow  Other:

#### Cause of Overflow

I & I - Rainfall  Roots  Grease  Debris  Equipment Failure

Construction  Vandalism  Power Failure  Line Failure/Break  Other: ice storm caused trees to break power lines and blocked roads

Volume of Overflow:

3000

Impact of SSO Overflow Incident

### Environmental Damage (check all items that apply)

OEHC - Observed or Evidence of Human Contact  OEI - Observed or Evidence of Environmental Impact

EFK - Evidence of Fish Kill Manhole  NEAH - No Evidence of Adverse Health/Environmental Impact

Action Taken (check all items that apply)

Short term and long-term action, including clean-up and any plans to remediate I & I.

Machine Rodded  Jet-Vac  Hand Rodded  Used Generator to Power Pumps/Equipment  
 Disinfected and Deodorized  Hydro Cleaned  Spread Lime on Affected Area  Public Notification  Other:

Reported By

"I certify" under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Name:

David Fitzgerald

Title:

manager

Phone:

870-942-2722

Email a Copy of This Report to the Email Address:

sheridanwater@windstream.net

Additional Comments: