Sanitary Sewer Overflow (SSO) Monthly Report

Facility Name: City of Benton	*	NPDES Permit No.: AR0036498	Monitoring Period (Month/Year): 06	

No Sanitary Sewer Overflows This Monitoring Period

REPORT CODE DESCRIPTIONS									
Cause(s) of SSO		Environmental Impact	Action(s)	Ultimate Discharge Locatio					
C - Construction	D - Debris	EFK - Evidence of Fish Kill	EC - Environmental Cleanup	JV - Jet Vac	GR - Ground				
EF - Equipment Failure	G - Grease	OEHC - Evidence of Human Contact	HC - Hydro Cleaned	SL - Spread Lime	CR - Creek / Stream / River (specify)				
LF - Line Failure	R - Rainfall (I&I)	OEEI - Evidence of Environmental Impact	HR - Hand Rodded	DD - Disinfected and	DI - Ditch				
PF - Power Failure	RO - Roots	NEAH - No Evidence of Adverse Health or	MR - Machine Rodded	Deodorized	DR - Drop Inlet				
V - Vandalism		Environmental Impact	PN - Public Notification	GP - Used Generator to	PA - Paved Area				
		EN - Referred to Engineering	Power Equipment	CB - Contained in Building					

Starting Location (Address, Intersection, or Manhole #)	Start Date of SSO	End Date of SSO	Estim. Volume	Cause(s) of SSO	Environmental Impact	Action(s) Taken	Discharge Location
1208 Holly, Manhole M11-19	06/13/2021	06/13/2021	250	D	NEAH	JV,HC,DD	DI
Hwy 35 and Apache	06/22/2021	06/22/2021	500	EF	NEAH	JV,HC,DD	DI
					Α.		
				9			

Signature of Cognizant or Ranking Official

Date

[&]quot;I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."