

Facility Name: City of Benton

**Semimonthly Sewer Overflow Monthly Report  
Permit Number: AR0036498 Reporting:**

Character of DEQ		Situations of Recent Coal Residues		Monitoring Period	
CO-Communication	D-Delays	NEAA-No Evidence of Adverse Health or Environmental Impact	WO-Work Order	Adverse(?) Taint	Unknown Discharge Location
E-Harmless Pollution	O-Once	ORAC-Only w/o Evidence of Human Contact	EC-Environmental Cleanup	CR-Creek Stream River (please specify)	
W-Clean	L-F/A	ER-Evidence of Harmful	RC-Residues Cleaned	DR-Dust	
R-Rainfall	R-Clean & Cleanse		PR-Hard Rainfall	DR-Drop Holes	
RO-Roots	V-Vandalism		RS-Referred to Blasting	DR-Ground Surface	
			RP-Paved Area		

Licenznummer	Meldekürzel	Start-Datum der EGD	End-Datum der EGD	Reaktivierungszeit Vorhersage (ca. (Fallzeit))	Centra der EGD	Reaktivierungsumfang Impakt	Aktion (1) Tiefdruck by Ablöse von EGD	Umlaufende Differenzierung Lokalitäten
2613 Meadowlawn	K14-57	03/07/2017	03/07/2017	500	R, D	NEAH	Jet-Vac Machine Rotted, AC dead /disint.	DI
2110 Misty Circle	K11-9	03/07/2017	03/07/2017	100	R.G.	NEAH	Jet-Vac, MRot/HC, HC, disinf./dead.	GR
Hwy 5 S. + Rückenstrasse (Rückenlift Str.)	LS	03/10/2017	03/10/2017	100	E (Power outage)	NEAH	HC, disinf./ dead./Reson/Power	DI
804 Park St.	N12-49	03/21/2017	03/21/2017	50	R, G	NEAH	M.Rotted Jet-Vac HC, disinf./dead	GR

*Sister Biff*  
Signature of Cognacq or Franklin Street

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that those persons responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."