

Sanitary Sewer Overflow Monthly Report

Facility Name: City of Benton

Permit Number: AR0036498

Reporting Period (Month/Year): March 2016

No Sanitary Sewer Overflows This Monitoring Period

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Sanitary Sewer Inflow	Sanitary Sewer Overflow	
							Address/Parcel	Ultimate Discharge Location
615 W. Hazel	P 11-07	03/09/2016	03/09/2016	100	R, D	NEAH	WO - Work Order	CR - Creek/Stream/River (please specify)
Brookview Dr	M14-13	03/09/2016	03/09/2016	720	R	NEAH	RC - Bathroom/Cleaner	DR - Drop Inlet
Hoover and Park St.	P12-76	03/09/2016	03/09/2016	300	R, D	NEAH	RC - Hydro Cleaned	DR - Drop Inlet
1217 Ferguson	Lift Station	03/15/2016	03/15/2016	100	E	NEAH	RC - Island Road	CR - Ground Surface
1115 + 1107 Brookview	M14-12	03/25/2016	03/25/2016	1500	G	NEAH	RC - Referenced to Engineering	PA - Paved Area
2603 Eagle Ave	L15-5	03/28/2016	03/28/2016	500	RG	NEAH	RC - Public Notification	CR - Connected in Building

Signature of Cognate or Ranking Official

04/17/2016

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."