

Facility Name: Benton Utilities wastewater Treatment Plant

NPDES Permit No.: AR0036498

Monitoring Period (Month/Year): 1 / 22

REPORT CODE DESCRIPTIONS

REPORT CODE DESCRIPTIONS					
Cause(s) of SSO	Environmental Impact		Action(s) Taken		Ultimate Discharge Location
C - Construction	D - Debris	EFK - Evidence of Fish Kill	EC - Environmental Cleanup	JV - Jet Vac	GR - Ground
EF - Equipment Failure	G - Grease	OEHC - Evidence of Human Contact	HC - Hydro Cleaned	SL - Spread Lime	CR - Creek / Stream / River (specify)
LF - Line Failure	R - Rainfall (L&I)	OEEL - Evidence of Environmental Impact	HR - Hand Rodded	DD - Disinfected and Deodorized	DI - Ditch
PF - Power Failure	RO - Roots	NEAH - No Evidence of Adverse Health or Environmental Impact	MR - Machine Rodded	GP - Used Generator to Power Equipment	DR - Drop Inlet
V - Vandalism			PN - Public Notification		PA - Paved Area
			EN - Referred to Engineering		CB - Contained in Building

[illegible]

Signature of Cognizant or Ranking Official

Date _____

02/08/2022

Mail together with DMR submission **NO LATER THAN THE 25th OF THE MONTH FOLLOWING THE MONITORING PERIOD** to:

ADCO Office of Water Quality ❖ 5301 Northshore Drive ❖ North Little Rock, AR 72118