

Sanitary Sewer Overflow Monthly Report

Facility Name: Mesa Water Utilities Permit Number: AR0036692 Reporting Period (Month/Year): April 2022
☐ No Sanitary Sewer Overflows This Monitoring Period

Cause(s) of SSO		Summary Report Code Descriptions		Action(s) Taken	Ultimate Discharge Location
CO-Construction	D-Debris	SSO Impact	NEAH-No Evidence of Adverse Health or Environmental Impact	WO-Work Order	CR-Creek/Stream/River (please specify)
E-Equipment Failure	G-Grease		OBHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup	DJ-Ditch
HC-Hydro Clean	LF-Line Failure/Break		BFK-Break Evidence of Fish Kill	HC-Hydro Cleaned	DR-Drop Inlet
R-Rainfall	RG-Roots & Grease			HR-Hand Rodded	GR-Ground Surface
RO-Roots	V-Vandalism			EN-Referred to Engineering	PA-Paved Area
				PN-Public Notification	CB-Contained in Building

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action (s) Taken to Address SSO	Ultimate Discharge Location
3074 Polk St	109	4-1-22	4-4-22	5000	ITIR	NEAH	Lined Area	GR
3074 Polk St	109	4-6-22	4-8-22	4500	ITIR	NEAH	Lined Area	GR
Church & Raines St	318	4-24-22	4-25-22	500	ITIR	NEAH	HC	PA
Weiss St	924	4-24-22	4-25-22	1000	ITIR	NEAH	HC	PA
Hornbeck	318	4-24-22	4-25-22	500	ITIR	NEAH	HC	PA
3074 Polk St	109	4-24-22	4-29-22	5000	ITIR	NEAH	Lined Area	GR
4th & Sherman	446	4-24-22	4-25-22	1000	ITIR	NEAH	HC	PA
Sherwood & Reeves	574	4-24-22	4-25-22	1000	ITIR	NEAH	HC	PA
3074 Polk St	109	4-21-22	5-2-2022	10,000	ITIR	NEAH	Lined	GR / CR

Signature of Cognizant of Ranking Official

Date

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

5-2-2022

The following information has been sent.

CONFIRMATION NUMBER

b1d26168-0d6b-47e6-883c-175216bef85

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

Date/Time Overflow Range

*Date Overflow Began:

4/1/2022

*Time:

9:00 am

Date Overflow Ended:

4/4/2022

Time:

8:00 am

Facility/Permit Information

*Facility Name:
Mena Water & Wastewater Utilities

*Permit Number:

AR0036692

Location Information

Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, stream, storm sewer, building, or other. Be specific as possible.

Manhole # is 109 it is located in the rear pasture of this address, and discharged into their field

Description of Problem (check all items that apply)

Type of Overflow

☒ Manhole Overflow ☐ Lift Station Overflow ☐ Main Line Overflow ☐ Service Line Overflow ☐ Other:

Cause of Overflow

☒ I & I - Rainfall ☐ Roots ☐ Grease ☐ Debris ☐ Equipment Failure

☐ Construction ☐ Vandalism ☐ Power Failure ☐ Line Failure/Break ☐ Other:

Volume of Overflow:

5000

Impact of SSO Overflow Incident

SSO Reached Public Land Only (ground)

Environmental Damage (check all items that apply)

☐ OEHC - Observed or Evidence of Human Contact ☐ OEEL - Observed or Evidence of Environmental Impact ☒ EFK - Evidence of Fish Kill Manhole ☒ NEAH - No Evidence of Adverse Health/Environmental Impact

Action Taken (check all items that apply)

Short term and long-term action, including clean-up and any plans to remediate I & I.

☐ Machine Rodded ☐ Jet-Vac ☐ Hand Rodded ☐ Used Generator to Power Pumps/Equipment ☒ Disinfected and Deodorized ☒ Spread Lime on Affected Area ☐ Public Notification ☐ Other:

Reported By

"I certify" under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Name:

Larry Gross

Title:

Maint. Supv.

Phone:

4792161255

Email a Copy of This Report to the Email Address:

thegrossman2@yahoo.com

CONFIRMATION NUMBER

8b0b4515-06fa-496f-a1b4-423e93732932

(NOTE: You will need this number should you ever need to contact ADEC concerning this report)

Date/Time Overflow Range

*Date Overflow Began: 4/6/2022

*Time: 6:00 pm

Date Overflow Ended: 4/8/2022

Time: 8:00 am

Facility/Permit Information

*Facility Name: Mena Water & Wastewater Utilities

*Permit Number: AR0036692

Location Information

Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, stream, storm sewer, building, or other. Be specific as possible.

3074 Polk Rd. 54 Manhole # 109 is overflowing in pasture at the very back of their property

Description of Problem (check all items that apply)

Type of Overflow

☒ Manhole Overflow ☐ Lift Station Overflow ☐ Main Line Overflow ☐ Service Line Overflow ☐ Other:

Cause of Overflow

☒ I & I - Rainfall ☐ Roots ☐ Grease ☐ Debris ☐ Equipment Failure

☐ Construction ☐ Vandalism ☐ Power Failure ☐ Line Failure/Break ☐ Other:

Volume of Overflow:

4500

Impact of SSO Overflow Incident

SSO Affected Private Property (ground)

Environmental Damage (check all items that apply)

☐ OBHC - Observed or Evidence of Human Contact ☐ OBEI - Observed or Evidence of Environmental Impact

☐ EFK - Evidence of Fish Kill Manhole ☒ NEAH - No Evidence of Adverse Health/Environmental Impact

Action Taken (check all items that apply)

Short term and long-term action, including clean-up and any plans to remediate I & I.

☐ Machine Rodded ☐ Jet-Vac ☐ Hand Rodded ☐ Used Generator to Power Pumps/Equipment

☒ Disinfected and Deodorized ☐ Spread Lime on Affected Area ☐ Public Notification ☐ Other:

Reported By

"I certify" under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Name: Larry Gross

Title:

Mainl. Supv:

Phone: 4792161255

CONFIRMATION NUMBER

6514fae5-c2c2-44c1-861c-5e464adb8f03

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

Date/Time Overflow Range

*Date Overflow Began: 4/24/2022

*Time: 1:00 am

Date Overflow Ended: 4/25/2022

Time: 10:30 am

Facility/Permit Information

*Facility Name: Mena Water and Wastewater Utilities

*Permit Number: AR0036692

Location Information

Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, stream, storm sewer, building, or other. Be specific as possible.

This manhole is located at Sherwood And Reeves st. # 574 and discharged into street and ditch

Description of Problem (check all items that apply)

Type of Overflow

☒ Manhole Overflow ☐ Lift Station Overflow ☐ Main Line Overflow ☐ Service Line Overflow ☐ Other:

Cause of Overflow

☒ I & I - Rainfall ☐ Roots ☐ Grease ☐ Debris ☐ Equipment Failure

☐ Construction ☐ Vandalism ☐ Power Failure ☐ Line Failure/Break ☐ Other:

Volume of Overflow:

Impact of SSO Overflow Incident

SSO Reached Public Land Only (ground)

Environmental Damage (check all items that apply)

☐ OEHC - Observed or Evidence of Human Contact ☐ OEI - Observed or Evidence of Environmental Impact

☐ EFK - Evidence of Fish Kill Manhole ☒ NEAH - No Evidence of Adverse Health/Environmental Impact

Action Taken (check all items that apply)

Short term and long-term action, including clean-up and any plans to remediate I & I.

☐ Machine Rodded ☐ Jet-Vac ☐ Hand Rodded ☐ Used Generator to Power Pumps/Equipment

☒ Disinfected and Decolorized ☒ Hydro Cleaned ☒ Spread Lime on Affected Area ☐ Public Notification ☐ Other:

Reported By

"I certify" under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Name: Larry Gross

Title: Maint. Supv.

Phone: 479-216-1255

CONFIRMATION NUMBER

61b3e9aa-a3b0-4bb5-90ab-c8b72b35b665

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

Date/Time Overflow Range

*Date Overflow Began:

4/24/2022

*Time:

1:00 pm

Date Overflow Ended:

4/25/2022

Time:

10:30 am

Facility/Permit Information

*Facility Name:

Mena Water and Wastewater Utilities

*Permit Number:

AR0036692

Location Information

Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, ditch, stream, storm sewer, building, or other. Be specific as possible.

This Manhole is located at Hornbeck Ave. # 318 and it discharged into street an ditch

Description of Problem (check all items that apply)

Type of Overflow

☒ Manhole Overflow ☐ Lift Station Overflow ☐ Main Line Overflow ☐ Service Line Overflow ☐ Other:

Cause of Overflow

☒ I & I - Rainfall ☐ Roots ☐ Grease ☐ Debris ☐ Equipment Failure

☐ Construction ☐ Vandalism ☐ Power Failure ☐ Line Failure/Break ☐ Other:

Volume of Overflow:

500

Impact of SSO Overflow Incident

SSO Reached Public Land Only (ground)

Environmental Damage (check all items that apply)

☐ OEHC - Observed or Evidence of Human Contact ☐ OEEL - Observed or Evidence of Environmental Impact ☐ EFK - Evidence of Fish Kill Manhole ☒ NEAH - No Evidence of Adverse Health/Environmental Impact

Action Taken (check all items that apply)

Short term and long-term action, including clean-up and any plans to remediate I & I.

☐ Machine Rodded ☐ Jet-Vac ☐ Hand Rodded ☐ Used Generator to Power Pumps/Equipment ☒ Disinfected and Deodorized ☒ Hydro Cleaned ☒ Spread Lime on Affected Area ☐ Public Notification ☐ Other:

Reported By

Name:

Larry Gross

Title:

Maint. Supv.

Phone:

479-216-1255

"I certify" under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

CONFIRMATION NUMBER

3206e014-e828-4b81-9d09-b625ac1fc258

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

Date/Time Overflow Range	
*Date Overflow Began:	4/24/2022
*Time:	1:00 pm
Date Overflow Ended:	4/25/2022
Time:	10:30 am

Facility/Permit Information	
*Facility Name:	Mena Water and Wastewater Utilities
*Permit Number:	Ar0036692

Location Information	
Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, stream, storm sewer, building, or other. Be specific as possible.	
This manhole is on Church and Reine St.# 518 and it overflowed into the street and ditch	

Description of Problem (check all items that apply)	
Type of Overflow	
☒ Manhole Overflow ☐ Lift Station Overflow ☐ Main Line Overflow ☐ Service Line Overflow ☐ Other:	
Cause of Overflow	
☒ I & I - Rainfall ☐ Roots ☐ Grease ☐ Debris ☐ Equipment Failure	
☐ Construction ☐ Vandalism ☐ Power Failure ☐ Line Failure/Break ☐ Other:	
Volume of Overflow:	
500	
Impact of SSO Overflow Incident	
SSO Reached Public Land Only (ground)	

Environmental Damage (check all items that apply)	
☐ OEHC - Observed or Evidence of Human Contact ☐ OEEL - Observed or Evidence of Environmental Impact	
☐ EFK - Evidence of Fish Kill Manhole ☒ NEAH - No Evidence of Adverse Health/Environmental Impact	
Action Taken (check all items that apply)	
Short term and long-term action, including clean-up and any plans to remediate I & I.	
☐ Machine Rodded ☐ Jet-Vac ☐ Hand Rodded ☐ Used Generator to Power Pumps/Equipment	
☒ Disinfected and Deodorized ☒ Hydro Cleaned ☐ Spread Lime on Affected Area ☐ Public Notification ☐ Other:	

Reported By	
Name: Larry Gross	
Title:	
Maint. Supv.	
Phone: 4792161255	

"I certify" under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

The following information has been sent.

CONFIRMATION NUMBER

94dbfd8-277a-4c56-9573-227a0918eb11

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

*Date Overflow Began:

4/24/2022

*Time:

1:00 am

Date Overflow Ended:

4/25/2022

Time:

1:00 pm

Facility/Permit Information

*Facility Name:

Mena Water and Wastewater Utilities

*Permit Number:

AR0036692

Location Information

Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, stream, storm sewer, building, or other. Be specific as possible.

This manhole is at Weiss Ave. # 924 and it discharged onto the street and ditch

Description of Problem (check all items that apply)

Type of Overflow

☒ Manhole Overflow ☐ Lift Station Overflow ☐ Main Line Overflow ☐ Service Line Overflow ☐ Other:

Cause of Overflow

☒ I & I - Rainfall ☐ Roots ☐ Grease ☐ Debris ☐ Equipment Failure

☐ Construction ☐ Vandalism ☐ Power Failure ☐ Line Failure/Break ☐ Other:

Volume of Overflow:

Impact of SSO Overflow Incident

SSO Reached Public Land Only (ground)

Environmental Damage (check all items that apply)

☐ OEHC - Observed or Evidence of Human Contact ☐ OEI - Observed or Evidence of Environmental Impact ☒ EFFK - Evidence of Fish Kill Manhole ☒ NEAH - No Evidence of Adverse Health/Environmental Impact

Action Taken (check all items that apply)

Short term and long-term action, including clean-up and any plans to remediate I & I.

☐ Machine Rodded ☐ Jet-Vac ☐ Hand Rodded ☐ Used Generator to Power Pumps/Equipment ☒ Disinfected and Deodorized ☒ Hydro Cleaned ☒ Spread Lime on Affected Area ☐ Public Notification ☐ Other:

Reported By

"I certify" under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Name:

Larry Gross

Title:

Maint. Supv.

Phone:

479-216-1255

Email a Copy of This Report to the Email Address:

thegrossman2@yahoo.com

Additional Comments:

CONFIRMATION NUMBER

83fe9075-c423-4afe-9322-ce15720ef925

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

Date/Time Overflow Range

*Date Overflow Began: 4/24/2022 1:00 am

Date Overflow Ended: 4/25/2022 2:00 pm

Time:

Facility/Permit Information

*Facility Name: Mena Water and Wastewater Utilities

*Permit Number: AR0036692

Location Information

Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, ditch, stream, storm sewer, building, or other. Be specific as possible.

This manhole is located at 4th & Sherwood Ave. # 446 and it discharged onto street and ditch

Description of Problem (check all items that apply)

Type of Overflow

☒ Manhole Overflow ☐ Lift Station Overflow ☐ Main Line Overflow ☐ Service Line Overflow ☐ Other:

Cause of Overflow

☒ I & I - Rainfall ☐ Roots ☐ Grease ☐ Debris ☐ Equipment Failure

☐ Construction ☐ Vandalism ☐ Power Failure ☐ Line Failure/Break ☐ Other:

Volume of Overflow:

Impact of SSO Overflow Incident

SSO Reached Public Land Only (ground)

Environmental Damage (check all items that apply)

☐ OEHC - Observed or Evidence of Human Contact ☐ OEEL - Observed or Evidence of Environmental Impact

☐ EFK - Evidence of Fish Kill Manhole ☒ NEAH - No Evidence of Adverse Health/Environmental Impact

Action Taken (check all items that apply)

Reported By

Short term and long-term action, including clean-up and any plans to remediate I & I.

☐ Machine Rodded ☐ Jet-Vac ☐ Hand Rodded ☐ Used Generator to Power Pumps/Equipment

☒ Disinfected and Deodorized ☒ Hydro Cleaned ☒ Spread Lime on Affected Area ☐ Public Notification ☐ Other:

Name: Larry Gross

Title: Maint. Supv.

Phone: 4792161255

"I certify" under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

The following information has been sent

CONFIRMATION NUMBER

f399f0e0-c2da-4f7d-a36a-e62c543aeb47

(NOTE: You will need this number should you ever need to contact ADEQ concerning this report)

Date/Time Overflow Range

*Date Overflow Began: 4/24/2022

*Time:

1:00 am

Date Overflow Ended: 4/29/2022

Time:

11:00 am

Facility/Permit Information

*Facility Name:

Mena Water and Wastewater Utilities

*Permit Number:

AR0036692

Location Information

Provide address and manhole number if numbered. Include where the overflow went into a yard, ditch, stream, storm sewer, building, or other. Be specific as possible.

This MH is located in back of a pasture at address 3074 Polk Rd. S4 # 109 and discharged onto ground surface

Description of Problem (check all items that apply)

Type of Overflow

☒ Manhole Overflow ☐ Lift Station Overflow ☐ Main Line Overflow ☐ Service Line Overflow ☐ Other:

Cause of Overflow

☒ I & I - Rainfall ☐ Roots ☐ Grease ☐ Debris ☐ Equipment Failure

☐ Construction ☐ Vandalism ☐ Power Failure ☐ Line Failure/Break ☐ Other:

Volume of Overflow:

5000

Impact of SSO Overflow Incident

SSO Reached Public Land Only (ground)

Environmental Damage (check all items that apply)

☐ OEHC - Observed or Evidence of Human Contact ☐ OEEL - Observed or Evidence of Environmental Impact ☒ EFK - Evidence of Fish Kill Manhole ☒ NEAH - No Evidence of Adverse Health/Environmental Impact

Action Taken (check all items that apply)

Short term and long-term action, including clean-up and any plans to remediate I & I.

☐ Machine Rodded ☐ Jet-Vac ☐ Hand Rodded ☐ Used Generator to Power Pumps/Equipment ☒ Disinfected and Deodorized ☒ Hydro Cleaned ☐ Spread Lime on Affected Area ☐ Public Notification ☐ Other:

Reported By

"I certify" under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Name:

Larry Gross

Title:

Maint. Supv.

Phone:

4792161255

Email a Copy of This Report to the Email Address:

thegrossman2@yahoo.com

Additional Comments: