

ility Name: Mesa WWT NPDES Permit No.: AR 0034692 Monitoring Period (Month/Year): 12/2021

☒ No Sanitary Sewer Overflows This Monitoring Period

REPORT CODE DESCRIPTIONS					
Cause(s) of SSO		Environmental Impact	Action(s) Taken		Ultimate Discharge Location
Construction	D - Debris	EFK - Evidence of Fish Kill	EC - Environmental Cleanup	JV - Jet Vac	GR - Ground
- Equipment Failure	G - Grease	OEHC - Evidence of Human Contact	HC - Hydro Cleaned	SL - Spread Lime	CR - Creek / Stream / River (specify)
- Line Failure	R - Rainfall (I&I)	OEEI - Evidence of Environmental Impact	HR - Hand Rodded	DD - Disinfected and Deodorized	DI - Ditch
- Power Failure	RO - Roots	NEAH - No Evidence of Adverse Health or Environmental Impact	MR - Machine Rodded		DR - Drop Inlet
Vandalism			PN - Public Notification	GP - Used Generator to Power Equipment	PA - Paved Area
		EN - Referred to Engineering			CB - Contained in Building

[illegible]

Date \_\_\_\_\_

Mail together with DMR submission **NO LATER THAN THE 25th OF THE MONTH FOLLOWING THE MONITORING PERIOD** to:  
ADEQ Office of Water Quality ♦ 5301 Northshore Drive ♦ North Little Rock, AR 72118