

05/11/2007 MON 9:42 FAX 501 376 3633 599 Garver Engineers Environ

006/007

WALNUT RIDGE CITY WATER WORKS
SANITARY SEWER OVERFLOW FORM

REPORTED BY: Jan Kopp ADDRESS: 216 S.W. 4th St.
CALL TIME: 5:00 AM or PM CALL DATE: 5-11-15
(circle one)

RESPONSE DATA:

CREW LEADER: Jan Kopp
ARRIVAL TIME: 5:00 AM or PM DATE: 5-11-15
COMPLETED TIME: 6:00 AM or PM DATE: 5-11-15
(circle one)

ACTION(S) TAKEN: Hydro-cleaned Environmental Cleanup Public Notice
 Hand Rodded Report to Engineering Work Order

SSO DATA:

DATE OF SSO: 5-11-15 TIME OF SSO: 5:00 AM or PM
(circle one)
LOCATION: Manhole ADDRESS: Intersection of Nazarene Drive + Peachtree Road

CAUSE: Root Debris Equipment Failure
 Grease Line Failure
 Rainfall Hydrocleaning
 Construction Vandalism

FATE: Creek/Stream/River Ditch Drop Inlet
 Ground Surface Paved Area Contained in Building

ACTIVE DISCHARGE: YES NO (Evidence of Discharge)
OBSERVED FLOWRATE: 10 GALLONS PER MINUTE
ESTIMATED DURATION: 60 MINUTES
ESTIMATED VOLUME: 600 GALLONS

IMPACT: No Evidence of Adverse Health or Environmental Impacts
 Observed or Evidence of Human Contact
 Evidence of Fish Kill