

08/11/2007 MON 9:42 FAX 501 376 3633 599 Carver Engineers Environ

006/007

WALNUT RIDGE CITY WATER WORKS
SANITARY SEWER OVERFLOW FORM

REPORTED BY: _____ ADDRESS: _____
CALL TIME: _____ AM or PM (circle one) CALL DATE: _____

RESPONSE DATA:

CREW LEADER: Jon Kopp
ARRIVAL TIME: 1:00 AM or PM (circle one) DATE: 12-22-13
COMPLETED TIME: 1:30 AM or PM (circle one) DATE: 12-22-13

ACTION(S) TAKEN: Hydro-cleaned Environmental Cleanup Public Notice
 Hand Rodded Report to Engineering Work Order

SSO DATA:

DATE OF SSO: 12-22-13 TIME OF SSO: 1:00 AM or PM (circle one)
LOCATION: Manhole ADDRESS: 901 W. Free St

CAUSE: Root Debris Equipment Failure
 Grease Line Failure
 Rainfall Hydrocleaning
 Construction Vandalism

FATE: Creek/Stream/River Ditch Drop Inlet
 Ground Surface Paved Area Contained in Building

ACTIVE DISCHARGE: YES NO (Evidence of Discharge)

OBSERVED FLOWRATE: 5 GALLONS PER MINUTE

ESTIMATED DURATION: 30 MINUTES

ESTIMATED VOLUME: 150 GALLONS

IMPACT: No Evidence of Adverse Health or Environmental Impacts
 Observed or Evidence of Human Contact
 Evidence of Fish Kill

06/11/2007 MON 9:42 FAX 501 376 3633 599 Garver Engineers Environ

006/007

WALNUT RIDGE CITY WATER WORKS SANITARY SEWER OVERFLOW FORM

REPORTED BY: _____ ADDRESS: _____
 CALL TIME: _____ AM or PM CALL DATE: _____
 (circle one)

RESPONSE DATA:

CREW LEADER: Son Kopp
 ARRIVAL TIME: 2:00 AM or PM DATE: 12-22-13
 COMPLETED TIME: 6:00 AM or PM DATE: ~~12-23-13~~ 12-22-13

ACTION(S) TAKEN: _____ Hydro-cleaned _____ Environmental Cleanup _____ Public Notice
 _____ Hand Rodded _____ Report to Engineering X Work Order

SSO DATA:

DATE OF SSO: 12-22-2013 TIME OF SSO: 2:00 AM or PM
manhole LOCATION: 623 Pocahontas RD ADDRESS: _____
 (circle one)

CAUSE: _____ Root _____ Debris _____ Equipment Failure
 _____ Grease _____ Line Failure
X Rainfall _____ Hydrocleaning
 _____ Construction _____ Vandalism

FATE: _____ Creek/Stream/River X Ditch _____ Drop Inlet
 _____ Ground Surface _____ Paved Area _____ Contained in Building

ACTIVE DISCHARGE: X YES _____ NO (Evidence of Discharge)
 OBSERVED FLOWRATE: 3 GALLONS PER MINUTE
 ESTIMATED DURATION: 240 MINUTES
 ESTIMATED VOLUME: 720 GALLONS

IMPACT: X No Evidence of Adverse Health or Environmental Impacts
 _____ Observed or Evidence of Human Contact
 _____ Evidence of Fish Kill