

08/11/2007 MON 9:42 FAX 501 376 3633 599 Carver Engineers Environ

006/007

WALNUT RIDGE CITY WATER WORKS  
SANITARY SEWER OVERFLOW FORM

REPORTED BY: Don Alls ADDRESS: 406 Matt Dr.  
CALL TIME: 4:00 AM or PM CALL DATE: 12-24-13  
(circle one)

RESPONSE DATA:  
CREW LEADER: Jon Kopp  
ARRIVAL TIME: 4:30 AM or PM DATE: 12-24-13  
COMPLETED TIME: 5:00 AM or PM DATE: 12-24-13

ACTION(S) TAKEN:  Hydro-cleaned  Environmental Cleanup  Public Notice  
 Hand Rodded  Report to Engineering  Work Order

SSO DATA:  
DATE OF SSO: 12-24-13 TIME OF SSO: 4:30 AM or PM  
LOCATION: Manhole ADDRESS: 406 Matt Dr.  
(circle one)

CAUSE:  Root  Debris  Equipment Failure  
 Grease  Line Failure  
 Rainfall  Hydrocleaning  
 Construction  Vandalism

FATE:  Creek/Stream/River  Ditch  Drop Inlet  
 Ground Surface  Paved Area  Contained in Building

ACTIVE DISCHARGE:  YES  NO (Evidence of Discharge)  
OBSERVED FLOWRATE: 2 GALLONS PER MINUTE  
ESTIMATED DURATION: 30 MINUTES  
ESTIMATED VOLUME: 60 GALLONS

IMPACT:  No Evidence of Adverse Health or Environmental Impacts  
 Observed or Evidence of Human Contact  
 Evidence of Fish Kill