

WALNUT RIDGE CITY WATER WORKS
SANITARY SEWER OVERFLOW FORM

REPORTED BY: Don Aills ADDRESS: 406 Matt Dr.
CALL TIME: 4:00 AM or PM (circle one) CALL DATE: 12-24-13

RESPONSE DATA:
CREW LEADER: Jon Kopp
ARRIVAL TIME: 4:30 AM or PM DATE: 12-24-13
COMPLETED TIME: 5:00 AM or PM DATE: 12-24-13

ACTION(S) TAKEN: Hydro-cleaned Environmental Cleanup Public Notice
 Hand Rodded Report to Engineering Work Order

SSO DATA:
DATE OF SSO: 12-24-13 TIME OF SSO: 4:30 AM or PM (circle one)
LOCATION: Manhole ADDRESS: 406 Matt Dr.

CAUSE: Root Debris Equipment Failure
 Grease Line Failure
 Rainfall Hydrocleaning
 Construction Vandalism

FATE: Creek/Stream/River Ditch Drop Inlet
 Ground Surface Paved Area Contained in Building

ACTIVE DISCHARGE: YES NO (Evidence of Discharge)
OBSERVED FLOWRATE: 2 GALLONS PER MINUTE
ESTIMATED DURATION: 30 MINUTES
ESTIMATED VOLUME: 60 GALLONS

IMPACT: No Evidence of Adverse Health or Environmental Impacts
 Observed or Evidence of Human Contact
 Evidence of Fish Kill