Sanitary Sewer Overflow Monthly Report

Facility Name: City of Walnut Ridge Permit Number: APOO46566 Reporting Period (Month/Year): November 2012 ☐ No Sanitary Sewer Overflows This Monitoring Period Summary Report Code Descriptions Cause(s) of SSO SSO Impact Action(s) Taken Ultimate Discharge Location CO-Construction D-Debris NEAH-No Evidence of Adverse Health or Environmental WO-Work Order CR-Creek/Stream/River (please spec Impact E-Equipment Failure G-Grease OEHC-Observed or Evidence of Human Contact EC-Environmental Cleanup HC-Hydro Clean LF-Line DI-Ditch EFK-Evidence of Fish Kill HC-Hydro Cleaned Failure/Break DR-Drop Inlet R-Rainfall RG-Roots & Grease HR-Hand Rodded RO-Roois V-Vandalism GR-Ground Surface EN-Referred to Engineering PA-Paved Area PN-Public Notification CB-Contained in Building-Location Manhole# Start Date of End Date of Estimated Volume Cause of SSO Environmental Action (s) Taken Ultimate Discharg SSO SSO (in gallanc)

820 HWY 67B	N-A	11-12-12	11-12-12	(in gallons)	LF	NEA H	to Address SSO	Location CR (Village Creek
		1						, 69
					-			
		`						
	!					·		
		·				-		,
		1					,	
			/					·
₹,		\sim	1/ -		!		l .	

Signature of Cognizant or Ranking Official

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information."

)

City Water Works
216 S.W. 4" St.
216 S.W. All St. 72476





ADEQ NPDES Enforcement 5301 Northshore Drive North Little Rock, AR 72118