

June 19, 2009

Mr. Doyan Huckabee P.O. Box 136 Cave City, AR 72521

**RE:** Complaint Investigation

Dear Mr. Huckabee:

On June 5, 2009, I performed a complaint investigation alleging dead chickens, sewage and chicken litter flowing into a creek near your property. The investigation was performed in accordance with the provisions of the Federal Clean Water Act, the Arkansas Water and Air Pollution Control Act, and the regulations promulgated thereunder. At the time of the inspection, I observed the following violation:

I observed a pool of liquid waste with a strong odor approx. 20-25 feet long located at the south side of your chicken house that was slowly flowing southwest off your property. I also observed where waste had washed against the north side of a composting shed on your property that had flowed around the shed to the southwest toward a wet weather branch located approximately 30-40 feet southwest. The shed was open on both ends and had waste piled up on the floor of the shed on the west end that could wash out of the shed toward the wet weather branch. This is a violation of the Arkansas Water and Air Pollution Control Act (8-4-217) a, 2.

I also observed a straight pipe coming from a mobile home on your property with the waste flowing onto the ground approximately 60-65 feet east of the mobile home. The waste as you stated was still on your property. Since you are in the process of working the Arkansas Department of Health to install a state approved septic tank system, there is no need to address this item to the Arkansas Department of Environmental Quality.

Concerning the other items mentioned you need to immediately take whatever measures necessary to prevent pollution to waters of the state.

The above items require your immediate attention. Please submit a written response to these findings to Cindy Garner, Technical Assistance Manager, Water Division Enforcement Branch of this Department at the following address:

Water Division Enforcement Branch Arkansas Department of Environmental Quality 5301 Northshore Drive North Little Rock, AR 72118-5317 Doyan Huckabee June 19, 2009 Page 2

This response should contain detailed documentation describing the course of action taken to correct each item noted. This corrective action should be completed as soon as possible, and the written response with all documentation (i.e. pictures) is due by July 2, 2009.

For additional information you may contact the Enforcement Branch by telephone at 501-682-0639 or by fax at 501-682-0910.

If I can be of any assistance, please contact me at 870-793-5819.

Sincerely,

sile Knowly

Mike Kennedy District 11 Field Inspector Water Division

cc: Water Division Enforcement Branch Water Division Permits Branch

WAT	ER DIVISION C	COMPLAINT REPORT				
GPS LOCATION:		AFIN: None				
		PERMIT#: None				
DATE RECEIVED: April 29, 2009		COUNTY: Izard				
COMPLAINANT NAME: Teresa Duncan		COMPLAINT AGAINST: Doyan Huckabee	1			
ADDRESS: P.O. Box 120		ADDRESS: P.O. Box 136				
Sidney, AR 72577		Cave City, AR. 72521				
PHONE: 281-615-8362		PHONE: 870-528-4054				
	CKING & REFER	RAL INFORMATION				
PERSON RECEIVING REPORT: Lacye Reagan	DATE: <b>4-28-09</b>	SUPERVISOR REFERRAL:	DATE:			
INSPECTOR REFERRAL:	DATE:	MEDIA SUPERVISOR REFERRAL:	DATE:			
Mike Kennedy	4-29-09					
PHONE REFERRAL CONTACT:	DATE:	RECEIVING INSPECTOR:	DATE:			
COMPLAINT RECEIVED BY: PHONE	LETTER UV	ERBAL DINTERNET DEMAIL				
	DETAILED D	ESCRIPTION				
The complaint alleged chicken litter and	sewage had be	en running into a wet weather creek on h	er property.			
	LOC	ATION				
Drive on Highway #58 east approx. 3 mil approx. 2.5 miles to the Doyan Huckabe		, AR. to County Road #72. Turn on this ro	ad and drive			
PREVIOUS COMPLAINT: DYES DNO						
DISCHARGE TO STREAM: DYES ZNO	NAME OF ST	REAM:				
	INVEST	GATION				
INSPECTOR:		DATE:				
Mike Kennedy		June 5, 2009				
ACTION TAKEN:		PHOTOS TAKEN: 🗹 YI	ES □NO			
The Water Inspector met with Mr. Doyan Huckabee, Owner, of the chicken farm. The Inspector observed a pool of liquid waste washed from chicken litter stored at the farm on the south side of the 2 <sup>nd</sup> of 2 chicken houses located at the farm. The pool was approx. 20-25 feet long and approx. 6-9 inches deep. The pool was slowly flowing southwest from Mr. Huckabee's property onto neighboring property. There was also a flowing wet weather branch located approx. 90-100 feet southwest of Mr. Huckabee's chicken house. Mr. Huckabee stated that chicken litter from the chicken houses had been stored where the pool is located and that the Arkansas Poultry and Livestock Commission had recently required him to remove the litter and build a stacking shed at his facility. Mr. Huckabee was informed that the waste flowing from his property was a violation of the Arkansas Water and Air Pollution Control Act (8-4-217) a, 2. He was also informed that he needed to drain the liquid waste, clean up the area, put out Lime for dor control and plant vegetation in this area to prevent pollution to waters of the state. There was also a composting shed located approx. 60-65 feet west of the chicken house that was open on both ends and waste was piled up near the open west end of the shed. The shed is located approx. 30-40 feet east of the same wet weather branch mentioned previously. Liquid waste had also washed up against the composting shed on the north side. Mr. Huckabee was informed that this area needed to be cleaned up and Lime put out for odor control. Also the composting shed needed to be enclosed on the west end to prevent pollution to waters of the state. There was also a mobile home located on the farm that had a straight pipe coming from the mobile home approx. 60-65 feet long flowing east onto Mr. Huckabee's pasture. Jeff Jackson of the Arkansas Department of Health was in the process of working with Mr. Huckabee to install a state approved septic tank						
east of the same wet weather branch me composting shed on the north side. Mr. Lime put out for odor control. Also the o pollution to waters of the state. There was also a mobile home located approx. 60-65 feet long flowing east onto Health was in the process of working with	cated approx. 60 he open west e ntioned previou Huckabee was composting she I on the farm th o Mr. Huckabee	nd of the shed. The shed is located appro usly. Liquid waste had also washed up ag informed that this area needed to be clea ed needed to be enclosed on the west end at had a straight pipe coming from the mo 's pasture. Jeff Jackson of the Arkansas	ox. 30-40 feet jainst the ned up and to prevent obile home			
east of the same wet weather branch me composting shed on the north side. Mr. Lime put out for odor control. Also the o pollution to waters of the state. There was also a mobile home located approx. 60-65 feet long flowing east onto Health was in the process of working with FURTHER ACTION:	cated approx. 60 he open west e ntioned previou Huckabee was composting she of on the farm th Mr. Huckabee	nd of the shed. The shed is located appro usly. Liquid waste had also washed up ag informed that this area needed to be clea ed needed to be enclosed on the west end at had a straight pipe coming from the mo 's pasture. Jeff Jackson of the Arkansas	ox. 30-40 feet gainst the ned up and to prevent obile home Department of			

SIGNATURE:		
The state of the s	Mike Kennedy	DATE: June 19, 2009

			Wate	r Division NPDES Photo	ographic Ev	vidence Sheet		
Location:	Ap	prox. 3	miles eas	st of Sidney, AR. off High	way #58 on	County Rd. #7	2 (Izard C	ounty)
Photograph	ner:	Mike I	Kennedy		Witness:	Doyan Huck	abee	
Photo #	1	Of	10		Date:	6-5-09	Time:	1058
Description	:	This is south s	a view sl side of the	nowing liquid pooled up v 2 <sup>nd</sup> of 2 chicken houses 1	here chicke ocated on th	n litter had bee e farm. Strong	n piled up. odor and g	This is on the green in color.
Photograph	er.	Mike I	Kennedy		Witness:	Doyan Huck	abee	
Photo #	2	Of	10		Date:	6-5-09	Time:	1058
Description		This vi		s the liquid slowly flowing				
		There	was also a	a flowing wet weather bra				

			Wate	er Division	NPDES Pl	notographic Ev	idence Sheet	t			
Location:	App	prox. 3	miles ea	st of Sidney	y, AR. off H	lighway #58 on	County Rd. #	#72 (Izard C	ounty)		
Photographer	:	Mike K	Kennedy			Witness:	ess: Doyan Huckabee				
Photo #	3	Of	10			Date:	6-5-09	Time:	1057		
Description:		Anothe propert		f picture #2	2. The liquid	d appeared to pr	obably have	gotten onto n	eighboring		
Photographer Photo # Description:	4	<b>Of</b> This is	Kennedy 10 looking	in the oppo	site directio	Witness:   Date:   n of the liquid particular	Doyan Huc 6-5-09 bool looking e	Time:	1058 n litter had been		
		piled u	p here ac		Mr. Huckat	ee.					

				er Division NF					
Location:				st of Sidney, A	.R. off High				County)
Photograph			Kennedy			Witness:	Doyan H	uckabee	
Photo #	5	Of	10			Date:	6-5-09	Time:	1058
Description				f picture #4 at the of the of			100se lookir	g north. Chi	cken litter had
Photograph									
	er:	Mike F	Kennedy			Witness:	Doyan H	uckabee	
Photo #	<b>er:</b> 6	Mike k	Kennedy 10			Witness: Date:	Doyan H 6-5-09		1115
	6	Of Liquid feet we	10 from chi est of the	cken litter and chicken house pprox. 30-40 f	. It had flow	Date: had washe wed around	6-5-09 d down to th	<b>Time:</b> iis compostin	g shed approx. 60

			Wate	r Division NPDES Pho	tographic Ev	vidence Shee	t	
Location:	Aŗ	prox. 3	miles eas	st of Sidney, AR. off Hig	hway #58 on	County Rd.	#72 (Izard C	County)
Photographe	r:	Mike I	Kennedy		Witness:	Doyan Hu	ckabee	
Photo #	7	Of	10		Date:	6-5-09	Time:	1114
Description:				est end of the compostin				
Description.	waste could wash from the shed to the wet weather branch approx. 30-40 feet west.							
Photographe	r:	Mike H	Kennedy		Witness:	Doyan Hu	ckabee	
Photo #	8	Of	10		Date:	6-5-09	Time:	1114
Description:				the west end of the com nch in the trees approx.			ere waste cou	ld wash into the

				Wate	er Division NPDES Phot	ographic Ev	vidence Sheet		
Location:					st of Sidney, AR. off Higl	-	-		ounty)
Photograp	· · · ·	_		Kennedy		Witness:	Doyan Huc	-	
Photo #		9	Of	10		Date:	6-5-09	Time:	1107
Descriptior	ı:				ast side of the mobile hom home off the hillside to t		picture #5. Th	ere is a sewe	er pipe leading
Photograp	ner:		Mike F	Kennedy		Witness:	Doyan Huc	kabee	
Photo #	]	10	Of	10		Date:	6-5-09	Time:	1107
Descriptior	n:		Mr. Hu	ickabee's	nd of the open pipe locate property. Arkansas Dep of requiring Mr. Huckab	artment of H	lealth is alread	y aware of the	he open pipe and



August 26, 2009

Doyan Huckabee P.O. Box 136 Cave City, AR 72521

## RE: Complaint Investigation, AFIN: 33-00000 No Response Received

Dear Mr. Huckabee:

On **June 19, 2009**, we sent a letter (copy enclosed) with the findings from a complaint investigation of your *property*. A reply was requested by **July 2, 2009**, but as of today we have not received a response.

If you have already replied, please send a copy of your letter so we may update our files. If you have not answered our letter, please do so by **September 16, 2009**.

<u>A continued lack of cooperation in this matter could subject you to formal enforcement</u> action. Such action could include but would not be limited to monetary civil penalties.

ADEQ will consider the inspection and your response as required by Pollution Control and Ecology Commission Regulation No. 7, Civil Penalties. This regulation requires ADEQ to consider the past compliance history of your company and how expeditiously the violations were addressed, in determining any civil penalty that may be necessary

Thank you for your attention to this matter. If you have any questions, please feel free to contact me at (501)682-0667 or e-mail: blaket@adeq.state.ar.us.

Sincerely,

Vacey I de

Tracey Blake Enforcement Analyst Water Division

Enclosure

### September 10, 2009

Tracey Blake Enforcement Analyst/Water Division Arkansas Department of Environmental Quality 5301 Northshore Drive North Little Rock, AR 72118-5317

RE: Complaint Investigation, AFIN: 33-00000

Dear Tracy:

Please be advised that all of the required actions requested by your department have been addressed and performed as specified.

- 1) We have installed a septic tank for the mobile home on our property.
- 2) We have repaired the drainage problem from the chicken houses that was flowing off of our property. Our composting shed has had a wall put on to prevent any waste flowing from the shed.
- 3) We have planted grass behind chicken house #2 to stop any drainage problems.
- 4) We have spread gravel along the sides of the composter.
- 5) We have cleaned up all litter outside the buildings.

Please contact me if you need any further information.

Sincerel

Doyan Huckabee



August 26, 2009

Doyan Huckabee P.O. Box 136 Cave City, AR 72521

## RE: Complaint Investigation, AFIN: 33-00000 No Response Received

Dear Mr. Huckabee:

On **June 19, 2009**, we sent a letter (copy enclosed) with the findings from a complaint investigation of your *property*. A reply was requested by **July 2, 2009**, but as of today we have not received a response.

If you have already replied, please send a copy of your letter so we may update our files. If you have not answered our letter, please do so by **September 16, 2009**.

A continued lack of cooperation in this matter could subject you to formal enforcement action. Such action could include but would not be limited to monetary civil penalties.

ADEQ will consider the inspection and your response as required by Pollution Control and Ecology Commission Regulation No. 7, Civil Penalties. This regulation requires ADEQ to consider the past compliance history of your company and how expeditiously the violations were addressed, in determining any civil penalty that may be necessary

Thank you for your attention to this matter. If you have any questions, please feel free to contact me at (501)682-0667 or e-mail: blaket@adeq.state.ar.us.

Sincerely,

any Flate

Tracey Blake Enforcement Analyst Water Division

Enclosure

SPS

ARKANSAS DEPARTMENT OF ENVIRONMENTAL QUALITY

5301 NORTHSHORE DRIVE / NORTH LITTLE ROCK / ARKANSAS 72118-5317 / TELEPHONE 501-682-0744 / FAX 501-682-0880



June 19, 2009

Mr. Doyan Huckabee P.O. Box 136 Cave City, AR 72521

**RE:** Complaint Investigation

Dear Mr. Huckabee:

On June 5, 2009, I performed a complaint investigation alleging dead chickens, sewage and chicken litter flowing into a creek near your property. The investigation was performed in accordance with the provisions of the Federal Clean Water Act, the Arkansas Water and Air Pollution Control Act, and the regulations promulgated thereunder. At the time of the inspection, I observed the following violation:

I observed a pool of liquid waste with a strong odor approx. 20-25 feet long located at the south side of your chicken house that was slowly flowing southwest off your property. I also observed where waste had washed against the north side of a composting shed on your property that had flowed around the shed to the southwest toward a wet weather branch located approximately 30-40 feet southwest. The shed was open on both ends and had waste piled up on the floor of the shed on the west end that could wash out of the shed toward the wet weather branch. This is a violation of the Arkansas Water and Air Pollution Control Act (8-4-217) a, 2.

I also observed a straight pipe coming from a mobile home on your property with the waste flowing onto the ground approximately 60-65 feet east of the mobile home. The waste as you stated was still on your property. Since you are in the process of working the Arkansas Department of Health to install a state approved septic tank system, there is no need to address this item to the Arkansas Department of Environmental Quality.

Concerning the other items mentioned you need to immediately take whatever measures necessary to prevent pollution to waters of the state.

The above items require your immediate attention. Please submit a written response to these findings to Cindy Garner, Technical Assistance Manager, Water Division Enforcement Branch of this Department at the following address:

Water Division Enforcement Branch Arkansas Department of Environmental Quality 5301 Northshore Drive North Little Rock, AR 72118-5317

#### ARKANSAS DEPARTMENT OF ENVIRONMENTAL QUALITY

5301 NORTHSHORE DRIVE / NORTH LITTLE ROCK / ARKANSAS 72118-5317 / TELEPHONE 501-682-0744 / FAX 501-682-0880 www.adeq.state.ar.us White River Insurance Agency of Sharp County 116 N. Street, Suite A-B Cave City, AR 72521





# <u>FIRST CLASS MAIL</u>

Iracey Blake Enforcement Analyst - Water Division Arkansas Department of Environmental Quality 5301 Morth Shore Drive Morth Gittle Rock, AR 72110-5317

in the second se



October 9, 2009

Doyan Huckabee P.O. Box 136 Cave City, AR 72521

RE: Complaint Investigation

Dear Mr. Huckabee:

The Department has received your response dated September 10, 2009 to the June 5, 2009 complaint investigation by District Field Inspector Mike Kennedy. The complaint alleged that dead chickens, sewage and chicken litter was flowing into a creek near your property.

Your letter appears to adequately address the discrepancies identified during the investigation. However, the Department requires that you submit photos of these corrective actions. These photos must be submitted to the Department no later than October 19, 2009.

The Department assumes the corrective action taken will be maintained to ensure consistent compliance. Acceptance of this response by the Department does not preclude any future enforcement action deemed necessary at this site or any other site.

The Department will keep the inspection and response on file. If future violations occur that require enforcement action, the Department will consider the inspection and response as required by the Pollution Control and Ecology Commission Regulation No. 7, Civil Penalties. This regulation requires the Department to consider your past history and how expeditiously the violations were addressed in determining any civil penalty that may be necessary for any future violations.

If we need further information concerning this matter, we will contact you. Thank you for your attention to this matter. Should you have any questions, feel free to contact me at 501-682-0635 or you may e-mail me at anderson@adeq.state.ar.us.

Sincerely,

Alan Anderson

Alan Anderson Enforcement Analyst Water Division Enforcement Branch

From:	Foster, Lisa
То:	Stracener, Connie;
Subject:	FW: doyan huckabee
Date:	Monday, October 19, 2009 14:13:54
Attachments:	Doyan Huckabee 003.jpg
	Doyan Huckabee 004.jpg
	Doyan Huckabee 005.jpg
	Doyan Huckabee 006.jpg
	Doyan Huckabee 007.jpg

-----Original Message----- **From:** Allen-Daniel, Leslie **Sent:** Monday, October 19, 2009 10:13 AM **To:** Foster, Lisa **Subject:** FW: doyan huckabee

Would you please put the email and the attachments in Zylab under the Water Division?

Thanks,

*Leslie Allen-Daniel* Secretary II Arkansas Department of Environmental Quality NPDES Enforcement Division 501-682-0639 allen-daniel@adeq.state.ar.us

-----Original Message----- **From:** Garner, Cindy **Sent:** Monday, October 19, 2009 9:01 AM **To:** Allen-Daniel, Leslie **Subject:** FW: doyan huckabee

-----Original Message----- **From:** Anderson, Alan **Sent:** Monday, October 19, 2009 8:14 AM **To:** Garner, Cindy

## Subject: FW: doyan huckabee

Cindy:

Here is the response from Mr. Huckabee. It is complaint #009069, The photos are attached.

-----Original Message----- **From:** dhuckabee@wria.com [mailto:dhuckabee@wria.com] **Sent:** Friday, October 16, 2009 3:19 PM **To:** Anderson, Alan **Subject:** doyan huckabee

Mr. Anderson, I am sending the pictures and just a note that we put a new septic system in, built a new compost shed (dead chickens) and planted grass where we use to stock pile the litter. we have dozed a place where we are going to build a stacking shed for the litter. just for your info, Townsends (poultry co.) will not let us clean out but 1 time a year now, so they wont be much litter to be moved. please call me @870-283-5300 or 870-710-4054 if you need anything futher. thanks Doyan Huckabee









