



ARKANSAS
Department of Environmental Quality

November 14, 2013

The Honorable Jimmy Alexander, Mayor
City of Lewisville
330 west 1st Street
Lewisville, AR 71845

RE: Complaint Investigation (Lafayette Co)
AFIN: 37-00032 **NPDES Permit No.: AR0035696**

Dear Mayor Alexander:

On October 28, 2013, I performed a reconnaissance inspection in response to a complaint of the wastewater treatment facility and in accordance with the provisions of the Federal Clean Water Act, the Arkansas Water and Air Pollution Control Act, and the regulations promulgated thereunder. The complaint alleged you had a manhole overflowing on private property at 425 North Maple and had not taken corrective actions. This inspection revealed that you were in compliance with the terms of your permit.

If I can be of any assistance, please contact me at 870-777-7585 ext. 2 or smithron@adeq.state.ar.us.

Sincerely,

A handwritten signature in black ink that reads "Red Smith".

Red Smith
District 10 Field Inspector
Water Division



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
Washington, D.C. 20460

Form Approved
OMB No. 2040-0003

NPDES Compliance Inspection Report

Section A: National Data System Coding

Transaction Code	NPDES	Yr/Mo/Day	Inspec. Type	Inspector	Fac. Type
1 [N] 2 [5] 3 [A] [R] [0] [0] [3] [5] [6] [9] [6]	11 [1] 12 [3] 13 [1] 14 [0] 15 [2] 16 [8]	17 [V]	18 [S]	19 [1]	
Remarks					
Inspection Work Days	Facility Evaluation Rating	BI	QA	Reserved	
67 [] [] [] 69	70 [N]	71 [N]	72 [N]	73 [] [] []	74 [] [] [] [] [] [] 80

Section B: Facility Data

Name and Location of Facility Inspected (*For industrial users discharging to POTW, also include POTW name and NPDES permit number*)

City of Lewisville POTW

Located downtown Lewisville at the Public Works office on Hwy 82 West

Entry Time/Date
1000 / 10-28-2013

Permit Effective Date
2-1-2009

Exit Time/Date
1130 / 10-28-2013

Permit Expiration Date
1-31-2014

Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s)
Steven Nutt / Waste Water Superintendent / 870-921-5279

Other Facility Data

Minor municipal

Name, Address of Responsible Official/Title/Phone and Fax Number
Jimmy Alexander / Mayor / 870-921-5279
330 West 1st Street
Lewisville, AR 71845

Contacted
Yes ☐ No ☒

PDS# 074670

Section C: Areas Evaluated During Inspection

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

N	Permit	N	Flow Measurement	N	Operations & Maintenance	N	Sampling
N	Records/Reports	N	Self-Monitoring Program	N	Sludge Handling/Disposal	N	Pollution Prevention
N	Facility Site Review	N	Compliance Schedules	N	Pretreatment	N	Multimedia
N	Effluent/Receiving Waters	N	Laboratory	N	Storm Water	S	Other: SSO'S

Section D: Summary of Findings/Comments (Attach additional sheets if necessary)

No violations found during the inspection/investigation.

Permittee had responded in a timely manner and was in the process of disinfecting area and reporting the SSO to ADEQ.

Name(s) and Signature(s) of Inspector(s)

Red Smith

Agency/Office/Telephone/Fax
AR Dept. of Environmental Quality-District 10
870-777-7585 ext. 2-smithron@adeq.state.ar.us

Date

October 29, 2013

Signature of Reviewer

Kerri McCabe

Agency/Office/Phone and Fax Numbers
ADEQ / NLR / 501-682-0642

Date

November 13, 2013

McCabe, Kerri

From: System <donotreply@adeq.state.ar.us>
Sent: Thursday, November 14, 2013 8:12 AM
To: McCabe, Kerri
Subject: Screen Shot of AR0035696 - Date Received: 10/28/2013

Screen Shot:

ID: 70ef5fbf-f67f-450c-b682-a8f26738178a

Facility

NPID: AR0035696

LEWISVILLE, CITY OF

AFIN: 37-00032

Facility Addr: WASTEWATER TREATMENT PLANT, 330 W. FIRST STREET, LEWISVILLE,AR

SSO

Date Received: 10/28/2013

Volume: 500 gallons

Date Started: 10/27/2013

Start Time: 08:00 pm

Stream: SSO Affected Private Property (ground)

Date Stopped: 10/28/2013

End Time: 09:00 am

Receiving Waters: STEEL CK,BODCAU BU

Location: 417 N. Maple Street - overflow went in ditch

Overflow Type

- ☒ Manhole Overflow ☐ Service Line Overflow ☐ Other
☐ Lift Station Overflow ☐ Main Line Overflow

Cause

- ☐ I & I - Rainfall ☐ Construction ☒ Debris ☐ Other
☐ Equipment Failure ☐ Power Failure ☐ Roots
☐ Line Failure Break ☐ Vandalism ☒ Grease

Measures Taken

- ☐ Machine Rodded ☒ Hydro Cleaned ☐ Disinfected and Deodorized
☐ Jet-Vac ☐ Spread Lime on Affected Area ☐ Public Notification
☐ Hand Rodded ☒ Used Generator to Power Equipment ☐ Other

Environmental Damage

- ☐ OEHC - Observed or Evidence of Human Contact ☒ NEAH - No Evidence of Adverse Health Environmental Impact
☐ OEEI - Observed or Evidence of Environmental Impact ☐ EFK - Evidence of Fish Kill