



ARKANSAS
Department of Environmental Quality

September 19, 2011

Gary Savage
Faith Energy, LLC
7330 Fern Ave. # 403
Shreveport, LA 71105

RE: AFIN: 50-00062 Permit Tracking No.: 0323-WG-SW-1
S. W. Willisville SWD System

Dear Mr. Savage:

The Department has received your response to the August 10, 2011 inspection of your facility by our District Field Inspector, Connery Salter. Your response has been deemed deficient for the following reason:

The Department requires that you send photo documentation of the items addressed in the September 9, 2011 response letter.

A copy of the inspection report and the inadequate response is included with this letter for your review. Please submit an adequate response to the Water Enforcement Branch by **October 3, 2011**. Failure to adequately respond by this date will be considered in determining the enforcement action, if required, for this construction site.

Thank you for your attention to this matter. Should you have any questions, feel free to contact me at 501-682-0667 or you may e-mail me at carlsonm@adeq.state.ar.us.

Sincerely,

A handwritten signature in black ink, appearing to read "Michelle Carlson", followed by a stylized flourish.

Michelle Carlson
Enforcement Analyst
Water Division Enforcement Section