Analysis Report

2425 New Holland Pike, Lancaster, PA 17601 • 717-656-2300 • Fax: 717-656-2681 • www.LancasterLabs.com

ANALYTICAL RESULTS

Prepared by: Prepared for:

Eurofins Lancaster Laboratories Environmental 2425 New Holland Pike Lancaster, PA 17601 ExxonMobil PO Box 4592 Houston TX 77210-4592

February 26, 2015

Project: Mayflower, AR Pipeline Incident

Submittal Date: 02/21/2015 Group Number: 1540252 SDG: PEO55 PO Number: 4410272923 Release Number: SIXSMITH State of Sample Origin: AR

Client Sample Description	Lancaster Labs (LL) #
WS-007(0.5-1.0)021915 Grab Surface Water	7780788
WS-007(0.5-1.0)021915 MS Grab Surface Water	7780789
WS-007(0.5-1.0)021915 MSD Grab Surface Water	7780790
WS-009(Surface)021915 Grab Surface Water	7780791
WS-001(0.5-1.0)021915 Grab Surface Water	7780792
WS-021(0.5-1.0)021915 Grab Surface Water	7780793
WS-004(0.5-1.0)021915 Grab Surface Water	7780794
DUP-WS-140-021915 Grab Surface Water	7780795

The specific methodologies used in obtaining the enclosed analytical results are indicated on the Laboratory Sample Analysis Record.

Regulatory agencies do not accredit laboratories for all methods, analytes, and matrices. Our scopes of accreditation can be viewed at http://www.eurofinsus.com/environment-testing/laboratories/eurofins-lancaster-laboratories-environmental/resources/certifications/.

ELECTRONIC	ARCADIS	Attn: Stephen Barrick
COPY TO ELECTRONIC	ARCADIS	Attn: Lyndi Mott
COPY TO	ARCADIS	Attii. Lyildi Wiott
ELECTRONIC	ExxonMobil	Attn: Michael J. Firth
COPY TO		
ELECTRONIC	ARCADIS	Attn: Emily Leamer
COPY TO		
ELECTRONIC	ARCADIS	Attn: Rhiannon Parmelee
COPY TO		
ELECTRONIC	ExxonMobil	Attn: Michael L Sixsmith

Analysis Report

2425 New Holland Pike, Lancaster, PA 17601 • 717-656-2300 • Fax: 717-656-2681 • www.LancasterLabs.com

COPY TO

ELECTRONIC ExxonMobil Attn: Julie Foster

COPY TO

ELECTRONIC ARCADIS Attn: Sonal Patil

COPY TO

ELECTRONIC ARCADIS Attn: Kim Abbott

COPY TO

Respectfully Submitted,

Katherine A. Klinefelter Principal Specialist

Katherine a. Klinefelter

(717) 556-7256



Project Name: Mayflower, AR Pipeline Incident LL Group #: 1540252

General Comments:

See the Laboratory Sample Analysis Record section of the Analysis Report for the method references.

All QC met criteria unless otherwise noted in an Analysis Specific Comment below. Refer to the QC Summary for specific values and acceptance criteria.

Project specific QC samples are included in this data set

Matrix QC may not be reported if site-specific QC samples were not submitted. In these situations, to demonstrate precision and accuracy at a batch level, a LCS/LCSD was performed, unless otherwise specified in the method.

Surrogate recoveries (if applicable) which are outside of the QC window are confirmed unless attributed to a dilution or otherwise noted in an Analysis Specific Comment below.

The samples were received at the appropriate temperature and in accordance with the chain of custody unless otherwise noted.

Analysis Specific Comments:

No additional comments are necessary.



Analysis Report

2425 New Holland Pike, Lancaster, PA 17601 • 717-656-2300 • Fax: 717-656-2681 • www.LancasterLabs.com

Sample Description: WS-007(0.5-1.0)021915 Grab Surface Water

S20135565 Mayflower, AR

Pipeline Incident

LL Sample # WW 7780788

LL Group # 1540252 Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 02/19/2015 14:50 by ZP ExxonMobil PO Box 4592

Houston TX 77210-4592

Submitted: 02/21/2015 10:00 Reported: 02/26/2015 08:40

7051- SDG#: PEO55-01BKG

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Semivolatiles SW-846	8270C SIM	ug/l	ug/l	ug/l	
08357	Acenaphthene	83-32-9	N.D.	0.010	0.051	1
08357	Acenaphthylene	208-96-8	N.D.	0.010	0.051	1
08357	Anthracene	120-12-7	N.D.	0.010	0.051	1
08357	Benzo(a) anthracene	56-55-3	N.D.	0.010	0.051	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.010	0.051	1
08357	Benzo(b) fluoranthene	205-99-2	N.D.	0.010	0.051	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.010	0.051	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.010	0.051	1
08357	Chrysene	218-01-9	N.D.	0.010	0.051	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.010	0.051	1
08357	Fluoranthene	206-44-0	0.016 J	0.010	0.051	1
08357	Fluorene	86-73-7	N.D.	0.010	0.051	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.010	0.051	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.010	0.051	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.010	0.051	1
08357	Naphthalene	91-20-3	N.D.	0.030	0.061	1
08357	Phenanthrene	85-01-8	N.D.	0.030	0.061	1
08357	Pyrene	129-00-0	0.011 J	0.010	0.051	1

General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	15054WAB026	02/24/2015 19:1	B Holly Berry	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	15054WAB026	02/23/2015 20:3	Nicholas W Shroyer	1



Analysis Report

2425 New Holland Pike, Lancaster, PA 17601 • 717-656-2300 • Fax: 717-656-2681 • www.LancasterLabs.com

Sample Description: WS-007(0.5-1.0)021915 MS Grab Surface Water

LL Sample # WW 7780789 S20135565 Mayflower, AR LL Group # 1540252 Pipeline Incident Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 02/19/2015 14:50 by ZP ExxonMobil PO Box 4592

Houston TX 77210-4592

Submitted: 02/21/2015 10:00 Reported: 02/26/2015 08:40

7051-SDG#: PEO55-01MS

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Semivolatiles SW-846	8270C SIM	ug/l	ug/l	ug/l	
08357	Acenaphthene	83-32-9	0.82	0.010	0.051	1
08357	Acenaphthylene	208-96-8	0.80	0.010	0.051	1
08357	Anthracene	120-12-7	0.89	0.010	0.051	1
08357	Benzo(a) anthracene	56-55-3	0.82	0.010	0.051	1
08357	Benzo(a)pyrene	50-32-8	0.69	0.010	0.051	1
08357	Benzo(b) fluoranthene	205-99-2	0.84	0.010	0.051	1
08357	Benzo(g,h,i)perylene	191-24-2	0.41	0.010	0.051	1
08357	Benzo(k)fluoranthene	207-08-9	0.79	0.010	0.051	1
08357	Chrysene	218-01-9	0.78	0.010	0.051	1
08357	Dibenz(a,h)anthracene	53-70-3	0.42	0.010	0.051	1
08357	Fluoranthene	206-44-0	0.80	0.010	0.051	1
08357	Fluorene	86-73-7	0.84	0.010	0.051	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	0.45	0.010	0.051	1
08357	1-Methylnaphthalene	90-12-0	0.82	0.010	0.051	1
08357	2-Methylnaphthalene	91-57-6	0.80	0.010	0.051	1
08357	Naphthalene	91-20-3	0.82	0.031	0.061	1
08357	Phenanthrene	85-01-8	0.78	0.031	0.061	1
08357	Pyrene	129-00-0	0.76	0.010	0.051	1

General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	e	Analyst	Dilution Factor
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	15054WAB026	02/24/2015	19:40	Holly Berry	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	15054WAB026	02/23/2015 2	20:30	Nicholas W Shroyer	1



Analysis Report

2425 New Holland Pike, Lancaster, PA 17601 • 717-656-2300 • Fax: 717-656-2681 • www.LancasterLabs.com

Sample Description: WS-007(0.5-1.0)021915 MSD Grab Surface Water

LL Sample # WW 7780790 S20135565 Mayflower, AR LL Group # 1540252 Pipeline Incident Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 02/19/2015 14:50 by ZP ExxonMobil PO Box 4592

Submitted: 02/21/2015 10:00 Houston TX 77210-4592

Reported: 02/26/2015 08:40

7051-SDG#: PEO55-01MSD

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Semivolatiles SW-846	8270C SIM	ug/l	ug/l	ug/l	
08357	Acenaphthene	83-32-9	0.87	0.010	0.052	1
08357	Acenaphthylene	208-96-8	0.85	0.010	0.052	1
08357	Anthracene	120-12-7	0.94	0.010	0.052	1
08357	Benzo(a) anthracene	56-55-3	0.89	0.010	0.052	1
08357	Benzo(a)pyrene	50-32-8	0.76	0.010	0.052	1
08357	Benzo(b) fluoranthene	205-99-2	0.87	0.010	0.052	1
08357	Benzo(g,h,i)perylene	191-24-2	0.45	0.010	0.052	1
08357	Benzo(k)fluoranthene	207-08-9	0.92	0.010	0.052	1
08357	Chrysene	218-01-9	0.84	0.010	0.052	1
08357	Dibenz(a,h)anthracene	53-70-3	0.46	0.010	0.052	1
08357	Fluoranthene	206-44-0	0.85	0.010	0.052	1
08357	Fluorene	86-73-7	0.89	0.010	0.052	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	0.49	0.010	0.052	1
08357	1-Methylnaphthalene	90-12-0	0.88	0.010	0.052	1
08357	2-Methylnaphthalene	91-57-6	0.85	0.010	0.052	1
08357	Naphthalene	91-20-3	0.88	0.031	0.063	1
08357	Phenanthrene	85-01-8	0.83	0.031	0.063	1
08357	Pyrene	129-00-0	0.82	0.010	0.052	1

General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Ti	me	Analyst	Dilution Factor
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	15054WAB026	02/24/2015	20:08	Holly Berry	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	15054WAB026	02/23/2015	20:30	Nicholas W Shroyer	1



Analysis Report

LL Sample # WW 7780791

2425 New Holland Pike, Lancaster, PA 17601 • 717-656-2300 • Fax: 717-656-2681 • www.LancasterLabs.com

Sample Description: WS-009(Surface)021915 Grab Surface Water

S20135565 Mayflower, AR

LL Group # 1540252 Pipeline Incident Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 02/19/2015 15:00 by ZP ExxonMobil PO Box 4592

Submitted: 02/21/2015 10:00 Houston TX 77210-4592

Reported: 02/26/2015 08:40

09SRF SDG#: PEO55-02

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Semivolatiles SW-846	8270C SIM	ug/l	ug/l	ug/l	
08357	Acenaphthene	83-32-9	N.D.	0.011	0.053	1
08357	Acenaphthylene	208-96-8	N.D.	0.011	0.053	1
08357	Anthracene	120-12-7	N.D.	0.011	0.053	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.011	0.053	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.011	0.053	1
08357	Benzo(b) fluoranthene	205-99-2	N.D.	0.011	0.053	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.011	0.053	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.011	0.053	1
08357	Chrysene	218-01-9	N.D.	0.011	0.053	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.011	0.053	1
08357	Fluoranthene	206-44-0	N.D.	0.011	0.053	1
08357	Fluorene	86-73-7	N.D.	0.011	0.053	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.011	0.053	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.011	0.053	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.011	0.053	1
08357	Naphthalene	91-20-3	N.D.	0.032	0.063	1
08357	Phenanthrene	85-01-8	N.D.	0.032	0.063	1
08357	Pyrene	129-00-0	N.D.	0.011	0.053	1

General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Ti	me	Analyst	Dilution Factor
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	15054WAB026	02/24/2015	20:35	Holly Berry	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	15054WAB026	02/23/2015	20:30	Nicholas W Shroyer	1



Analysis Report

2425 New Holland Pike, Lancaster, PA 17601 • 717-656-2300 • Fax: 717-656-2681 • www.LancasterLabs.com

Sample Description: WS-001(0.5-1.0)021915 Grab Surface Water

LL Sample # WW 7780792 S20135565 Mayflower, AR LL Group # 1540252 Pipeline Incident Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 02/19/2015 15:10 by ZP ExxonMobil PO Box 4592

Submitted: 02/21/2015 10:00 Houston TX 77210-4592

Reported: 02/26/2015 08:40

01051 SDG#: PEO55-03

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Semivolatiles SW-846	8270C SIM	ug/l	ug/l	ug/l	
08357	Acenaphthene	83-32-9	N.D.	0.010	0.051	1
08357	Acenaphthylene	208-96-8	N.D.	0.010	0.051	1
08357	Anthracene	120-12-7	N.D.	0.010	0.051	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.010	0.051	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.010	0.051	1
08357	Benzo(b) fluoranthene	205-99-2	N.D.	0.010	0.051	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.010	0.051	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.010	0.051	1
08357	Chrysene	218-01-9	N.D.	0.010	0.051	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.010	0.051	1
08357	Fluoranthene	206-44-0	N.D.	0.010	0.051	1
08357	Fluorene	86-73-7	N.D.	0.010	0.051	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.010	0.051	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.010	0.051	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.010	0.051	1
08357	Naphthalene	91-20-3	N.D.	0.030	0.061	1
08357	Phenanthrene	85-01-8	N.D.	0.030	0.061	1
08357	Pyrene	129-00-0	N.D.	0.010	0.051	1

General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Ti	me	Analyst	Dilution Factor
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	15054WAB026	02/24/2015	21:02	Holly Berry	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	15054WAB026	02/23/2015	20:30	Nicholas W Shroyer	1



Analysis Report

2425 New Holland Pike, Lancaster, PA 17601 • 717-656-2300 • Fax: 717-656-2681 • www.LancasterLabs.com

Sample Description: WS-021(0.5-1.0)021915 Grab Surface Water

S20135565 Mayflower, AR

Pipeline Incident

LL Sample # WW 7780793

LL Group # 1540252 Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 02/19/2015 15:15 by ZP ExxonMobil PO Box 4592

Houston TX 77210-4592

Submitted: 02/21/2015 10:00 Reported: 02/26/2015 08:40

21051 SDG#: PEO55-04

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Semivolatiles SW-846	8270C SIM	ug/l	ug/l	ug/l	
08357	Acenaphthene	83-32-9	N.D.	0.010	0.051	1
08357	Acenaphthylene	208-96-8	N.D.	0.010	0.051	1
08357	Anthracene	120-12-7	N.D.	0.010	0.051	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.010	0.051	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.010	0.051	1
08357	Benzo(b) fluoranthene	205-99-2	N.D.	0.010	0.051	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.010	0.051	1
08357	Benzo(k) fluoranthene	207-08-9	N.D.	0.010	0.051	1
08357	Chrysene	218-01-9	N.D.	0.010	0.051	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.010	0.051	1
08357	Fluoranthene	206-44-0	N.D.	0.010	0.051	1
08357	Fluorene	86-73-7	N.D.	0.010	0.051	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.010	0.051	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.010	0.051	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.010	0.051	1
08357	Naphthalene	91-20-3	N.D.	0.030	0.061	1
08357	Phenanthrene	85-01-8	N.D.	0.030	0.061	1
08357	Pyrene	129-00-0	N.D.	0.010	0.051	1

General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Ti	me	Analyst	Dilution Factor
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	15054WAB026	02/25/2015	02:54	Brian K Graham	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	15054WAB026	02/23/2015	20:30	Nicholas W Shroyer	1



Analysis Report

2425 New Holland Pike, Lancaster, PA 17601 • 717-656-2300 • Fax: 717-656-2681 • www.LancasterLabs.com

Sample Description: WS-004(0.5-1.0)021915 Grab Surface Water

LL Sample # WW 7780794 S20135565 Mayflower, AR LL Group # 1540252 Pipeline Incident Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 02/19/2015 15:20 by ZP ExxonMobil PO Box 4592

Submitted: 02/21/2015 10:00 Houston TX 77210-4592

Reported: 02/26/2015 08:40

04051 SDG#: PEO55-05

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Semivolatiles SW-846	8270C SIM	ug/l	ug/l	ug/l	
08357	Acenaphthene	83-32-9	N.D.	0.010	0.051	1
08357	Acenaphthylene	208-96-8	N.D.	0.010	0.051	1
08357	Anthracene	120-12-7	N.D.	0.010	0.051	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.010	0.051	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.010	0.051	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.010	0.051	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.010	0.051	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.010	0.051	1
08357	Chrysene	218-01-9	N.D.	0.010	0.051	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.010	0.051	1
08357	Fluoranthene	206-44-0	N.D.	0.010	0.051	1
08357	Fluorene	86-73-7	N.D.	0.010	0.051	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.010	0.051	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.010	0.051	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.010	0.051	1
08357	Naphthalene	91-20-3	N.D.	0.030	0.061	1
08357	Phenanthrene	85-01-8	N.D.	0.030	0.061	1
08357	Pyrene	129-00-0	N.D.	0.010	0.051	1

General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Ti	me	Analyst	Dilution Factor
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	15054WAB026	02/24/2015	21:56	Holly Berry	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	15054WAB026	02/23/2015	20:30	Nicholas W Shroyer	1



Analysis Report

2425 New Holland Pike, Lancaster, PA 17601 • 717-656-2300 • Fax: 717-656-2681 • www.LancasterLabs.com

Sample Description: DUP-WS-140-021915 Grab Surface Water

S20135565 Mayflower, AR

Pipeline Incident

LL Sample # WW 7780795

LL Group # 1540252 Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 02/19/2015 by ZP ExxonMobil
PO Box 4592

Houston TX 77210-4592

Submitted: 02/21/2015 10:00 Reported: 02/26/2015 08:40

FD140 SDG#: PEO55-06FD

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Semivolatiles SW-846	8270C SIM	ug/l	ug/l	ug/l	
08357	Acenaphthene	83-32-9	N.D.	0.011	0.053	1
08357	Acenaphthylene	208-96-8	N.D.	0.011	0.053	1
08357	Anthracene	120-12-7	N.D.	0.011	0.053	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.011	0.053	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.011	0.053	1
08357	Benzo(b) fluoranthene	205-99-2	N.D.	0.011	0.053	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.011	0.053	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.011	0.053	1
08357	Chrysene	218-01-9	N.D.	0.011	0.053	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.011	0.053	1
08357	Fluoranthene	206-44-0	0.013 J	0.011	0.053	1
08357	Fluorene	86-73-7	N.D.	0.011	0.053	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.011	0.053	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.011	0.053	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.011	0.053	1
08357	Naphthalene	91-20-3	N.D.	0.032	0.064	1
08357	Phenanthrene	85-01-8	N.D.	0.032	0.064	1
08357	Pyrene	129-00-0	N.D.	0.011	0.053	1

General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Ti	me	Analyst	Dilution Factor
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	15054WAB026	02/24/2015	22:24	Holly Berry	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	15054WAB026	02/23/2015	20:30	Nicholas W Shroyer	1



Analysis Report

2425 New Holland Pike, Lancaster, PA 17601 • 717-656-2300 • Fax: 717-656-2681 • www.LancasterLabs.com

Quality Control Summary

Client Name: ExxonMobil Group Number: 1540252

Reported: 02/26/15 at 08:40 AM

Matrix QC may not be reported if insufficient sample or site-specific QC samples were not submitted. In these situations, to demonstrate precision and accuracy at a batch level, a LCS/LCSD was performed, unless otherwise specified in the method.

All Inorganic Initial Calibration and Continuing Calibration Blanks met acceptable method criteria unless otherwise noted on the Analysis Report.

Laboratory Compliance Quality Control

Analysis Name	Blank <u>Result</u>	Blank MDL**	Blank <u>LOQ</u>	Report <u>Units</u>	LCS %REC	LCSD %REC	LCS/LCSD <u>Limits</u>	RPD	RPD <u>Max</u>
Batch number: 15054WAB026	Sample numb	er(s): 77	80788-778	0795					
Acenaphthene	N.D.	0.010	0.050	ug/l	92		76-139		
Acenaphthylene	N.D.	0.010	0.050	uq/l	90		67-120		
Anthracene	N.D.	0.010	0.050	ug/l	97		72-128		
Benzo(a)anthracene	N.D.	0.010	0.050	ug/l	96		71-127		
Benzo(a)pyrene	N.D.	0.010	0.050	ug/l	94		64-132		
Benzo(b)fluoranthene	N.D.	0.010	0.050	ug/l	107		71-139		
Benzo(g,h,i)perylene	N.D.	0.010	0.050	ug/l	73		49-140		
Benzo(k)fluoranthene	N.D.	0.010	0.050	ug/l	93		63-136		
Chrysene	N.D.	0.010	0.050	ug/l	90		72-132		
Dibenz(a,h)anthracene	N.D.	0.010	0.050	ug/l	60		37-142		
Fluoranthene	N.D.	0.010	0.050	ug/l	97		76-121		
Fluorene	N.D.	0.010	0.050	ug/l	95		71-124		
Indeno(1,2,3-cd)pyrene	N.D.	0.010	0.050	ug/l	71		45-136		
1-Methylnaphthalene	N.D.	0.010	0.050	ug/l	91		65-122		
2-Methylnaphthalene	N.D.	0.010	0.050	ug/l	87		59-124		
Naphthalene	N.D.	0.030	0.060	ug/l	88		69-119		
Phenanthrene	N.D.	0.030	0.060	ug/l	91		75-121		
Pyrene	N.D.	0.010	0.050	ug/l	88		70-124		

Sample Matrix Quality Control

Unspiked (UNSPK) = the sample used in conjunction with the matrix spike Background (BKG) = the sample used in conjunction with the duplicate

Analysis Name	MS <u>%REC</u>	MSD %REC	MS/MSD <u>Limits</u>	RPD	RPD <u>MAX</u>	BKG <u>Conc</u>	DUP Conc	DUP <u>RPD</u>	Dup RPD Max
Batch number: 15054WAB026	Sample	number(s)	: 7780788	-77807	95 UNSP	K: 7780788			
Acenaphthene	80	83	69-134	6	30				
Acenaphthylene	78	82	66-132	7	30				
Anthracene	87	89	64-129	5	30				
Benzo(a)anthracene	80	85	32-151	8	30				
Benzo(a)pyrene	67	73	32-137	10	30				
Benzo(b)fluoranthene	82	83	41-137	4	30				
Benzo(g,h,i)perylene	40	43	21-127	9	30				
Benzo(k)fluoranthene	78	88	36-139	15	30				
Chrysene	76	81	51-129	8	30				
Dibenz(a,h)anthracene	42	44	17-134	8	30				
Fluoranthene	76	80	49-138	7	30				
Fluorene	82	85	59-137	6	30				
Indeno(1,2,3-cd)pyrene	44	47	26-130	9	30				

- *- Outside of specification
- **-This limit was used in the evaluation of the final result for the blank
- (1) The result for one or both determinations was less than five times the LOQ.
- (2) The unspiked result was more than four times the spike added.

2425 New Holland Pike, Lancaster, PA 17601 • 717-656-2300 • Fax: 717-656-2681 • www.LancasterLabs.com

Quality Control Summary

Client Name: ExxonMobil Group Number: 1540252

Reported: 02/26/15 at 08:40 AM

Sample Matrix Quality Control

Unspiked (UNSPK) = the sample used in conjunction with the matrix spike Background (BKG) = the sample used in conjunction with the duplicate

	MS	MSD	MS/MSD		RPD	BKG	DUP	DUP	Dup RPD
Analysis Name	%REC	%REC	<u>Limits</u>	RPD	<u>MAX</u>	Conc	Conc	<u>RPD</u>	Max
1-Methylnaphthalene	81	84	47-136	6	30				
2-Methylnaphthalene	79	81	66-120	6	30				
Naphthalene	81	84	58-131	7	30				
Phenanthrene	76	79	66-126	6	30				
Pyrene	73	77	37-142	7	30				

Surrogate Quality Control

Surrogate recoveries which are outside of the QC window are confirmed unless attributed to dilution or otherwise noted on the Analysis Report.

Analysis Name: PAHs in waters by SIM

Batch number: 15054WAB026

	Fluoranthene-d10	Benzo(a)pyrene-d12	1-Methylnaphthalene-
			d10
7780788	90	82	80
7780789	86	82	79
7780790	88	87	81
7780791	94	81	81
7780792	94	73	82
7780793	93	64	77
7780794	84	68	74
7780795	86	68	76
Blank	99	95	87
LCS	100	110	89
MS	86	82	79
MSD	88	87	81
Limits:	56-134	26-158	52-127

^{*-} Outside of specification

^{**-}This limit was used in the evaluation of the final result for the blank

⁽¹⁾ The result for one or both determinations was less than five times the LOQ.

⁽²⁾ The unspiked result was more than four times the spike added.


ExxonMobil Analysis Request/Chain of Custody

💸 eurofins

Lancaster Laboratories Environmental

Acct. # 14739	For Eurofins Lancaster Laboratories Environmental use only Group # / 50257 Sample # 778
	Instructions on reverse side correspond with circled numbers.

1) Client Informa	(4)	Matrix			5 Analyses F								SCR#:	- 16	59	27			
Facility #/SID									Prese	ervati	on Co	de	W. L				Non-California de la companya de la		-
Man flower likeline Incident																Preserva	tion C	odes	
Site Address			and the same of th	Ground Surface											H =	HCI	T = T	hiosulfate	
ExxonMobil PM Cost Center/AFE				Ground												HNO_3	B = N		
				our											S =	H ₂ SO ₄	O = C		
A) ICC S(XSm;YL) Consultant/Office] t	G											6	Rer	narks		
Consultant/Office			це			ပွ	2												
Arcadis	nsultant Phone #		Sediment		<u>.</u>	ne	SS	Ì											
		ű	ble ES	Air	ıtai														
Stem Borrick				Potable NPDES		of Containers	1												
Sampler	(3) site				of (00													
Lac formers	Collected	G Grab Composite			Ш	Total#	1												
2	Time G G G	Soil	Water	lio	ota	72													
Sample Identification			<u> </u> ທ	X	0	- process	(a)					_	-				Senson society according		_
		:50 X	-			hui	X_{\perp}						+						_
W5-009 (Surface) 021915 Z.	19.15 15	200 X		X		2	X												_
UB-001(0,5-1,0)021915 Z	.19.15 15	51/0 X		X		2	X												
	19.15 15	5:15 X	A. T.	×		7	\times												
		:20 X		V		Z	v												
		1:50				Ц	1												
	19.15 -	- V				-7							+						
DUP-445-140-021915 2.	11117		-								-	+	+						\dashv
			-	-							_		+-+						_
			-	-			\vdash						+						-
													\bot					www.wichesta	_
7) Turnaround Time Requested (TAT) (ple	ease circle)	Relinguished by	i 1/			Date	1	Т	ime		eceive	by				Date		Time (9)
Standard 5 day	4 day	L Megas	1/LB			2/	2/14		8:28		7/		EXPERIENCE CONTRACTOR			2/19/	T .	0900	
Standard	4 day	Relinquished by				Date	1	- 1	ime	R	eceive	Тбу	10			Date	ľ	Time	
72 hour 48 hour	24 hour		A STATE OF THE PARTY OF THE PAR			7 /2	0/1		1200			UF							_
72 110di 40 110di	24 Hour	Relinguished by				Ďate		T	ime	R	eceive	l by	-			Date	ľ	Time	
8 Data Package (circle if required) EDD (cir																			
Type I - Full Locus EIM (default)				ercial Carrier							Received by				ĺ	Date		Time	
Type VI (Raw Data) Other UPS				FedEx Other							1 4/1				7	2-21.1	2	1076	
NJ Reduced		Tomp	aratu	re Upon R	acair	\tag{t}	1.3	0	С			uetod	y Seal:	s Int	act2	(Ye	1	No	
Other		rempe	Jialu	то орон К	oooih	/ L			_		_	usiou	y Ocal	o nill	uot:	<u> </u>	•	INU	



Sample Administration Receipt Documentation Log

Doc Log ID:

57048

Group Number(s): 1540252

Client: ExxonMobil

Delivery and Receipt Information

Delivery Method:

UPS

Arrival Timestamp:

02/21/2015 10:00

Number of Packages:

1

Number of Projects:

1

Arrival Condition Summary

Shipping Container Sealed:

Yes

Sample IDs on COC match Containers:

Yes

Custody Seal Present:

Yes

Sample Date/Times match COC:

Yes

Custody Seal Intact:

Yes

VOA Vial Headspace ≥ 6mm:

N/A

Samples Chilled:

Yes

Total Trip Blank Qty:

0

Paperwork Enclosed:

Yes

Air Quality Samples Present:

No

Samples Intact:

Yes

Missing Samples:

No

Extra Samples:

No No

Unpacked by Timothy Cubberley (6520) at 12:03 on 02/21/2015

Samples Chilled Details

Thermometer Types:

DT = Digital (Temp. Bottle)

IR = Infrared (Surface Temp)

All Temperatures in °C.

Cooler # Thermometer ID

1 DT121

eter ID Corrected Temp
21 1.3

Discrepancy in Container Qty on COC:

Therm. Type
DT

Ice Type Wet

Ice Present?

Ice Container
Bagged

Elevated Temp?

Page 1 of 1

2425 New Holland Pike Lancaster, PA 17605-2425

Page 15 of 16

T | 717-656-2300 F | 717-656-2681 www.LancasterLabs.co



Explanation of Symbols and Abbreviations

The following defines common symbols and abbreviations used in reporting technical data:

RL N.D.	Reporting Limit none detected	BMQL MPN	Below Minimum Quantitation Level Most Probable Number
TNTC	Too Numerous To Count	CP Units	cobalt-chloroplatinate units
IU	International Units	NTU	nephelometric turbidity units
umhos/cm	micromhos/cm	ng	nanogram(s)
С	degrees Celsius	F	degrees Fahrenheit
meq	milliequivalents	lb.	pound(s)
g	gram(s)	kg	kilogram(s)
μg	microgram(s)	mg	milligram(s)
mL	milliliter(s)	L	liter(s)
m3	cubic meter(s)	μL	microliter(s)
		pg/L	picogram/liter

less than <

greater than

ppm parts per million - One ppm is equivalent to one milligram per kilogram (mg/kg) or one gram per million grams. For aqueous liquids, ppm is usually taken to be equivalent to milligrams per liter (mg/l), because one liter of water has a weight very close to a kilogram. For gases or vapors, one ppm is equivalent to one microliter per liter of gas.

ppb parts per billion

Results printed under this heading have been adjusted for moisture content. This increases the analyte weight Dry weight basis

concentration to approximate the value present in a similar sample without moisture. All other results are reported on an

as-received basis.

Laboratory Data Qualifiers:

B - Analyte detected in the blank

C - Result confirmed by reanalysis

E - Concentration exceeds the calibration range

J (or G, I, X) - estimated value ≥ the Method Detection Limit (MDL or DL) and the < Limit of Quantitation (LOQ or RL)

P - Concentration difference between the primary and confirmation column >40%. The lower result is reported.

U - Analyte was not detected at the value indicated

V - Concentration difference between the primary and confirmation column >100%. The reporting limit is raised due to this disparity and evident interference...

Additional Organic and Inorganic CLP qualifiers may be used with Form 1 reports as defined by the CLP methods. Qualifiers specific to Dioxin/Furans and PCB Congeners are detailed on the individual Analysis Report.

Analytical test results meet all requirements of the associated regulatory program (i.e., NELAC (TNI), DoD, ISO17025) unless otherwise noted under the individual analysis.

Measurement uncertainty values, as applicable, are available upon request.

Tests results relate only to the sample tested. Clients should be aware that a critical step in a chemical or microbiological analysis is the collection of the sample. Unless the sample analyzed is truly representative of the bulk of material involved, the test results will be meaningless. If you have questions regarding the proper techniques of collecting samples, please contact us. We cannot be held responsible for sample integrity, however, unless sampling has been performed by a member of our staff.

This report shall not be reproduced except in full, without the written approval of the laboratory.

Times are local to the area of activity. Parameters listed in the 40 CFR Part 136 Table II as "analyze immediately" are not performed within 15 minutes.

WARRANTY AND LIMITS OF LIABILITY - In accepting analytical work, we warrant the accuracy of test results for the sample as submitted. THE FOREGOING EXPRESS WARRANTY IS EXCLUSIVE AND IS GIVEN IN LIEU OF ALL OTHER WARRANTIES, EXPRESSED OR IMPLIED. WE DISCLAIM ANY OTHER WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING A WARRANTY OF FITNESS FOR PARTICULAR PURPOSE AND WARRANTY OF MERCHANTABILITY. IN NO EVENT SHALL EUROFINS LANCASTER LABORATORIES ENVIRONMENTAL, LLC BE LIABLE FOR INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES INCLUDING, BUT NOT LIMITED TO, DAMAGES FOR LOSS OF PROFIT OR GOODWILL REGARDLESS OF (A) THE NEGLIGENCE (EITHER SOLE OR CONCURRENT) OF EUROFINS LANCASTER LABORATORIES ENVIRONMENTAL AND (B) WHETHER EUROFINS LANCASTER LABORATORIES ENVIRONMENTAL HAS BEEN INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. We accept no legal responsibility for the purposes for which the client uses the test results. No purchase order or other order for work shall be accepted by Eurofins Lancaster Laboratories Environmental which includes any conditions that vary from the Standard Terms and Conditions, and Eurofins Lancaster Laboratories Environmental hereby objects to any conflicting terms contained in any acceptance or order submitted by client.