

Mayflower Pipeline Incident Update

June 28, 2013

Current Response Status/Activities

Neighborhood

- Have completed hydro-vacing near driveway of #50 N Starlite – awaiting sample results prior to backfilling excavation – will address electrical, water, and phone needs as soon as excavation is filled and fence along driveway is installed

Main Street

- No change - continue monitoring and maintenance activities

365

- Addressing a small area near 365 along creek where small amount of oil was found – looks like some type of void in ground that captured some oil

Cove

- Continue monitoring and maintenance, including airboat pom-pom operations
- Working with ADEQ and AGF to finalize boom removal strategy

Other

- Have generated additional roll offs (hydro-vacing)
- Generated some additional decon water from frac tank cleaning – will go to Rineco

Air Sampling Results/Meetings with Homeowners

- See attached diagram

MDW 06/25/13

Mayflower Pipeline Incident Update

June 28, 2013

Key Incident Statistics

Solid Waste Summary (original response)

	Soil	Debris	Wood Chips	Vac Boxes	Total
Conway	1	5	0	0	6
Landfill	432	310	281	79	1102
Total	432	315	281	79	1108

Have generated additional roll offs from maintenance activities (hydro vacuuming)

Solid Waste Summary (recent residential remediation)

	Soil	Debris	Wood Chips	Vac Boxes	Total
(EMES)	25	0	0	0	25
Landfill	0	0	0	0	0
Total	25	0	0	0	25

Awaiting sample results prior to disposal

Oil/Liquids Summary (number of fracs)

	Total Fracs	Frac Shipped	Frac Left
Oil/water to Rineco	26	26	0
Decon water to Rineco	8	5	3
Oil/water to BRRF	38	38	0
Total oil/water	72	69	3

Note – frac tank cleaning generating additional water to Rineco

Mayflower Pipeline Incident Update

June 28, 2013

Northwoods Subdivision

Updated: 6/25/13

