



The above locations were monitored for Benzene, VOC, and H₂S during the day work shift. All readings were below the limit of detection for the instruments used.