

**FOR OFFICE USE ONLY:
AIR HW RST SW WATER
MINING**

**ARKANSAS DEPARTMENT OF ENVIRONMENTAL QUALITY
P. O. BOX 8913, LITTLE ROCK, AR 72219-8913**

COMPLAINT REPORT

LOCATION: Latitude 36.1399 N Longitude 94.2573 W	AFIN#: 72-00144 PERMIT#: ARG160003
DATE RECEIVED: 10/20/06	COUNTY: Washington
COMPLAINANT NAME: Gary Escalante	COMPLAINT AGAINST: Sunray Landfill
ADDRESS: Tontitown	ADDRESS: Attn: Waste Management 18633 Stutts Rd. Springdale, AR 72762
PHONE: 479-466-5716 FAX: N/A	PHONE: 479-361-2069 FAX: N/A

PERSON RECEIVING REPORT: Tony Morris	DATE: 11/6/06	SUPERVISOR REFERRAL:	DATE:
INSPECTOR REFERRED:	DATE:	MEDIA SUPERVISOR REFERRAL:	DATE:
PHONE REFERRAL CONTACT:	DATE:	RECEIVING INSPECTOR: Tony Morris	DATE: 11/6/06

DESCRIPTION (IN DETAIL)

The complaint stated that a large amount of sediment had accumulated on the road from the landfill and was creating safety and water quality problems.

LOCATION (IN DETAIL)

The landfill is located south of Tontitown in Washington County.

PREVIOUS COMPLAINT? ☐ YES ☐ NO **DATES:**

DISCHARGE TO STREAM? ☐ YES ☒ NO **NAME OF STREAM:** Clear Creek to Illinois River

HOW COMPLAINT WAS RECEIVED: ☒ PHONE ☐ LETTER ☐ VERBAL ☐ FAX ☐ E-MAIL

FOLLOW UP ON COMPLAINT

COMPLAINT #:

AFIN #: 72-00144

INSPECTOR: Tony Morris

DATE: 11/8/06

ACTION TAKEN: On site investigation on 11/8/06, meeting with Mr. Kirby Thompson, the landfill manager.

PHOTOS TAKEN: Yes

A complaint investigation was conducted on 11/8/06. At that time no mud was noted on the roads leading away from the landfill. The landfill manager stated that following the rain event over the weekend of 11/4-5/06, vehicles leaving the landfill had tracked mud onto the road. The landfill has a water truck and a sweeper, however, on the morning of 11/6/06 it was too foggy to clean the road. The dense fog created a safety hazard for the equipment operators so Mr. Thompson did not promptly clean the roads.

FURTHER ACTION TAKEN/TO BE TAKEN: No further action required

NPDES Storm Water Reconnaissance Inspection of the permitted facility will be completed and a compliance letter sent to the operator.

INSPECTOR SIGNATURE:

Tony Morris

Tony L Morris

DATE:

11/13/06

HOURS WORKED:

5 hours

ddw