

January 10, 2008

Warren Taff, Environmental Engineer Quanex Corporation-MacSteel Division P.O. Box 1592 Fort Smith, AR 72902

AFIN: 66-00274 NPDES Permit No.: AR0039730

Dear Mr. Taff:

On December 12, 2007, I performed a reconnaissance inspection of your facility in response to a complaint. This inspection was performed in accordance with the provisions of the Federal Clean Water Act, the Arkansas Water and Air Pollution Control Act, and the regulations promulgated thereunder. The complainant alleged that he had observed a strong reddish tint in the waters of Massard Creek downstream from your facility. He expressed concerns that the facility's outfall could be the source of the discoloration. During my inspection, I observed the outfall and various downstream locations along Massard Creek throughout Ben Geren Park and did not observe or detect any reddish tint in the waters.

Should you have any questions or if I can be of any assistance, please contact me at 479-452-4822 ext. 11.

Sincerely,

Jeff Tyler District 4 Field Inspector Water Division

cc: Water Division Enforcement Branch Water Division Permits Branch



€EPA

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY Washington, D.C. 20460 NPDES Compliance Inspection Report													Form Approved OMB No. 2040-0003																			
	Section A: National Data System Coding																															
Transaction Code NPDES Yr/Mo/Day Inspec. Type Inspector Fac. Type 1 N 2 5 3 A R 0 0 3 9 7 3 0 11 12 0 7 1 2 17 18 R 19 S 20 2 2																																
	IN	2	3	5	A	ĸ		U	U	3	9	<i>'</i>	3	U	1			/	1	2	1	4		17	10	N		19	3	20	2	
1		A	F	Ιт	N	I I	I	6	6	I	٨	ا ا		17	4	Remai	:ks	1		I	I	I	Ĩ				ĺ		I	I	I	
				1				0		-	U				4																	
	1	specti 0	on W	ork D	Ĺ				Fac		1	tion	Ratin	g		BI	1	QA		 	 I	 _]	Reserv	ed		 	 		
	07 09 70 N 71 N 72 N 73 74 73 60																															
	Section B: Facility Data																															
Name and Location of Facility Inspected (For industrial users discharging to POTW, also include POTW name and NPDES permit number) Entry Time/Date Permit Effective Date 1440 / December 12, 2007 November 1, 2001																																
	include POTW name and NPDES permit number) 1440 / December 12, 2007 November 1, 2001																															
522	5225 Planters Road Exit Time/Date Permit Expiration Date																															
For	Fort Smith, AR 72903 Data Market Supervision Data Market Supervision <thdata market="" superv<="" td=""></thdata>																															
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s) Other Facility Data																																
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s) Other Facility Data																																
Name, Address of Responsible Official/Title/Phone and Fax Number																																
Name, Address of Responsible Official/Title/Phone and Fax Number Warren Taff / Environmental Engineer / 479-648-5544 Contacted																																
P.O. Box 1592																																
Foi	Fort Smith, AR 72902YesNo																															
	Section C: Areas Evaluated During Inspection (S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)																															
Ν	Per	mit						Ν	H		Measu		-		0	N	1	eratio	-				,		Ν	Sam	oling					
Ν	Rec	cords/	Repo	rts				Ν	5	elf-M	Ionito	ring	g Prog	ram		Ν	Slu	ldge H	andli	ng/Di	ispos	al		ľ	Ν	Pollu	tion	Preve	ention	l		
Ν		ility S	_		v			Ν	-				hedule			Ν		etreati		0	•			ľ	Ν	Mult	imed	ia				
S		•			Wate	ers		Ν		-	atory					Ν	Sto	orm W	ater					ľ	Ν	Othe	r:					
								5			•	nar	y of F	inding	s/Cor	nment				onal s	heets	s if n	eces	sary	y)		-					
Α	reco	onna	nissa	ance	ins	pect	tio	n v	vas	per	forn	ied	l in r	espo	nse	to a	con	plai	nt. '	Гhe	con	npl	ain	ant	t all	eged	tha	t a 1	redd	lish	tint	
													ek d																			
		0			-						0		sou					-		· ·												'y
											•		trong not c	·															ions	oft	he	
u	CCK	um	Jugi	1001	. Del	u G	EL		1 аі	K al	iu u	IU .	not (USEI	vea	my s	11 01	ig ie	uuis	ii u	ISCU	101	au	UII .	111 U	Ie w	atei	•				
N.		1.0	•		67		,						_	,	2.65	/10.1	1	(P								D						
Nar	ne(s)	and S	ignat	ure(s)	of In	spect	or(s)								/Telep		'Fax t al Q u	ality	-/ Ft.	Smit	h / 4	79-4	152-		Date Jan	: uary	8.2	007			
Nar Jeff	Tyl	er 7	0	/										_		479-45		-	-								J	,				
															0.07	/D'		n								F						
Sig	nature	e of R	eview	/er									A	gency	Office	e/Phon	e and	Fax N	lumbe	ers						Dat	e					

ARKANSAS DEPARTMENT OF ENVIRONMENTAL QUALITY

5301 NORTHSHORE DRIVE / NORTH LITTLE ROCK / ARKANSAS 72118-5317 / TELEPHONE 501-682-0744 / FAX 501-682-0880

ADEQ Water NPDES Inspection	AFIN: 66-00274	Permit #:AR0039730	
· · · · · · · · · · · · · · · · · · ·			

ADEQ Water NPDES Inspection	
-----------------------------	--

Water Division NPDES Phot	ographic Ev	idence Sheet		
Location: Quanex Corporation-Mac Steel 5225 Planter	rs Road			
Photographer: Jeff Tyler	Witness:	None		
Photo # 1 Of 6	Date:	12-12-07	Time:	1450
Description: Outfall at MacSteel under heavy flow due	e to rain. No	reddish discolo	pration in th	e water.
Photographer: Jeff Tyler	Witness:	None		
Photo # 2 Of 6	Date:	12-12-07	Time:	1451
Description: Outfall at MacSteel with no evidence of s	strong reddisl	h colors in the	water.	

AFIN: 66-00274

			Wat	er Division NPDES Phot	ographic Ev	idence Sheet		
Location:	Be	n Geren	Park					
Photograp	her:	Jeff Ty	ler		Witness:	None		
Photo #	3	Of	6		Date:	12-12-07	Time:	1455
Description	n:	Receivi	ing strea	am approximately 50 feet d	lownstream f	from MacSteel	's outfall.	
Photograp	her	Jeff Ty	ler		Witness:	None		
Photo #	4	Of	6	Γ	Date:	12-12-07	Time:	1455
Description				I approximately 100 feet				1155

ADEQ Water NPDES Inspection

AFIN: 66-00274

			Wat	er Division N	PDES Phot	ographic E	vi	dence Sheet		
Location:	Ber	n Gerer	n Park							
Photographer	; .	Jeff Ty	ler			Witness:		None		
Photo #	5	Of	6			Date:		12-12-07	Time:	1510
Description:		Massar	d Creek	approximately	y .5 miles fro	m MacStee	el's	s outfall.	-	
Photographer	: .	Jeff Ty	ler			Witness:		None		
Photo #	6	Of	6			Date:		12-12-07	Time:	1515
Description:		Massaı	rd Creek	approximately	y .75 miles fi	om MacSte	eel	's outfall.		

ADEQ Water NPDES Inspection

AFIN: 66-00274

WATER DIVISION NPDES COMPLAINT REPORT										
GPS LOCATION: Not Available		AFIN: 66-00274								
		PERMIT#: AR00	39730							
DATE RECEIVED: December 10, 2007		COUNTY: Sebastian								
COMPLAINANT NAME: Anonymous		COMPLAINT AGAINST: Quanax Corporation-								
		MacSteeel								
ADDRESS: NA		ADDRESS: 5225		Road						
PHONE: NA		PHONE: 479-64	8-5544							
TRAC	CKING & REFE	RRAL INFORMATION								
PERSON RECEIVING REPORT:	DATE:	SUPERVISOR R	EFERRAL	:	DATE:					
Jeff Tyler	12-10-07									
INSPECTOR REFERRAL:	DATE:	MEDIA SUPERVI	ISOR REF	ERRAL:	DATE:					
PHONE REFERRAL CONTACT:	DATE:	RECEIVING INSP	PECTOR:		DATE:					
COMPLAINT RECEIVED BY: PHONE LETTER VERBAL INTERNET EMAIL										
DETAILED DESCRIPTION										
Strong reddish tint in waters of Massard Creek downstream from the facility's outfall.										
	LOCA	TION								
Observed in waters of Massard Creek th	roughout Ben (Geren Park.								
PREVIOUS COMPLAINT: YES MO	DATES:									
DISCHARGE TO STREAM: DYES DNO	NAME OF ST	REAM: Massard C	reek							
	INVEST	IGATION								
INSPECTOR:		DATE:								
Jeff Tyler		December 12, 20	007							
ACTION TAKEN:										
Recon inspection performed, I did not ol from the facility's outfall.	bserve any stro	ng reddish discol	oration in	the waters do	wnstream					
FURTHER ACTION:										
None at this time										
SIGNATURE: Jeff Tyler 977			C	ATE: January	7, 2008					