

WATER DIVISION NPDES COMPLAINT REPORT

GPS LOCATION: 33 12 01.36 92 40 18.76

AFIN: 70-00016

PERMIT#: AR0000647

DATE RECEIVED: 9/25/08

COUNTY: UNION

COMPLAINANT NAME: Unknown

COMPLAINT AGAINST: Lion Oil Company-El Dorado Refinery

ADDRESS:

ADDRESS: 1000 McHenry Avenue, El Dorado,, AR 71730

PHONE:

PHONE: 870-864-1289

TRACKING & REFERRAL INFORMATION

PERSON RECEIVING REPORT:

Karen Duke

DATE:

9/25/08

SUPERVISOR REFERRAL:

DATE:

INSPECTOR REFERRAL:

John Lamb

DATE:

9/25/08

MEDIA SUPERVISOR REFERRAL:

DATE:

PHONE REFERRAL CONTACT:

DATE:

RECEIVING INSPECTOR:

DATE:

COMPLAINT RECEIVED BY: ☒PHONE ☐LETTER ☐VERBAL ☐INTERNET ☐EMAIL

DETAILED DESCRIPTION

Complainant states that a gray material is being dumped on the East side of the site from a vacuum truck.

LOCATION

PREVIOUS COMPLAINT: ☐YES ☒NO DATES:DISCHARGE TO STREAM: ☐YES ☐NO NAME OF STREAM:

INVESTIGATION

INSPECTOR:

John Lamb

DATE:

9/26/08


ACTION TAKEN:

PHOTOS TAKEN: ☐YES ☒NO

See NPDES inspection report dated 9/26/08

FURTHER ACTION:

SIGNATURE: John W. Lamb



DATE: 16 October 2008