



AR KANSAS  
Department of Environmental Quality

## WATER DIVISION COMPLAINT REPORT

AFIN: <b>51-00000</b>	PERMIT #: <b>NA</b>
COUNTY: <b>51 Newton</b>	PDS #: <b>023046</b>
GPS LOCATION: LAT: <b>36.10192</b> LONG: <b>-93.01016</b>	
<input type="checkbox"/> Discharge Site / <input checked="" type="checkbox"/> General Area / <input type="checkbox"/> Entrance	

COMPLAINANT NAME: <b>Ruth Haley</b> MAILING ADDRESS: <b>396 NC 3570</b> CITY, STATE, ZIP: <b>Western Grove AR 72685</b> PHONE & EXT: / FAX: <b>870.429.8118</b> / EMAIL: <b>ruth_haley@hotmail.com</b> RESPONSE REQUESTED BY COMPLAINANT: <b>Yes</b>	COMPLAINT AGAINST: <b>Pat Sanders</b> SITE ADDRESS: <b>Between county roads 3560 and 3570, Western Grove</b> MAILING ADDRESS: <b>Route 1 Box 238</b> CITY, STATE, ZIP: <b>Western Grove AR 72685</b> PHONE & EXT: / FAX: <b>870.577.0478</b> / EMAIL:
---	---

HOW WAS COMPLAINT RECEIVED BY ADEQ: **EML**

ADEQ = ADEQ Personnel | EML = E-Mail | FAX = Fax | LTR = Letter  
 PERS = Personal Contact | PHON = Telephone | WEB = ADEQ Website

PERSON RECEIVING REPORT: <b>Jessica Flanigin West</b>	DATE: <b>07/16/2017</b>	SUPERVISOR REFERRAL: <b>Jason Bolenbaugh</b>	DATE: <b>07/24/2017</b>
MEDIA SUPERVISOR REFERRAL:	DATE:	RECEIVING INSPECTOR: (ID & Name) <b>104111 Garrett Grimes</b>	DATE: <b>07/24/2017</b>

### DETAILED DESCRIPTION OF COMPLAINT

Complainant stated that Mr. Sanders has recently started to keep hogs at the above mentioned location. Complainant stated that the hogs are not penned and is concerned about the condition of the animals and runoff associated with their activity and waste. Complainant states that there are no retaining ponds and that the pasture drains into a nearby creek which flows into the Buffalo River.

### DETAILED LOCATION

From Hwy 65 turn west onto Gladden St. Stay on pavement for approximately 2 miles then the dirt road approximately 1 mile. Between roads 3560 and 3570.

PREVIOUS COMPLAINTS: **No** DATE(S):

### FOLLOW-UP ON COMPLAINT

NUMBER OF SITE VISITS: **02** DATES: FIRST **8/17/2017** SECOND **10/04/2017** THIRD

PHOTOS TAKEN: **Yes** DISCHARGE TO WATER OF THE STATE: **\*\*\*** SAMPLES COLLECTED: **\*\*\***

NAME OF WATERBODY:

FAYETTEVILLE SHALE RELATED: **No** FAYETTEVILLE SHALE VIOLATIONS: **No**

### INVESTIGATION & ACTION TAKEN

**Refer to separate reconnaissance inspection PDS # 099746.**

REFERRED: **\*\*\*** TO WHOM: **N/A** DATE REFERRED:

### RESPONSE TRACKING

RESPONSE REQUESTED: **Yes** RESPONSE PROVIDED: **Yes** RESPONSE PROVIDED DATE: **10/25/2017**

BY WHOM?(ID and Name): **04315 Melissa McConnell** ASSIGNED TO? (ID and Name): **104111 Garrett Grimes**

RESPONSE COMMENT:  
**Emailed copy of inspection report to complainant**

INSPECTOR: **Garrett Grimes** DATE: **10/16/2017**

SUPERVISOR: **Jason Bolenbaugh** DATE: **10/25/2017**