



ENVIRONMENTAL
QUALITY

OFFICE OF WATER QUALITY COMPLAINT REPORT

AFIN: 46-00985

PERMIT #: AR0052965

COUNTY: 46 Miller

PDS #: 028813

GPS LOCATION: LAT: 33.059008 LONG: 93.855489

☐ Discharge Site / ☒ General Area / ☐ Entrance

COMPLAINANT NAME:

Larry Nelson

MAILING ADDRESS:

699 Wynn Road

CITY, STATE, ZIP:

Doddridge AR

PHONE & EXT: / FAX:

430-333-0075 /

EMAIL:

RESPONSE REQUESTED BY COMPLAINANT:

Yes

COMPLAINT AGAINST:

Performance Proppants

SITE ADDRESS:

2651 Miller Co Road 4

MAILING ADDRESS:

4803 Benton Road

CITY, STATE, ZIP:

Bossier City LA 71111

PHONE & EXT: / FAX:

318-584-7327 /

EMAIL:

bill@perfproppants.com

HOW WAS COMPLAINT RECEIVED BY ADEQ: EML

ADEQ = ADEQ Personnel | EML = E-Mail | FAX = Fax | LTR = Letter
PERS = Personal Contact | PHON = Telephone | WEB = ADEQ Website

PERSON RECEIVING REPORT:

Thomas Hunting, ER Inspector

DATE:

10/4/2021

SUPERVISOR REFERRAL:

Kerri McCabe

DATE:

10/4/2021

MEDIA SUPERVISOR REFERRAL:

DATE:

RECEIVING INSPECTOR: (ID & Name)

141737 Trey Butler

DATE:

10/4/2021

DETAILED DESCRIPTION OF COMPLAINT

As recorded by T Hunting, Emergency Response Inspector:

"Larry Nelson, 430-333-0075

On 10/04@1112 the ER Section received notification from the ADEM that Larry Nelson, 699 Wynn Road (County Road 4), Doddridge, AR reported that his well and the Red River near his home is contaminated due to fracking in the area. He has requested assistance in reporting and working with the issue. Mr. Nelson told ADEM he had his water well sampled and sent the results to the Dept. of Agriculture who said it was contaminated (it was not disclosed what the contaminate is). A records review by the ER section confirmed that there is no "fracking" in that area of the state. There is a large facility close to his address on County Road 4 (Performance Proppants River Ridge Sand Plant) that manufactures fracking sand, it is suspected by the ER section that this facility is the one that Mr. Nelson is concerned about. Attempts to reach Mr. Nelson at the number provided have been unsuccessful."

Mr. Nelson also contacted Arkansas Department of Health (ADH).

DETAILED LOCATION

GPS coordinates listed above; Google Earth image attached.

PREVIOUS COMPLAINTS: No DATE(S):

FOLLOW-UP ON COMPLAINT

NUMBER OF SITE VISITS: 1 DATES: FIRST 10/11/2021 SECOND THIRD

PHOTOS TAKEN: Yes

DISCHARGE TO WATER OF THE STATE: Yes

SAMPLES COLLECTED: No

NAME OF WATERBODY: Permitted discharge to Red River

FAYETTEVILLE SHALE RELATED: No

FAYETTEVILLE SHALE VIOLATIONS: No


INVESTIGATION & ACTION TAKEN

A reconnaissance inspection was performed in response to the complaint. Findings from the inspection can be found in the separate inspection report performed on October 11, 2021.

REFERRED: No

TO WHOM: N/A

DATE REFERRED:

RESPONSE TRACKING		
RESPONSE REQUESTED: Yes	RESPONSE PROVIDED: Yes	RESPONSE PROVIDED DATE: 10/28/2021
BY WHOM?(ID and Name): 141737 Trey Butler		ASSIGNED TO? (ID and Name): 141737 Trey Butler
RESPONSE COMMENT: Complainant was contacted via phone on October 28, 2021 and informed that the facility in question was in compliance. Mr. Nelson stated that the contaminate in his well and in the Red River was E. coli. I explained to him that DEQ-OWQ does not regulate private water wells.		
INSPECTOR:  Trey Butler		DATE: 10/11/2021
SUPERVISOR:  Kerri McCabe		DATE: 12/7/2021

Revised: 8/12/2019

Office of Water Quality Photographic Evidence Sheet

Location:	Doddridge, AR		
Photographer:	Trey Butler	Date:	10/27/2021
Time:	10:30	Witness:	
Photo #:	1	Description:	Google Earth image showing complainant address in relation to permitted facility

