

ADEQ

ARKANSAS
Department of Environmental Quality

December 13, 2006

Kirby Thompson
Waste Management
18633 Stutts Road
Springdale, AR 72762


Re: AFIN: 72-00144 NPDES Permit No. ARG160003

Dear Mr. Thompson:

On November 8, 2006, I performed a routine storm water inspection of your facility in accordance with the provisions of the federal Clean Water Act, the Arkansas Water and Air Pollution Control Act and the regulations promulgated thereunder. This inspection revealed that you are in compliance with terms of your permit.

If I can be of any assistance, please contact me at 870-446-2770.


Sincerely,



Tony L. Morris
Field Inspector
ADEQ Water Division

cc: NPDES Branch
John Fazio, District 1 Field Inspector

**Arkansas Department of Environmental Quality (ADEQ)
Official Photograph Sheet**

Location:	Waste Management Sunray Landfill, Washington County						
Photographer:	Tony Morris			Witness:			
Photo #	1	Of	2	Date:	11/08/06	Time:	15:14
Description:	Two of the storm water ponds on the landfill property. Samples are collected from the empty pond in the background.						
							
Photographer:	Tony Morris			Witness:			
Photo #	2	Of	2	Date:	11/08/06	Time:	1515
Description:	Storm water ponds with a leachate storage tank in the left center of the photo.						
	